Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103			
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-015-20293			
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease			
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE 🖂			
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOT	7. Lease Name or Unit Agreement Name				
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	J Lazy J			
PROPOSALS.)	8. Well Number				
1. Type of Well: Oil Well	1				
2. Name of Operator Yates Petroleum Corporation	9. OGRID Number 025575				
3. Address of Operator	10. Pool name or Wildcat				
105 South Fourth Street, Artesia, N	Eagle Creek; San Andres				
4. Well Location					
Unit Letter H:	2310 feet from the North line and	feet from the East line			
Section 22	Township 17S Range 25E	NMPM Eddy County			
A STATE OF THE STA	11. Elevation (Show whether DR, RKB, RT, GR, e.	tc.)			
	3518'GR				
12 Charle	A	- Danield an Other Date			
12. Check 2	Appropriate Box to Indicate Nature of Notic	e, Report of Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☑ REMEDIAL WORK ☐ ALTERING CASING ☐				
TEMPORARILY ABANDON 🔲	—··)	PAND A □			
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB			
DOWNHOLE COMMINGLE		,			
OTHER:	□ OTHER:	П			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
13. Describe proposed of comp	stered operations. (Greatly state an pertindent details,	and give periment dates, including estimated date			
of starting any proposed we	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (Completions: Attach wellbore diagram of			
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (completion.	Completions: Attach wellbore diagram of Notify OCD 24 hrs. prior			
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (Completions: Attach wellbore diagram of			
of starting any proposed we proposed completion or recovered Yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting any proposed we have a supposed to the starting and the starting a	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment.	Notify OCD 24 hrs. prior to any work done.			
of starting any proposed we proposed completion or recovered Yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to the start of the sta	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to	Notify OCD 24 hrs. Prior to 500' with 115 sx. NOTE: If fill is tagged and			
of starting any proposed we proposed completion or recovered Yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to the start of the sta	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to a class and set a CIBP above perfs at 1250' before circulation.	Notify OCD 24 hrs. prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx).			
of starting any proposed we proposed completion or reconstruction. Yates Petroleum Corporation plans 1. MIRU any safety equipment as reconstruction. 2. RIH with bit and scraper to just be unable to get below perfs then TOH. 3. Cut off wellhead and verify that	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I	Notify OCD 24 hrs. Prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then			
of starting any proposed we proposed completion or reconstruction. Yates Petroleum Corporation plans 1. MIRU any safety equipment as reconstruction. 2. RIH with bit and scraper to just be unable to get below perfs then TOH. 3. Cut off wellhead and verify that	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to a class and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I rface behind each casing string before cementing to set to the complete t	Notify OCD 24 hrs. Prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then			
of starting any proposed we proposed completion or reconstruction. Yates Petroleum Corporation plans MIRU any safety equipment as reconstruction. RIH with bit and scraper to just be unable to get below perfs then TOH. Cut off wellhead and verify that perforate and circulate cement to sue. Install dry hole marker and cleans.	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to a class and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I rface behind each casing string before cementing to set to the complete t	Notify OCD 24 hrs. Prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then			
of starting any proposed we proposed completion or reconstruction. Yates Petroleum Corporation plans MIRU any safety equipment as reconstruction. RIH with bit and scraper to just the unable to get below perfs then TOH. Cut off wellhead and verify that perforate and circulate cement to su	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to a class and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I rface behind each casing string before cementing to set to the complete t	Notify OCD 24 hrs. prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then turface inside production casing.			
of starting any proposed we proposed completion or reconstruction. 1. MIRU any safety equipment as rown 2. RIH with bit and scraper to just be unable to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and cleans wellbore schematics attached	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. Prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then			
of starting any proposed we proposed completion or reconstruction. 1. MIRU any safety equipment as rown 2. RIH with bit and scraper to just be unable to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and cleans wellbore schematics attached	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to a class and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I rface behind each casing string before cementing to set to the complete t	Notify OCD 24 hrs. prior to any work done. to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing.			
of starting any proposed we proposed completion or reconstruction. 1. MIRU any safety equipment as rown 2. RIH with bit and scraper to just be unable to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and cleans wellbore schematics attached	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. prior to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then turface inside production casing.			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to sue 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. prior to 500' with 115 sx. NOTE: If fill is tagged and ang cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. RECEIVED JAN 2 8 2013			
of starting any proposed we proposed completion or reconstruction. 1. MIRU any safety equipment as rown 2. RIH with bit and scraper to just be unable to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and cleans wellbore schematics attached	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. prior to any work done. to 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing.			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to sue 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. prior to 500' with 115 sx. NOTE: If fill is tagged and ang cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. RECEIVED JAN 2 8 2013			
of starting any proposed we proposed completion or recovered to proposed completion or recovered to the proposed completion or recovered to the proposed completion or recovered to the proposed to the propos	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date:	Notify OCD 24 hrs. prior to any work done. to 500' with 115 sx. NOTE: If fill is tagged and and cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. RECEIVED JAN 2 8 2013 NMOCD ARTESIA			
of starting any proposed we proposed completion or recovered to proposed completion or recovered to the proposed completion or recovered to the proposed completion or recovered to the proposed to the propos	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location.	Notify OCD 24 hrs. prior to any work done. to 500' with 115 sx. NOTE: If fill is tagged and and cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. RECEIVED JAN 2 8 2013 NMOCD ARTESIA			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to sue 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date:	Notify OCD 24 hrs. prior to any work done. To any work done. To 500' with 115 sx. NOTE: If fill is tagged and any cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. RECEIVED JAN 2 8 2013 NMOCD ARTESIA			
of starting any proposed we proposed completion or recovered to proposed completion or recovered to the proposed completion or recovered to the proposed completion or recovered to the proposed to the propos	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement to and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date:	Notify OCD 24 hrs. prior to any work done. to 500' with 115 sx. NOTE: If fill is tagged and and cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. PECEIVED JAN 2 8 2013 NMOCD ARTESIA			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information SIGNATURE	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. Delow perfs at 1420' and circulate Class "C" cement of and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	Notify OCD 24 hrs. prior to any work done. To any work done. To 500' with 115 sx. NOTE: If fill is tagged and ang cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then aurface inside production casing. RECEIVED JAN 2 8 2013 NMOCD ARTESIA dge and belief. Supervisor DATE January 24, 2013			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to sue 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. Delow perfs at 1420' and circulate Class "C" cement of and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	Notify OCD 24 hrs. prior to any work done. To any work done. To 500' with 115 sx. NOTE: If fill is tagged and ang cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then aurface inside production casing. RECEIVED JAN 2 8 2013 NMOCD ARTESIA dge and belief. Supervisor DATE January 24, 2013			
of starting any proposed we proposed completion or recovered yates Petroleum Corporation plans 1. MIRU any safety equipment as recovered to get below perfs then TOH 3. Cut off wellhead and verify that perforate and circulate cement to su 4. Install dry hole marker and clean Wellbore schematics attached NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information SIGNATURE Type or print name Tina Hue For State Use Only	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement of and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date: TITLE Regulatory Reporting TITLE Regulatory Reporting E-mail address: tinah@yatespetrole Approval Granted on	Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. Notify OCD 24 hrs. prior to any work done. NOTE: If fill is tagged and not then surface inside production casing. PECEIVED JAN 2 8 2013 NMOCD ARTESIA Appendix Date Danuary 24, 2013 PHONE: 575-748-4168			
of starting any proposed we proposed completion or recovered to proposed completion or recovered to the proposed completion or recovered to the proposed completion or recovered to the proposed to the propos	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. to plug and abandon this well as follows: needed. NU BOP. TOH with production equipment. below perfs at 1420' and circulate Class "C" cement of and set a CIBP above perfs at 1250' before circulating there is cement behind all casing strings at surface. I reface behind each casing string before cementing to so a location. On will use steel pits and no earth pits Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	Notify OCD 24 hrs. prior to any work done. To any work done. To 500' with 115 sx. NOTE: If fill is tagged and ng cement to 500' (90 sx). If so, cement to surface with 60 sx. If not then surface inside production casing. PECEIVED JAN 2 8 2013 NMOCD ARTESIA dge and belief. Supervisor DATE January 24, 2013 PHONE: 575-748-4168			

Well Name: J Lazy J #1 Field: Eagle Creek Location: 2310' FNL & 330' FEL Sec 22-17S-25E


County: Eddy State: New Mexico

GL: 3,518' Zero: KB:

Spud Date: 3/18/1970 Completion Date: 7/27/1970

Comments: API # 30015202930000

BEFORE



10 3/4" csg @ 718' Mudded.

Casing Program

Size/Wt/Grade

10 ¾" 36# K-55

7" 23# K-55

4½° 9.5# & 5½" 15.5# K-55

Depth Set

718'

1,150'

1,431'

10" hole

7" csg @ 1,150' cmtd w/ 810 sx.

6 1/4" hole

San Andres perfs 1,351-1,403' (24)

PBTD 1,431'

4 ½" & 5 ½" csg @ 1,431' cmtd w/ 150 sx.

TD 1,431'

DATE: 12/13/2012

Well Name: J Lazy J #1 Field: Eagle Creek Location: 2310' FNL & 330' FEL Sec 22-17S-25E


County: Eddy State: New Mexico
GL: 3,518' Zero: KB:

Spud Date: <u>3/18/1970</u> Completion Date: <u>7/27/1970</u>

Comments: API # 30015202930000

12 1/2" hole

AFTER



10 ¾" 36# K-55	
	718'
7" 23# K-55	1,150'
4½" 9.5# & 5½" 15.5# K-55	1,431'

10" hole

7" csg @ 1,150' cmtd w/ 810 sx.

10 3/4" csg @ 718' Mudded.

6 1/4" hole

San Andres perfs 1,351-1,403' (24)

PBTD 1,431'

4½" & 5½" csg @ 1,431' cmtd w/ 150 sx.

TD 1,431'

DATE: 12/13/2012

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator	YaTes 1	eTroleum	Corp.
	/	1 Lazy 1	
API #:	30-015	5-20293	·

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

- 9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.

11. Minimum WOC time for tag plugs will be 4 hrs.

DG

Date: 1/30/2018