Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMNM104661

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
shandoned well. Use form 3160-3 (APD) for such proposals

Ó.	If Indian,	Allottee c	or Tribe N	lame

abandoned we	6. If Indian, Allottee	or Tribe Name					
SUBMIT IN TRI	7. If Unit or CA/Agre NMNM120212	7. If Unit or CA/Agreement, Name and/or No. NMNM120212					
Type of Well Oil Well		8. Well Name and No. TRINITY 20 FEDERAL COM 2					
2. Name of Operator CIMAREX ENERGY COMPAN	9. API Well No. 30-015-34500-0)0-S1					
3a. Address 600 NORTH MARIENFELD S MIDLAND, TX 79701	TREET SUITE 600 3b. P	hone No. (include area code) 432-620-1936	10. Field and Pool, or COTTONWOO				
4. Location of Well (Footage, Sec.; T.	., R., M., or Survey Description)	HECEIVE	11. County or Parish,	and State			
Sec 20 T25S R26E NWSW 19		FEB 1 2 20					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATIONAL REPORT, OR OTHER DATA							
TYPE OF SUBMISSION			ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off			
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity			
☐ Subsequent Report	Casing Repair	■ New Construction	☐ Recomplete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon				
	☐ Convert to Injection	☑ Plug Back	☐ Water Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) CIMAREX ENERGY RESPECTFULLY REQUESTS APPROVAL TO PERFORM OPEN HOLE ISOLATION PROCEDURE AS INDICATED BELOW: Performed Pressure Test - Per Paul Swartz BLM PUMPED 5 BBLS DOWN TBG, PRESSURED UP TO 3,500#, SHUT DOWN PUMP, 30 MINUTES AFTER SHUTTING DOWN PUMP, PRESSURE GUAGE READING ON TBG WAS 2,500#. MR SWARTZ W/ BLM WAS PRESENT FOR INJECTION RATE. Procedure: 1. Notify BLM ? Paul Swartz of intent to work on well. 2. MIRU pulling unit. Set pipe racks w/ 2 7/8 P-110 Work string. Blow well down, and kill well w/ BW as needed. ND WH, NU BOP. 3. Take measures to either retrieve or otherwise clear the stuck spear from the SEE ATTACHED FOR CONDITIONS OF APPROVAL AND CONDITIONS OF APPROVAL							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #162052 verified by the BLM Well Information System For CIMAREX ENERGY COMPANY OF CO, sent to the Carlsbad Committed to AFMSS for processing by KURT SIMMONS on 12/13/2012 (13KMS4123SE) Name (Printed/Typed) TERRI STATHEM Title REGULATORY ANALYST							
Signature (Electronic S		Date 12/09/20					
THIS SPACE FOR FEDERAL OR STATE OFFICE DEL TOUTE							
Approved By (BLM Approver Not Standard By (BLM Approver Not Standard By Approved By Ap	d. Approval of this notice does not war itable title to those rights in the subject of operations thereon. U.S.C. Section 1212, make it a crime for	Office Carlsbac	FFR 8 2013 /s/ Chris Wall BUREAU OF LAND MANAGE willfully to Africa San Stephing of the	MEN T			
States any false, fictitious or fraudulent s	tatements or representations as to any n	natier within its jurisdiction.	• .				

Additional data for EC transaction #162052 that would not fit on the form

32. Additional remarks, continued

4.5" liner.
4. MIRU wireline truck. RIH w/ GRJB for 4.5.11.6 liner. RIH & Perforate squeeze circulation holes @ 9951' (50' above 7" csg shoe per BLM requirement). RDMO wireline.
5. RIH w/ 4.5" CICR and set @ 10700'. (Notify BLM? Paul Swartz of intent to pump cement? 4 hr minimum notice) MIRU cement company. Mix and pump 110 sx Class H cement and flush w/ 60 bbls. Sting out of retainer and leave 2 bbls cement on top of retainer. Sting out of retainer and POOH to 9890'. Reverse hole clean. POOH w/ tbg and setting tool. WOC. RIH w/ tbg and tag cement (minimum cement top to be at 9951') w/ BLM witness.
6. Once Tagged cement depth desired by BLM is satisfied, resume efforts to remove top section of liner top. If successful in removing liner from 9890' up, Include bottom perforated interval in Wolframs recompletion. If upsuccessful in removing liner section. Recomplete Wolframs without

Wolfcamp recompletion. If unsuccessful in removing liner section, Recomplete Wolfcamp without bottom perf interval and follow original recompletion procedure as needed.

Conditions of Approval

Cimarex Energy Company Trinity 20 Federal Com 2 API 30-015-34500 T25S-R26E, Sec 20 February 8, 2013

- 1. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 9,600' or below to top of cement. The CBL may be attached to a pswartz@blm.gov email.
- 4. Notify BLM 575-200-7902 before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. If there is no response, 575-361-2822. Note the contact, time, & date in your subsequent report.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. A minimum of 3,000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 10. The BLM PET witness is to run the tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.

- 11. Class H > 7,500' & C < 7,500') cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100' cement plug across the drilled wellbore. Add 10% to the 100' slurry volume for each 1,000' of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 12. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 13. Step 6 of NOI: A balanced cement required is required to be set from the CICR at ~10,700' to 50' above the 7" csg shoe or 50' above the top of the 4 ½" liner whichever is higher,
- 14. After setting the top plug and before perforating, perform a BLM PET witnessed (charted) casing integrity test of 600 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 15. File intermediate **subsequent sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 16. Submit the BLM Form 3160-4 Completion Report within 30 days of the date all BLM approved procedures are complete. Include all formation tops including the Wolfcamp formation.

Amendments to the Communitization Agreement must also be made if new formations are added.

17. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 18. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 05/10/2013.
- 19. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

PRS/CRW

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html § 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.