

	•		
Submit Copy To Appropriate District State of New Mexico			Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources		esources WELL API	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		20.015.2021	1
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		ISION 5 Indicate	Type of Lease
$\frac{District III}{1000 \text{ Rio Brazos Rd., Aztec, NM 87410}}$	District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.		TE 🛛 FEE 🗌
$\frac{\text{District IV}}{1220 \text{ S}} = (505) 476-3460$	Santa Fe, NM 87505	6. State Oil	& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			me or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			DRAW UNIT
PROPOSALŚ.)		8. Well Nur	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		9. OGRID 1	
Devon Energy Production Company, LP		6137	
3. Address of Operator			me or Wildcat
333 W. Sheridan Avenue, Oklahoma City, OK 73102		COTTON D	RAW;ATOKA, SOUTH
4. Well Location			
Unit Letter_L:198	80feet from theSouthli		m theWestline
Section 35 Township 24S Range 31E NMPM Eddy, County, NM			
	1. Elevation (Show whether DR, RKB 508' KB; 3483' GL	, <i>RT, GR, etc.)</i>	
3	508 KB; 5485 GL		an na shi ka kura san shi ya s
12 Check Apr	ropriate Box to Indicate Nature	of Notice Report or O	ther Data
	ropitate Dox to indicate Mature	of Notice, Report of O	diel Data
NOTICE OF INTE		SUBSEQUENT	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			PÀNDA 🗌
		SING/CEMENT JOB	
OTHER:		IER:	<u>``</u>
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
hickore combranes in the			
1. MIRU. Retrieve RBP @ 8,995'.			
2. Set CIBP @ 13,850'. Spot 145 sx cement on top. Tag TOC. (CTOC @ 12,250'. 5-1/2" liner top @ 12,282')			
 Spot 25 sx cement @ 8,300'. (CTOC @ 8,170'. Top of Bone Spring @ 8,300') Spot 25 sx cement @ 7,940'. (CTOC @ 7,810'. DV Tool @ 7,886') 			
5. Cut & pull 7-5/8" casing from 6,620'. Spot 50 sx cement @ 6,670'. Tag TOC. (CTOC @ 6,520')			
6. Spot 100 sx cement @ 4,475'. Tag TOC. (CTOC @ 4,300'. Delaware top @ 4,438'. 10-3/4 shoe @ 4,425')			
 Spot 45 sx cement @ 4,200'. Tag TOC. (CTOC @ 4,090'. B Salt @ 4,190') Spot 45 sx cement @ 1,012'. Tag TOC. (CTOC @ 902'. T Salt @ 1,012') 			
	g TOC. (CTOC @ 665'. 13-3/8'' sho		
10. Circulate 45 sx cement from 11	0' to surface.		RECEIVED
11. Cut wellhead off and set dry ho	le marker. Approved for	plugging of well bore only. r bond is retained pending receipt	TECEIVED
Spud Date:	D = D = 1 = 01 Cr 103 (Sub	sequent Report of Well Plugging)	MAY 03 2013
	which may be	tound at OCD web Page under	
			MOCD ARTESIA
I hereby certify that the information abo	ve is true and complete to the best of	my knowledge and belief.	
ρ ρ			
SIGNATURE Konnie Sla	TITLE Operations	Technician	DATE 5-2-13
Type or print name _Ronnie Slack	E-mail address: _Ronni	e.Slack@dvn.com PH	ONE:405-552-4615
For State Use Only	·· 1	*	1 1
APPROVED BY	L TITLE DIST	Supervisor	DATE 5/10/2013
Conditions of Approval (if any):			
Approval Granted providing work			
SEE ATTACHED COR'S Approval Granted providing work is complete by May 10 - 2014			4 10 - 2014
		lyear	6
		r 1	





|

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: DEVON Energy

Well Name & Number: COTTON Draw Unit #67

API #: <u>30 ~ 015 - 20210</u>

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.10. Plugs may be combined after consulting with and getting approval from NMOCD.11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: May 15 - 2013

APPROVED BY Mach

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman

1

- o Devonian
- o Morrow
- o Wolfcamp
- o Bone Spring
- o Delaware
- Any Salt Section (Plug at top and bottom)
- o Abo
- o Glorieta
- Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).