Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010


SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NI	NMNM0428657 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ Gas Well ☐ Other						8. Well Name and No. OXY 33 FEDERAL-1			
2. Name of Operator OXY USA WTP LP	DUARTE	9. API Well No. 30-015-28970							
3a. Address PO BOX 4294 HOUSTON, TX 77210 3b. Phone No Ph: 713-51			3-6640 (include area code) 10. Field BURT			ield and Pool, or JRTON FLAT	eld and Pool, or Exploratory RTON FLAT STRAWN NORTH		
4. Location of Well (Footage, Sec., T			11. C	ounty or Parish,	and State				
Sec 33 T19S R28E SESE 510FSL 660FEL			EDDY CC			DDY COUNTY	Y, NM		
12. СНЕСК АРР	ROPRIĄTĘ BOX(ES) TO) INDĮCĄŢĮ	E NATURE OF N	OTICE,	REPOR'	Г, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				1				
Notice of Intent	☐ Acidize☐ Alter Casing	□ Dee	pen cture Treat	☐ Produ	•	art/Resume)	☐ Water Shut-		
☐ Subsequent Report	□ Casing Repair	□ Nev	v Construction	Reco	mplete		Other		
☐ Final Abandonment Notice	Change Plans	☐ Change Plans ☐ Plug and Abandon			Temporarily Abandon				
	☐ Convert to Injection ☐ Plug Back ☐ Water Disposal				1				
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi	ally or recomplete horizontally, k will be performed or provide operations. If the operation re- pandonment Notices shall be file	give subsurface the Bond No. o sults in a multip ed only after all	locations and measurn file with BLM/BIA le completion or recordequirements, including	red and true . Required impletion in ing reclamate	vertical de subsequen a new inte	epths of all pertin t reports shall be rval, a Form 316	nent markers and zon- filed within 30 days i0-4 shall be filed one	es.	
WORKOVER PROCEDURE 1- Move the Rig	CEIVED JL 2.6 2013								
2- Kill the well with 2%KCL. N	JL 2 6 2013	i							
Recover Upper packer 3- Retrieve packer from 8852? 4- RIH and fish DR latching plug from 10090? Permanent completion NMOCD ARTES'A SEE ATTACHED FOR CONDITIONS OF APPROVAL								L.	
Permanent completion 5- RIH D packer with seal bore	e extension sliding sleeve	e Gilocator v	ith 3 seal units	U	וועווט		All I NO W	,	
6- Sting into D packer at 1009	0? 	o, a todator v	min o ocar armo.		SU		torrecord OCD 7/3///	3	
14. I hereby certify that the foregoing is	Electronic Submission #2	USA WTP LP	sent to the Carls	sbad	•				
Name(Printed/Typed) JENNIFEF		ATORY S				_			
						APPRO	DVED		
Signature (Electronic S	Date 06/10/20					 			
	THIS SPACE FO	H FEDERA	T OR STATE (UFFICE	USE	27 الال	7913		
Approved By			Title		DITO	MANNA	a Trate Ov	DE T	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	·*	BU/	CARLSBAD FU	LD OFFICE		

Additional data for EC transaction #210157 that would not fit on the form

32. Additional remarks, continued

7- Drop standing valve to set at F nipple at 10107?
8- Pressure up tubing to 2500 psi and set D packer at 8852?. Release pressure.
9- Pressure up casing to 500 psi to verify packer at 8852? is set.
10- RU Wireline unit. Recover standing valve at 10107?. RD Wireline unit.
11- RIH G locator with 6 seal units, sliding sleeve on 2-3/8? tubing.
12- Sting into D packer at 8852?. Space out 2?.
13- Pressure up casing to 500 psi to verify seals are inside seal bore extension.
14- Sting out. Space out. Land tubing hanger.
15- Pressure up casing to 500 psi to verify seals are inside seal bore extension.

Put on Production 16- ND BOP. NU X/Mas Tree. 17- Rig Down Well Service Rig. 18- Swab the well and produce Strawn in Natural Flow.



OXY 33 Federal 1 30-015-28970 OXY USA WTP LP July 22, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by October 22, 2013.

Operator is approved for completion in the Strawn formation ONLY.

- 1. Before plugging and abandoning the Strawn formation, operator shall submit a sundry to plug the top of the Morrow formation.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 072213