

RECEIVED

NOV 3 0 2011

NMOCD ARTESIA

October 20, 2011

Ms. Jennifer Van Curen Bureau of Land Management 620 E. Green Street AMARILLO 921 North Bivins Carlsbad, NM 88220

Amarillo, Texas 79107 Phone 806,467,0607 Fax 806.467.0622

**ARTESIA** 

408 West Texas Ave. Artesia, New Mexico 88210 Phone 575.746.8768 Fax 575.746.8905

**AUSTIN** 

9II West Anderson Lane Suite 202 Austin Texas 78757 Phone 512.989.3428 Fax 512.989.3487

HOBBS

318 East Taylor Street Hobbs, New Mexico 88240 Phone 575.393.4261 Fax 575.393.4658

MIDLAND

290I State Hwy 349 Midland, Texas 79706 Phone 432.522.2133 Fax 432.522.2180

SAN ANTONIO

II Commercial Place Schertz, Texas 78154 Phone 210.265.8025 Fax 210.568.2191

TULSA 525 South Main Street Suite 535 Tulsa, Oklahoma 74103 Phone 918.742.0871

Fax 918.382.0232

**ENVIRONMENTAL CONSULTING ENGINEERING** 

> DRILLING CONSTRUCTION SPILL MANAGEMENT GENERAL CONTRACTING

Subject:

Soil Assessment and Remediation Work Plan

Cimerax Energy Corporation

Callaway Federal #3 Drilling Pit Remediation

API#30-015-23505

Dear Ms. Van Curen,

Cimerax Energy has contracted Talon/LPE (Talon) to perform soil assessment and remediation services at the referenced Callaway Federal #3 location. Our soil sampling results and proposed remediation activities consists of the following:

### **Incident Date**

May 18, 2011

### **Background Information**

The Callaway Federal #3 is located approximately twenty (20) miles northeast of Artesia, New Mexico. The legal location for the site is Section 6, Township 16 South and Range 28 East in Eddy County, New Mexico. More Specifically the latitude and longitude for the release are 32.9501 North and -104.21647 West.

According to the soil survey provided by the United States Department of Agriculture National Resources Conservation Services, the soil in this area is made up of Reeves-Gypsum land complex soils with 0 to 3 percent slopes. The local surface and shallow geology, Quaternary Age sedimentary deposits, is comprised of alluvium and eolian sands which includes silty soils under lain by gypsum and hard caliches. Drainage courses in this area are normally dry. The New Mexico State Engineer web site indicates the nearest ground water data to be in S34-T15S-R27E. The ground water in Section 34 is reported to be at depth of 85' below ground surface (bgs). The referenced groundwater data is presented in Appendix I.

The ranking for this site is 10 based on the as following:

Depth to ground water 50'-100' Wellhead Protection Area >1000' Distance to surface water body >1000'

Toll Free: 866,742,0742 www.talonlpe.com

### **Incident Description**

On May 18, 2011 the Bureau of Land Management notified Cimarex Energy Corporation that the drilling pit at the Callaway Federal #3 had not been re-vegetated. The BLM has requested a work plan for the restoration of the non-vegetated pit area.

### **Actions Taken**

On July 13, 2011 Talon mobilized personnel to begin the assessment and soil sampling for the construction of a work plan. The soil sample S-1 was collected from soil within the drilling pit area.

The soil sample was collected by Talon personnel wearing clean nitrile gloves. The sample was placed in a laboratory provided sample container and transported to Cardinal Laboratories in Hobbs, New Mexico for analysis of chlorides using Method SM4500CL-B. The complete laboratory report is attached as Appendix II.

### **Analytical Results**

Analytical results received from Cardinal Laboratories are summarized below:

July 18, 2011

Samp	ole, Depth	<u>Chlorides</u>
S-1	0'.	3,600 mg/kg

### **Summary and Conclusions**

- Groundwater in the project vicinity is greater than 50-feet below land surface per the New Mexico State Engineer Database.
- Based upon the results of the laboratory data obtained for this investigation, the chloride impacts have been documented to be 3,600 mg/kg at the surface of the drilling pit area.
- Based on the depth to groundwater and the chloride levels detected in the soil at the sample location, it is unlikely that the chloride impacts identified from this release will pose a threat to groundwater after proposed remediation activities are complete.

### **Proposed Remedial Actions**

- A decontamination station will be set up to pressure wash off all equipment and vehicles before leaving location to prevent the cross contamination of the African Rue.
- The surface of the closed drilling pit area will be bladed to prepare for the installation of a liner. Rock and debris will be deep buried into the drilling reserve pit area.
- A composite 20 millimeter liner will be installed over the closed drilling pit area. The edges of the liner will be keyed a minimum of three 3-feet deep into a trench excavated at the boundaries of the closed drilling pit area. Visually impacted area outside the drilling pit will be pushed up under the liner area with a dozer.
- New soil will be transported to the location from a local borrow pit and will be placed over the top of the 20 millimeter liner with a 3-foot soil lift.
- The soil lift will be contoured to match the surrounding terrain and seeded using the recommended BLM seed mixture for the area.
- Erosion control berms will be installed to prevent storm waters from running across the location.
- A final report will be provided to the Bureau of Land Management Carlsbad Office utilizing Form 3160.

If we can provide additional information or be of further assistance please contact our office at 575.746.8768.

Respectfully submitted,

TALON/LPE

Mile & well


Mike Stubblefield

Project Manager

David J. Adkins

District Manager

### SITE MAP





Drawn By: TJS

Cimarex Energy
Artesia, Eddy County, New Mexico Site Plan

## APPENDIX I GROUNDWATER DATA



# New Mexico Office of the State Engineer Water Column/Average Depth to Water

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

Sub Depth Depth Water POD Number basin, Use County 64:16:44 Sec Tws, Rng X Y Distance Well WaterColumn

RA 08613

DOM CH 4 4 1 34 15S 27E

572480 3648590\*

2952 200

85 11

Average Depth to Water:

85 feet

Minimum Depth:

85 feet

Maximum Depth:

85 feet

**Record Count: 1** 

UTMNAD83 Radius Search (in meters):

Easting (X): 573304

Northing (Y): 3645755

Radius: 5000

\*UTM location was derived from PLSS - see Help

### **James Tinney**

From:

Mark Cummings

Sent:

Wednesday, May 18, 2011 11:00 AM

To:

Terry Ainsworth; James Tinney

Subject:

FW: location that need work-response requested.

FYI, on the lease inspection that we should be doing now let's make sure we catch this kind of stuff before the BLM ships us these type of letters.

Thanks

Mark Cummings Midland - Texas Cimarex Energy

### mcummings@cimarex.com

(432) 571-7816 office (956) 744-0137 cell

-----Original Message-----

From: Zeno Farris

Sent: Wednesday, May 18, 2011 10:45 AM

To: Edgar F. Locke; John Osborne; Mark Martino; Mark Cummings

Subject: FW: location that need work-response requested.

----Original Message-----

From: jvancure@blm.gov [mailto:jvancure@blm.gov]

Sent: Wednesday, May 18, 2011 10:37 AM

To: Zeno Farris

Subject: location that need work-response requested.

- 1. Callaway Fed 3--The location has not vegetated and is past due on a reclamation. Complete reclamation of location by 6-17-11. Contact me with plan of action before start.
- 2. Callaway Fed 4--Remove unused equipment, Replace windsock, Downsize and use material for pit remediation. Contact me before starting pit remediation.
- 3. Callaway Fed 1--Remove unused tank, Downsize location and use material for pit remediation after testing and also to prevent stormwater from east. Contact me before starting any remediation and so we can go over test sampling of chlorides.
- 4. Callaway Fed 2-- Block trespass road, Remove polyline from pit area, Remediation of pit area and stormwater prevention a must. Contact me before

## APPENDIX II LABORATORY RESULTS



July 18, 2011

MIKE STUBBLEFIELD

TALON LPE

408 W. TEXAS AVE.

ARTESIA, NM 88210

RE: CALLAWAY FED #3

Enclosed are the results of analyses for samples received by the laboratory on 07/14/11 14:47.

Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method SW-846 8260

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method TX 1005

Total Petroleum Hydorcarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2

Haloacetic Acids (HAA-5)

Method EPA 524.2

Total Trihalomethanes (TTHM)

Method EPA 524.4

Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

Celey D. Keine

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keene

Lab Director/Quality Manager



### Analytical Results For:

TALON LPE MIKE STUBBLEFIELD 408 W. TEXAS AVE. ARTESIA NM, 88210

Fax To:

(575) 745-8905

Received:

07/14/2011

Sampling Date:

07/13/2011

Reported:

07/18/2011

Sampling Type:

Soil

Project Name:

CALLAWAY FED #3

Sampling Condition:

Cool & Intact

Project Number:

701162.007.01

Sample Received By:

Jodi Henson

Project Location:

SEC. 6 - T16S - R28E

### Sample ID: S-1 0' DRILLING PIT (H101458-01)

Chloride, SM4500CI-B	mg/	'kg	Analyze	d By: HM					
- Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	3600	16.0	07/15/2011	ND	416	104	400	3.77	

Cardinal Laboratories

\*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed walved unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claims is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This

Celey D. Keine



#### **Notes and Definitions**

ND Analyte NOT DETECTED at or above the reporting limit

RPD Relative Percent Difference

\*\* Samples not received at proper temperature of 6°C or below.

\*\*\* Insufficient time to reach temperature.

Chloride by SM4500Cl-B does not require samples be received at or below 6°C

Samples reported on an as received basis (wet) unless otherwise noted on report

Cardinal Laboratories

\*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg & Keine



### CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

101 East Marland, Hobbs, NM 88240 (575) 393-2326 FAX (575) 393-2476

Company Name: Talon / LPF			BILL TO ANALYSIS REQUEST																
Project Manager: mike Stubblefield				P.O. #:															
Address: 408 N. Tekar Auc.				Company: Talon/LPE													ĺ		
City: Arteria State: NM Zip: 88210				Attn:															
Phone #: 525-441-7254 Fax #:			Address:				1	l											
Project #: 70 1162.007.01 Project Owner: Cimarcy Energy			City:					ı											
Project Name: Callaway Fed. No. 3				State: Zip:															
Project Location	1: SCC. 6- TIES-	RZBE			Phone #:				1			- 1							
Sampler Name:	mile Stilleli	e <i>s</i>			Fax #:			_ ا										1	
FOR LAB USE ONLY	٧		٠.	MATRIX		PRESERV.	SAMPL	ING	الح.	ļ	. 1								
			OM	S EE S					10:	1									
Lab I.D.	Sample I.	n	NER NATE			w _			chlorides	İ									
Lau I.D.	Sample i.	.D.	080	JAND JAND JEW	œ	GAS COC				l									
H101423			(G)RAB OR (C)OMP	# CONTAINERS GROUNDWATER WASTEWATER SOIL OIL	THE	ACID/BASE ICE / COOL OTHER:	DATE	TIME	Total	İ									
-1	S.1 o' drilling	ōΤ	Ğ	* J > 0, 0	+ 9-	1		4:15%											
	<u> </u>					- · · V	1.7. 47.3.												 
The state of the s	A THE PART OF THE														.,				 
								:											 
								:			Ī			:					
	. ,,															:			 
																			 , <u>.</u>
								····-											 
	,	·	·							··									 
	nd Damages. Cardinal's kability and di									l					Ь			L	 
service. In no event shall C	ng those for negligence and any other or profinal be liable for incidental or conse	quental dámages, including	edthau:	limitation, business interruptions	, lass o	tuse, or loss of p	rofits incurred by	client, its subsidio	ries.	ne				•					
affiliates or successors arising out of or related to the partamence of services hereunder by Cardinal, regardless of whether such claim   Relinquished By:			Phone R			Phone Re	sult:	☐ Yes		No	Add'l F		#:				 		
mile Sullfall 7/19/2011			V & 11 1 1400			Fax Resul	 МО	Add'i F	ах #:			**********		 					
Relinquished B	lifett	Date:	Re	ceived By:	4	10 VI	<i>J</i> 3	l .											
	•	Time:	O	•															
Dolivered De	: (Circle One)	1		Sample Condi	tion	CHECK	KED BY:												Ī
1	•	5	0	Cool Intact	_		tials)												
Sampler - UPS - Bus - Other:																			