rm 3160-5 ugust 2007)		UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAG	NTERIOR	OCD Artes	sia	OMB N Expires	APPROVED 40. 1004-0135 1 July 31, 2010
D		NOTICES AND REPO				5. Lease Serial No. NMNM99015	
ab	andoned we	is form for proposals to II. Use form 3160-3 (API) for such j	proposals.		6. If Indian, Allottee	or Tribe Name
SU	BMIT IN TRI	IPLICATE - Other instruc	tions on rev	verse side.		7. If Unit or CA/Agre	eement, Name and/or No.
. Type of Well	as Well 🔲 Oth	her				8. Well Name and No SEVEN RIVERS	17 FEDERAL 1H
Name of Operator OXY USA INC.		Contact: E-Mail: david_stew	DAVID STEV art@oxy.com	WART		9. API Well No. 30-015-33430	
a. Address P.O. BOX 50250 MIDLAND, TX 7			3b. Phone No Ph: 432-68 Fx: 432-68)	10. Field and Pool, or N. SEVEN RIV	r Exploratory ERS GLOR YESO
	0	T., R., M., or Survey Description,)			11. County or Parish,	and State
Sec 17 T20S R2 32.569780 N Lat		250FSL 1650FWL) W Lon				EDDY COUNT	Y, NM
12. C	HECK APPI	ROPRIATE BOX(ES) TO) INDICATE	E NATURE OF N	NOTICE, RE	PORT, OR OTHE	R DATA
TYPE OF SUBM	IISSION			TYPE OI	F ACTION		
Notice of Intent		Acidize	Dee Dee	-	—	on (Start/Resume)	□ Water Shut-Off
🗖 Subsequent Rep	ort	 Alter Casing Casing Repair 		cture Treat v Construction	□ Reclama		Well Integrity Other
🗖 Final Abandonn	nent Notice	Change Plans		g and Abandon		arily Abandon	
		Convert to Injection	🔀 Plug	g Back	U Water D	isposal	
testing has been com determined that the s OXY USA Inc. re originally approv oprations and the	pleted. Final Al ite is ready for f espectfully rec ed 2/6/13 be e work will be	d operations. If the operation res bandonment Notices shall be file final inspection.) quests that the attached ap given an extension. Oxy h e started as soon as appro- riginal approval, EC transa	ed only after all pproved sund has received val has been	requirements, includ dry notice to plug company approv received.	ling reclamation	, have been completed, s the Accepted	and the operator has
						PANA.	
WORK	to be	complet Feb. 6;	0 6		wen	1	\mathcal{A}^{+}
(DAS	From	Reb. 6.	2105	Still	appli	1.	
			201.0		CPTC	J SEE ATT	ACHED FOR
4. I hereby certify that	the foregoing is	s true and correct. Electronic Submission #2 For OX	220932 verifie	d by the BI M We	Il Information	System CONDITI	UNS OF APPI
	•	For OX Committed to AFMSS for p	. I OSA 110.,	pent to the Gallsr	Jau		11 (A) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B
	I) DAVID ST	ſEWART		Title SR. RE	GULATORY	ADXISOBDO	
Name(Printed/Typed							
Name(Printed/Typed				Date 09/24/2			0010
Name(Printed/Typed	(Electronic S				OFFICE US	EASFP 30	
	(Electronic S		R FEDER/	AL OR STATE			2013
Signature	(Electronic S		DR FEDER#			le ano an th	1 Alla
Signature Approved By nditions of approval, if	any, are attache		not warrant or			IREAD DE LAND MA	ALL POOR

4

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

٠

gust 2007)	UNITED STATES	S	OC	D Artesia		PPROVED	
	EPARTMENT OF THE I BUREAU OF LAND MANA				OMB NO. 1004-0135 Expires: July 31, 2010		
SUNDRY		RTS ON WI	ELLS		5. Lease Serial No. NMNM99015		
abandoned w	his form for proposals to ell. Use form 3160-3 (API	D) for such p	propósals.		6. If Indian, Allouee or	Tribe Name	
SUBMIT IN TR	NPLICATE - Other instruc	ctions on rev	verse side.		7. If Unit or CA/Agreen	nent, Name and/or No.	
Type of Well B Oil Well Gas Well O	ther.				8. Weil Name and No. SEVEN RIVERS 17 FEDERAL 1H		
Name of Operator OXY USA INC	Contact: E-Mail: jennifer_du	JENNIFER A larte@oxy.com			9. API Well No. 30-015-33430		
Address PO BOX 4294 HOUSTON, TX 77210		3b. Phone No Ph: 713-51	. (include area code 3-6640	e)	10. Field and Pool, or E N 7 RIVERS GLC	xploratory DRIETA YESO	
Location of Well (Footage, Sec.,	T., R., M., or Survey Description))			11. County or Parish, ar	nd State	
Sec 17 T20S R25E SESW 12	250FSL 1650FWL		•		EDDY COUNTY,	NM ·	
				· · · · · · · · · · · ·	·		
	ROPRIATE BOX(ES) TO	DINDICATE	·		EPORT, OR OTHER	DATA	
TYPE OF SUBMISSION	ļ			OF ACTION	· · · · · · · · · · · · · · · · · · ·		
🕱 Notice of Intent	Notice of Intent		Deepen Produce Fracture Treat Reclar		tion (Start/Resume) 🔲 Water Shut-Off		
Subsequent Report	Casing Repair	—	Construction	—			
Final Abandonment Notice	Change Plans	D Plug			rarily Abandon		
Describe Proposed or Completed Op	Convert to Injection	🛛 Plug		U Water I	•		
Attach the Bond under which the wo following completion of the involve	d operations. If the operation res	sults in a multipl	e completion or rec	completion in a	new interval a Form 3160-	led within 30 days 4 shall be filed once	
Attach the Bond under which the Wo following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba	sults in a multipl ed only after all r ack and recor	e completion or rec requirements, inclu- mplete the Seve	A. Required sub completion in a p ding reclamation on Rivers 17	new interval, a Form 3160 n, have been completed, an Federal	led within 30 days 4 shall be filed once d the operator has $a = \frac{2}{12}$	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba	sults in a multipl ed only after all r ack and recor	e completion or rec requirements, inclu- mplete the Seve	A. Required sub completion in a p ding reclamation on Rivers 17	new interval, a Form 3160 n, have been completed, an Federal	led within 30 days 4 shall be filed once d the operator has	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50' of of 5- RIH Open ended and tag of 6- Fill casing and test to 500 f 7- Pull tubing to 3600'.	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the NU BOP er. POH scanning tubing. sement above the packer a ement top at 9300' osi	sults in a multipl ed only after all r ack and recor current and p at 9350'.	e completion or rec requirements, inclu- mplete the Seve proposed wellbo	A. Required sul completion in a ding reclamation on Rivers 17 ore diagrams.	new interval, a Form 3160 n, have been completed, an Federal	led within 30 days 4 shall be filed once d the operator has Nocl 2/11/13 Nocl for 180010 NMOCD	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well, ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50 of of 5- RIH Open ended and tag of 6- Fill casing and test to 500 p	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the NU BOP er. POH scanning tubing. sement above the packer a ement top at 9300' osi	ack and recor current and p at 9350'.	PECEN FEB 11 2	A. Required sul completion in a ding reclamation on Rivers 17 ore diagrams. SEE EDOON 013	new interval, a Form 3160 have been completed, an Federal ATTACHED FC DITIONS OF A	led within 30 days 4 shall be filed once d the operator has Nocl 2/11/13 Nocl for 180010 NMOCD	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50' of of 5- RIH Open ended and tag of 6- Fill casing and test to 500 f 7- Pull tubing to 3600'.	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the strue and attached are the ement above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo	ack and recor current and p at 9350'.	PECEN FEB 112	A. Required sul completion in a i ding reclamation en Rivers 17 ore diagrams. SEE EDOON 013 ENAT	new interval, a Form 3160 have been completed, an Federal ATTACHED FC DITIONS OF A System 2013 ()	led within 30 days 4 shall be filed once d the operator has Nocl 2/11/13 Nocl for 180010 NMOCD	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50° of of 5- RIH Open ended and tag of 6- Fill casing and test to 500 p 7- Pull tubing to 3600'.	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the strue and attached are the ement above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo R A DUARTE Submission)	ack and recor current and p at 9350'. 87823 verifie Y USA INC, s or processing	e completion or rec requirements, inclu- mplete the Seve proposed wellbo PEB 112 IOCD A by the BLM We ent to the Carlst by KURT SIMMO Title REGUI	A. Required sul completion in a i ding reclamation en Rivers 17 bre diagrams. SEE EDOON 013 Constantion bad DNS on 01/24/ LATORY AN/ 2013	ATTACHED FC DITIONS OF A System 2013 () ALYST	led within 30 days 4 shall be filed once d the operator has Nocl 2/11/13 Nocl for 180010 NMOCD	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50' of 0 5- RIH Open ended and tag of 6- Fill casing and test to 500 f 7- Pull tubing to 3600'. I hereby certify that the foregoing i Name(Printed/Typed) JENNIFE	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the envert above the packer a ement above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo R A DUARTE	ack and recor current and p at 9350'. 87823 verifie Y USA INC, s or processing	e completion or rec requirements, inclu- mplete the Seve proposed wellbo PEB 112 IOCD A by the BLM We ent to the Carlst by KURT SIMMO Title REGUI	A. Required sul completion in a i ding reclamation en Rivers 17 bre diagrams. SEE EDOON 013 Constantion bad DNS on 01/24/ LATORY AN/ 2013	ATTACHED FC DITIONS OF A System 2013 () ALYST	led within 30 days 4 shall be filed once d the operator has Nocl 2/11/13 Nocl for 180010 NMOCD	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well, ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50' of c 5- RIH Open ended and tag c 6- Fill casing and test to 500 p 7- Pull tubing to 3600'. Thereby certify that the foregoing i Name(Printed/Typed) JENNIFE Signature (Electronic 1)	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the strue and attached are the ement above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo R A DUARTE Submission)	ack and recor current and p at 9350'. 87823 verifie Y USA INC, s or processing	e completion or rec requirements, inclu- mplete the Seve proposed wellbo PEB 1 1 2 Det BLM We ent to the Carlst by KURT SIMMO Title REGUI Date 01/22/2 L OR STATE	A. Required sul completion in a i ding reclamation en Rivers 17 bre diagrams. SEE EDOON 013 Constantion bad DNS on 01/24/ LATORY AN/ 2013	ATTACHED FC DITIONS OF A System 2013 () ALYST	Ied within 30 days 4 shall be filed once d the operator has react for record NAMOCE OR PPROVAL ROVED	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50° of to 5- RIH Open ended and tag to 6- Fill casing and test to 500 p 7- Pull tubing to 3600'. Thereby certify that the foregoing i Name(<i>Printed/Typed</i>) JENNIFE Signature (Electronic : proved By	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the ment above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo R A DUARTE Submission) THIS SPACE FO	ack and recor current and p at 9350'. 87823 verifier Y USA INC, s or processing R FEDERA	e completion or rec requirements, inclu- mplete the Seve proposed wellbo PEB 112 Defent to the Carlst by KURT SIMMO Title REGUI Date 01/22/2 L OR STATE Title	A. Required sul completion in a i ding reclamation en Rivers 17 bre diagrams. SEE EDOON 013 Constantion bad DNS on 01/24/ LATORY AN/ 2013	ATTACHED FC DITIONS OF A System 2013 () ALYST BUREAU OF L	led within 30 days 4 shall be filed once id the operator has react for record removed PR PPROVAL ROVED 6 2013 - Daier - 2 March J. (1990) - Daier - 2 - Daier - 2	
following completion of the involve testing has been completed. Final A determined that the site is ready for OXY USA INC respectfully re #1H well. Below is our proce WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. 3- Release On Off from packe 4- RIH bailer and spot 50' of to 5- RIH Open ended and tag to 6- Fill casing and test to 500 p 7- Pull tubing to 3600'. Thereby certify that the foregoing i Name(<i>Printed/Typed</i>) JENNIFE Signature (Electronic : proved By	d operations. If the operation res bandonment Notices shall be file final inspection.) quest permission to plugba dure and attached are the superior of the packer a ement above the packer a ement top at 9300' osi s true and correct. Electronic Submission #1 For OX Committed to AFMSS fo R A DUARTE Submission) THIS SPACE FO	ack and recor current and p ack and recor current and p at 9350'. NA 87823 verifie Y USA INC, s or processing R FEDERA not warrant or subject lease	e completion or rec requirements, inclu- mplete the Seve proposed wellbo PEB 112 Definition of the Carlst by the BLM We ent to the Carlst by KURT SIMMO Title REGUI Date 01/22/2 L OR STATE Title	A. Required sul completion in a l ding reclamation en Rivers 17 bre diagrams. SEE EDOON 013 EDIA 1 DNS on 01/24/ LATORY ANJ 2013 OFFICE US	ATTACHED FC DITIONS OF A System 2013 () ALYST BUREAU OF L BUREAU OF L CARLSBA	Ied within 30 days 4 shall be filed once id the operator has Amoc 1 cr record AMOCE PPROVAL ROVED 16 2013 1 Daier 12 2013 1 Daier 12 2013 1 Daier 12 2 Daier 12	

Additional data for EC transaction #187823 that would not fit on the form

32, Additional remarks, continued

8- RU cement trucks. Spot 1st cement plug: 25 Sxs class C cement of 14.8 ppg with no bentonite from 3500' to 3600'. Flush tubing. POH.

9- RIH tubing and tag top of cement at 3350'. POH.

10- RU wireline. Perforate 3300'-3302'. RD wireline 11- RIH and set 5 1/2" packer at 3250'. Pressure up tubing and see if get returns up 8 5/8"-5 1/2" annulus.

12- POH

13- RIH cement retainer on working string and set cement retainer at 3250'. Test casing to 500 psi.

14- Sting out and circulate. Sting back into retainer. Pump water down tubing until establish circulation to surface.

15- RU cement truck. Pump cement slurry with additives at 3 bpm and maximum 1,000 psi on surface.
Volume should exceed 20% (8 5/8" - 5 1/2" annulus) volume.
16- Sting out. Reverse out. POH with stinger. WOC.

17- RIH bit and mill out cement and cement retainer. Clean to 3200'. Pressure test casing to 500 psi. POH.

18- Perforate Yeso 2532?-2610? (20 holes) 60 degrees phase
19- 1st stage: Frac Yeso formation with 1,200 Bbls of X-Link gel with 140,000 lbs of 20/40 white sand.

20- Perforate Yeso 2455?-2492? (10 holes) 60 degrees phase 21- 2nd stage: Frac Yeso formation with 800 Bbls of X-Link gel with 90,000 lbs of 20/40 white sand. 22- RIH bit and clean to 3200, POH.

23- RIH tubing and TAC to 3400'

24- RIH rod pump

25- Rig Down. Put the well on production.

Please let me know if additional information is required.



.



Conditions of Approval

OXY USA Inc. Seven Rivers 17 Federal 1H API 30-015-33430 T20S-R25E, Sec 17 February 06, 2013

- 1. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. Notify BLM **575-393-3612** before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 4. Surface disturbance beyond the existing pad must have prior approval.
- 5. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 6. Functional H_2S monitoring equipment shall be on location.
- 7. A minimum of 5000 (5M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M) Diagrams of Choke Manifold
- Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2
- 8. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. The BLM PET witness is to run tog tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.

- 10. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100ft cement plug across the drilled wellbore. Add 10% to the 100ft slurry volume for each 1000ft of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 11. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 12. Operator shall either blank off the packer located at 9,350' and pump a minimum of 200' of cement on top of the packer from 9,350'-9,150' or pump cement through the packer establishing the top of cement at 9,150'. Tag required. A minimum of 25 sx of cement is required for this procedure.
- 13. Operator shall place balanced cement plug from 6,340'-6,175'. Tag required.
- 14. Operator shall perf from 3,300'-3,302' and squeeze cement as proposed (BLM PET must witness the circulation of cement notify BLM 24 hours prior to squeezing cement at 575-393-3612). If cement does not circulate contact the BLM on call engineer. Tag top of cement.
- 15. Operator shall place balanced cement plug directly above the cement retainer from approximately 3,200'-2,959'. Tag required.
- 16. Submit a C-102 form with the appropriate pool name.
- 17. File intermediate subsequent sundry Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 18. Submit the BLM Form 3160-4 Completion Report within 30 days of the date all BLM approved procedures are complete.
- 19. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 20. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

JAM 020613