Submit I Cor Office	by To Appropriate District	Stat	e of New M	exico		Form C-103	
	75) 393-6161	Energy, Min	erals and Nati	ural Resources		Revised August 1, 2011	
	ch Dr., Hobbs, NM 88240 575) 748-1283				WELL API N 30-015-0202		
811 S. First S	61., Artesia, NM 88210			1 DIVISION	5. Indicate T		
	strict III - (505) 334-6178 1220 South St. Francis Dr.				STAT		
District IV -	(505) 476-3460	Sar	ita Fe, NM 8	7505	6. State Oil &	& Gas Lease No.	
1220 S. St. F 87505	rancis Dr., Santa Fe, NM						
07303	SUNDRY NOTIC	CES AND REPOR	TS ON WELLS	Ŝ	7. Lease Nar	ne or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					-	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					STATE 647 AC 711	
1. Type of	1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other					8. Well Number 125	
2. Name of Operator					9. OGRID N	umber 243874	
	QUANTUM RESOURCES MANAGEMENT, LLC 3. Address of Operator					ne or Wildcat	
	S OF OPERACO MCKINNEY ST. SUITE 2	400 HOUSTON	TX 77010			A - Q - RB - SA	
4. Well L		11000,011,			ARTESIA	1 - Q - KB - 3A	
		660 feet from	tha N	lina and	660 foot fi	rom the E. line	
	ection 23	_oooleet from Townsh			_660feet fi NMPM	rom theEline	
3	ection 25			Range 28E R, RKB, RT, GR, etc		EDDY County	
		11. Lievation (5//	ow whether Dr	, KKD, KI, OK, etc	7	The Control of State	
	12. Check A	ppropriate Box	to Indicate N	Nature of Notice	Report or Of	ther Data	
			to marouto r	, active of free to	, response on the	inor Satu	
	NOTICE OF IN					REPORT OF:	
	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					ALTED"	
	TEMPORARILY ABANDON					nm.us on our line	
	ALTER CASING LE COMMINGLE	MULTIPLE COM	PL []	CASING/CEMEN	w.emnru.s	e available when thins	
	_			Cu	irrent formsho	IIIU B-	
OTHER:				OTHER: W	ebsite and docu	Iments.	
13. De	scribe proposed or comple	eted operations. (C	Clearly state all	pertinent details v	egulatori	ung estimated date	
of	scribe proposed or complestarting any proposed wor	k). SEE RULE 19).15.7.14 NMA	C. For Multiple	,-	wellbore diagram of	
pro	oposed completion or reco	impletion.					
MI	RU RIG. NU BOP.						
	SPOT 40 SX CMT AT 2750'. WOC AND TAG.						
CIRC HOLE W/ MUD LADEN FLUID.							
	RFORATE AT 470' AND				IDE 7" CSG.		
	T OFF WELLHEAD AN	D INSTALL DKY	HULE MARK	EK.		150	
	CONDITIONS OF APPRO	OVAL ATTACHED	Approved	for plugging of well bor		RECEIVED	
			Liability	inder bond is retained n	ending rassing	1 20 2013	
C 1 D	Approval Granted pro	oviding work is	which ma	(Subsequent Report of V	Vell Plugging)	OCT 18 2013	
Spud Date:	Completed by	,	i Release	y be found at OCD Web ale: www.cmnrd.state.nm.us/oc	ed.	NMOCD ARTESIA	
	10/	75 ZO14	_			NMOCD	
	<u>'</u>						
	L			<u></u>			
I hereby cer	tify that the information a	bove is true and co	implete to the b	est of my knowled	ge and belief.		
SIGNATUR	RE Ben mif -	_	TITLE A	+		DATE 10-17-13	
		>	TITLE A	(en)	***************************************	DATE 70 77 B	
Type or prir	nt name Ben Mon	tormers	E-mail addres	is: bernehen a	nal Associates	. BHQNE: 432-580-761	
For State U	lse Only	3	,			- Went - War - Wall	
A DDD O VID	DRY. (71/)	ala	TITLE Dis	- A Sin	<i>116.0</i>	0.000 1. / /2	
APPROVE!	of Approval (if any):		IIILE ///3	· ci cyser	1150)	DATE 10/22/2013	
Conditions	or Approval (II ally).	000:		-		. ,	
* See	Attached (10145					

CURRENT

8 5/8" @ 418' w/ 50 sx.

Perfs 2800'-2823'

7" @ 2823' w/ 100 sx. TOC calc at 1554'.

TD 2896'

QUANTUM RESOURCES MST, LLC STATE 647 AC 711 # 125

PROPOSED

CUT OFF WELLHEAD & INSTALL DRY HOLE MARKER

PERF @ 470'. CIRC CMT TO SURFACE.

8 5/8" @ 418' w/ 50 sx.

SPOT 40 SX AT 2750'. WOC & TAG.

Perfs 2800'-2823'
7 " @ **2823**' w/ 100 sx. TOC calc at 1554'.

TD 2896'

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:C	duantum		
Well Name &	Number: 5tola 647	ACTIL	<u> </u> 125
API #:	30-015-02021		

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/22/2013

APPROVED BY: KROws

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).