Expires: July 31, 2010 ial No. J428657 Allottee or Tribe Name				
Allottec or Tribe Name				
7. If Unit or CA/Agreement, Name and/or No.				
8. Well Name and No. OXY 33 FEDERAL 1				
9. API Well No. 30-015-28970-00-S1				
10. Field and Pool, or Exploratory WINCHESTER				
11. County or Parish, and State				
EDDY COUNTY, NM				
OTHER DATA				
TYPE OF ACTION				
sume) 🔲 Water Shut-Off				
U Well Integrity				
D Other				
· · · · ·				
OIL CONSERVATION ARTESIA DISTRICT JUN 06 2014				
JUN 00 2014				
RECEIVED				
E)				
PROVED				

•			C		
	UNITED STATES EPARTMENT OF THE INTEI UREAU OF LAND MANAGEM	17 N 177	erator Copy	OMB N	APPROVED O. 1004-0135 July 31, 2010
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMNM0428657	
				6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRI	PLICATE - Other instruction	s on reverse side.	<u>1997</u>	7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well Sold Oil Well Gas Well Other				8. Well Name and No. OXY 33 FEDERA	
2. Name of Operator OXY USA WTP LP E-Mail: jennifer_duarte@oxy.com				 API Well No. 30-015-28970 	
^{3a.} Address PO BOX 4294 HOUSTON, TX 77210		Phone No. (include area code 713-513-6640)	10. Field and Pool, or BURTON FLAT	Exploratory STRAWN NORTH
4. Location of Well (Footage, Sec., 7	R., M., or Survey Description)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		11. County or Parish,	and State
Sec 33 T19S R28E SESE 510	OFSL 660FEL			EDDY COUNT	Y, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
B Notice of Intent	🗖 Acidize	🗋 Deepen		ion (Start/Resume)	U Water Shut-Off
Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclama		Well Integrity Other
Final Abandonment Notice	Change Plans	Plug and Abandon	lug and Abandon 🔲 Temporarily Abandon		
-	Convert to Injection	D Plug Back			• •
Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well with 2%KCL. Ni Recover Upper packer 3- Retrieve packer from 8852? 4- RIH and fish DR latching plu Permanent completion	D well head. NU BOP. ug from 10090? e extension, sliding sleeve, G h	ond No. on file with BLM/BI/ n a multiple completion or reco y after all requirements, incluc	A. Required sub ompletion in a r ling reclamatior	sequent reports shall be new interval, a Form 316	filed within 30 days 0-4 shall be filed once and the operator has
14. I hereby certify that the foregoing is	Electronic Submission #21015	WTP LP sent to the Carl	sbad	-	
Name(Printed/Typed) JENNIFEF	ADUARTE	Title REGUL	ATORY SPE		
Signature (Electronic S	ubmission)	Date 06/10/2	013	APPRU	
	THIS SPACE FOR FI			SE 111 7	-9012
A server of Dr.				4	FAMA
Approved By Conditions of approval, if any, are attached ertify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the subject			BUPECIAP LAND	MATYAGEMININAL
fitle.18 U.S.C. Section 1001 and Title 43 t States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime :	for any person knowingly and matter within its jurisdiction.	willfully to ma	ke to any department or	agency of the United

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **


. .

Additional data for EC transaction #210157 that would not fit on the form

32. Additional remarks, continued


7- Drop standing valve to set at F nipple at 10107?
8- Pressure up tubing to 2500 psi and set D packer at 8852?. Release pressure.
9- Pressure up casing to 500 psi to verify packer at 8852? is set.
10- RU Wireline unit. Recover standing valve at 10107?. RD Wireline unit.
11- RIH G locator with 6 seal units, sliding sleeve on 2-3/8? tubing.
12- Sting into D packer at 8852?. Space out 2?.
13- Pressure up casing to 500 psi to verify seals are inside seal bore extension.
14- Sting out. Space out. Land tubing hanger.
15- Pressure up casing to 500 psi to verify seals are inside seal bore extension.

Put on Production 16- ND BOP. NU X/Mas Tree. 17- Rig Down Well Service Rig. 18- Swab the well and produce Strawn in Natural Flow.



Created by Neevia Document Converter trial version http://www.neevia.com

· .



Created by Neevia Document Converter trial version http://www.neevia.com

.

OXY 33 Federal 1 30-015-28970 OXY USA WTP LP July 22, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by October 22, 2013.

Operator is approved for completion in the Strawn formation ONLY.

- 1. Before plugging and abandoning the Strawn formation, operator shall submit a sundry to plug the top of the Morrow formation.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 072213