Srm 3160-5 August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			OCD Artes	Exp	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. I. Type of Well Gas Well Other				5. Lease Serial No NMNM9216		
				6. If Indian, Allot		
				7. If Unit or CA/A NMNM1202	 If Unit or CA/Agreement, Name and/or No NMNM120212 Well Name and No. TRINITY 20 FEDERAL COM 1 	
				8. Well Name and TRINITY 20 F		
2. Name of Operator CIMAREX ENERGY COMPANY OF COMail: tstathem@cimarex.com				9. API Well No. 30-015-3452	21-00-S1	
3a. Address 3b. Phone No. (im 600 NORTH MARIENFELD STREET SUITE 600 Ph: 432-620-1 MIDLAND, TX 79701 Ph: 432-620-1			clude area code) 936	a code) 10: Field and Pool, or Exploratory COTTONWOOD DRAW		
	Sec., T., R., M., or Survey Description	n) .		11. County or Par		
Sec 20 T25S R26E NWS	SE 1980FSL 1580FEL			EDDY COU	NIY, INIVI	
12. CHECK	APPROPRIATE BOX(ES) TO	O INDICATE NA	ATURE OF N	IOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent	☐ Acidize	Deepen		Production (Start/Resume) Uater Shut-Of	
_	□ Alter Casing	Fracture	Treat	Reclamation	U Well Integrity	
Subsequent Report	🗖 Casing Repair	□ New Co	onstruction	Recomplete	C Other	
Final Abandonment Not		-	d Abandon	Temporarily Abandon		
	Convert to Injection ted Operation (clearly state all pertine			UWater Disposal		
complete as a Cisco Car Well History: 7/10/14 RIH w/ CIBP & s 7/11/14 Tried to press te 7/14/14 RIH w/ pkr & tbg bbls, pumped 50 bbls. T pkr down to 11506' held 7/15/14 RIH w/ CIBP & t mins. OK. Tag CIBP. D	uests approval to plug back the hyon and Wolfcamp producer a set At 11525'. Tag plug. Spot est, would not press up. SD. g. Test to 8000#. 15 mins - ok ag CIBP @ 11525', no cmt. S 200# for mins. SD. tag first CIBP @ 11525'. Set C Dump 35' cmt w/ dump bailer. 950# for 5 mins, pressure drop	according to the f t 3 sx cmt on top . SEt pkr @ 114 Get pkr @ 11450' CIBP 11506'. Pre SD. o to 1850# held fo	ollowing proce w/ dump bailer 71' - tbg capac held 2000# for ess test csg to	edure: AF r. SD. city = 44.3 r 5 mins. Move 2100# for 15 sted to 5000#	CONSERVATIO TESIA DISTRICT JUL 3 1 2014 C Page 2 DEFENDED JUL 2 3 2014 JUL 2 3 2014 JUL 2 3 2014	
14. I hereby certify that the foreg	Electronic Submission # For CIMAREX ENE	ERGY COMPANY	OF CO, sent to	Information System the Carlsbad	EAU OF LAND MANAGE CARLSBAD FIELD OFF	
Name(Printed/Typed) TER	Committed to AFMSS for pro	ri Ti		INATOR REGULATORY CO		
Signature (Elect	ronic Submission)	Da	nte 07/23/20)14		
THIS SPACE FOR FEDERAL OR STATE OFFICE					<u></u>	
<u> </u>	<u> </u>				· <u>·</u>	
	INANDEZ	<u>_ </u> <u> </u> <u>T</u>	itlePETROLEL	JM ENGINEER	Date 07/23/	
Approved_ByEDWARD_FEF						
pproved as written	s from Sundry dated 5/2	8/2014 and	fice Carlsbad			
pproved as written eneral COA requirement	s from Sundry dated 5/2 Il apply for Plugging bac			willfully to make to any departmer	tt or agency of the United	

Additional data for EC transaction #254328 that would not fit on the form

32. Additional remarks, continued

for 5 mins. SI and lost 80# in 5 mins. SD. 7/17/14 Press test csg to 8075# loss of 349# in 5 mins. SD 7/18/14 RIH and tag ČIBP @ 11509'. no cmt. SD waiting on orders.

Path forward:

1. set a 15K CBP @ +/- 10375'. Tag CBP to confirm depth. Dump bail 35' cmt (3 sx) on top of CBP.

 Allow cmt to set overnight, then RIH to tag TOC @ 10700'.
 Perform casing integrity test, pressuring up to 8000 psi (max treating pressure).
 Perforate Cisco Canyon (10124 - 10387'). Acidize & frac Cisco Canyon perfs w/ 5000 gals acid, 211000 gals slickwater, 100000 gals linear gel, 100000# 100 mesh sand and 200000# 40/70 sand in 2 stages, setting a CBP above 2nd stg perfs and in between 1st and 2nd stg perfs.
5. Perforate Wolfcamp (9114-9938'). Acidize & frac Wolfcamp perfs w/ 7500 gals acid, 732374 gals slickwater, 362500 gals linear gel, 375000# 100 mesh sand and 725000# 40/70 sand in 3 stages,

setting a CBP in between each stage.

setting a CBP in between each stage.
Drill out the 4 CBPs w/ coil tubing. Flow well back 24 hours to clean up sand production.
Run in gauge ring to clean out wellbore to PBTD @ +/- 10700'.
Run in with pkr & tubing string, setting pkr @ +/- 10090'.
Put well on production, producing the Wolfcamp zone up the casing and the Cisco Canyon zone up the tubing. Produce the well for 2-3 months, until stabilized production established.
Obtain a gauge rank to be a set and a set and a set and the context of the set and the context of the set of th

10. Obtain a gas analysis from each zone, and any other additional data required per BLM. Upon successfully producing each zone independently and gathering all necessary data, submit request to State and Fed DHC production. Upon approval request to DHC and procedure will be submitted for approval.

Please note: Correct Morrow are @ 11551-11577'. Production casing ran = 4-1/2", 11.6#, P-110 set @ 12280'. Previous reports indicate otherwise.

WILL Surface Commingle Request be Submitted? LRA/7/31/2014

