

Submit 1 Copy To Appropriate District State of New Mexic	o Form C-103	
Office Diffice		
District I – (575) 393-6161 Energy, Minerals and Natural 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DI	VISION 30-015-28053 5. Indicate Type of Lease	
District III - (505) 334-6178 1220 South St. Francis	Dr. STATE FEE	
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/50	5 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SI		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 119	
2. Name of Operator Yates Petroleum Corporation	9. OGRID Number 025575	
3. Address of Operator	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210	Dagger Draw; Upper Penn, North	
4. Well Location Unit Letter K 1980 feet from the South line and 1980 feet from the West line		
Section 28 Township 19S Range 25E NMPM Eddy County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3480'GR		
12. Check Appropriate Box to Indicate Natu	re of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
	EMEDIAL WORK Image: Altering Casing Image: Altering Image: Altering Casing Image: Altering Casing Image: Al	
— — — — — — — — — — — — — — — — — — — —	DMMENCE DRILLING OPNS. P AND A	
	·····	
	THER:	
OTHER: OTHER: III OTHER: IIII OTHER:		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Yates Petroleum Corporation plans to plug and abandon this well as follows:		
1. NU BOP. RU all safety equipment as needed. No casing recovery will be attempted.		
 Run a GR/JB to 7596'. Set a CIBP at 7586' and cap it with 25 sx Class "H" cement. This will place a plug over open Canyon perfs. Spot a 35 sx Class "C" cement plug from 5879'-6039'. This will leave a plug across the Wolfcamp top and stage tool. WOC and tag, reset if 		
necessary. 4. Spot a 35 sx Class "C" cement plug from 3730'-3890'. This will leave a plug across Bone Spring top.		
5. Spot a 35 sx Class "C" cement plug from 2150'-2310'. This will leave a plug across Glorieta top.		
 Spot a 35 sx Class "C" cement plug from 1040'-1200'. This will leave a plug across surface casing shoe. WOC and tag, reset if necessary. Spot a 35 sx Class "C" cement plug from 0'-150'. This will form the surface plug. WOC and tag, reset if necessary. 		
8. Remove all surface equipment and weld dry hole marker per regulations.		
Wellbore schematics attached Appro	ved for plugging of well bore only.	
-10113. The association of the first and -102101 recompletion submitted on $J/2004$	ty under bond is retained pending retained D3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under ARTESIA DISTRICT	
CONDITIONS OF APPROVAL ATTACHED	may be found at OCD Web Page under	
Rig Release Date:	, www.emnrd.state.nm.us/ocd. OCT 1 6 2014	
Approval Granted providing work is Recease Date.	PECEN/CD	
()ct28 2015	RECEIVED	
is true and complete to the best of	f my knowledge and belief.	
SIGNATURE (June furta TITLE Regulate	ory Reporting Supervisor _ DATE _ October 15, 2014	
Type or print name <u>Tina Huerta</u> E-mail address: <u>tinah@yatespetroleum.com</u> PHONE: <u>575-748-4168</u> For State Use Only O O O O O O O O O O O O O O O O O O O		
The must in mille		
APPROVED BY: DATE DATE Conditions of Approval (if any):		
, & Seo Attiched	(10)45	
	CKII-	





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: Vates Act
Well Name & Number: NDDUP Unt (Stete K#3)
API #: 30-015-28053

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/28/14

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).