

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1436357039*

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company <b>Devon Energy Production</b> <i>6137</i>	Contact <b>Wesley Ryan</b>
Address <b>6488 Seven Rivers Hwy Artesia, NM 88220</b>	Telephone No. <b>575.390.5436</b>
Facility Name <b>Black Jack 1 Fed 2</b>	Facility Type <b>Oil</b>
Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>
API No. <b>30-015-33383</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	1	24S	30E	1980	FSL	1980	FEL	Eddy

Latitude:

Longitude:

**NATURE OF RELEASE**

Type of Release <b>Spill - None</b> <b>Fire - Property Damage</b>	Volume of Release <b>0</b>	Volume Recovered <b>0</b>
Source of Release <b>None</b>	Date and Hour of Occurrence <b>12/21/14</b>	Date and Hour of Discovery <b>12/21/14 8:00 AM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jim Amos at 2:50 PM</b> <b>Randy Dade 3:00PM</b>	
By Whom? <b>Wesley Ryan</b>	Date and Hour <b>12/21/14 at 3:00PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Delaware Basin BU. Black Jack 1 Fed 2. - Lease Operator was checking tank levels on the Black Jack 1 Fed 2 when he noticed the flame on the heater treater was burning backwards out of the flame arrestor. The operator used his fire extinguisher to put out the fire and turned the supply gas off. After investigating it was discovered that the burner was plugged up and the flame came out of the burner end backwards smoking up the flame arrestor.

Describe Area Affected and Cleanup Action Taken.\*

Assistant Foreman, will verify that all burners will be on a preventive maintenance plan

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jeanette Barron</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>Field Admin Support</b>	Approval Date: <i>12/29/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <b>Jeanette.barron@dvn.com</b>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <b>12/29/14</b>	Phone: <b>575.748.1813</b>	

Attach Additional Sheets If Necessary

*22P-2696*