Form 3160-5 (August 1999)

its jurisdiction

7.

UNITED STATES

UNITED STATES

DEPARTMENT OF THE INTERIOR OF TWO AND MANAGEMENT OF LAND MA

Do not use this form for proposals to drill or to re-enter an	NM-0544986
abandoned well. Use Form 3160-3 (APD) for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	NA 7. Unit or CA Agreement Name and No.
1a. Type of Well Oil Well Gas Well Other RECEIVED	NA
1a. Type of Well Oil Well Gas Well Other	8 Well Name and No.
2. Name of Operator	TODD 25P FEDERAL 16
DEVON ENERGY PRODUCTION COMPANY, LP	9. API Well No.
3. Address and Telephone No.	30-015-28817
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615	10. Field and Pool, or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*	INGLE WELLS (DELAWARE)
660 FSL 660 FEL P 25 T23S R31E	12. County or Parish 13. State
	EDDY NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OS SUBMISSION TYPE OF ACTION	
I 14 Notice of Intent	n (Start/Resume)
☐ Alter Casing ☐ Fracture Treat ☐ Reclamat ☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recomple	= * * * · · · · · · · · · · · · · · · ·
Change Plans V Plug and Abandon Tempora	rily Abandon
Final Abandonment Notice Convert to Injection Plug Back Water Dis	·
deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)	
 Spot balanced cement plug from 7075' to 7175' (100' plug) to isolate Delaware perfs from 7202' to 8230'. Circulate wellbore with 9 ppg mud. Spot balanced cement plug from 5860' to 6260' (400' plug) to isolate parted casing at 6185'. Spot balanced cement plug from 4421' to 4521' (100' plug). 8-5/8" casing shoe at 4471'. Cut 5-1/2" casing at approx. 3580'. TOC at 3680' by CBL. POOH and lay down 5-1/2" casing. Spot balanced cement stub plug from 3505' to 3655' (150' plug) Spot balanced cement plug from 976' to 1076' (100' plug). 13-3/8" casing shoe at 1026'. Spot 60' surface cement plug. Cut wellhead off 3' below ground level. Install dry hole marker. Restore location. 	
SPECIAL STIP	UBJECT TO QUIREMENTS AND PULATIONS ATTACHED
Signed Signed State State State Signed State Sta	Date 10/12/2005
(This space for Federal or State Office use) Approved by ORIG. SGD.) ALEXIS C. SWOSODA Title Conditions of approval, if any:	P Date OCT 2 0 2005

Little Too i, makes it a crime for any person knowingly and williamy to make any department or agency or the critico states any haise, inclinous or maddelent statements or representations to any matter within



