Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5.	Lease Serial No.
	NMNM112931

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreen	ment, Name and/or N	0	
i. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. BIG SINKS 1 A2PA FED COM 1H			
Name of Operator     MEWBOURNE OIL COMPAN		JACKIE LAT ewbourne.com			9. API Well No. 30-015-42694			
3a. Address PO BOX 5270 HOBBS, NM 88241	. (include area code) 13-5905		10. Field and Pool, or E BONE SPRING	Exploratory				
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description	)			.11. County or Parish, a	nd State		
Sec 12 T26S R31E NENE 46	5FNL 330FEL				EDDY COUNTY	, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF N	NOTICE, RI	EPORT, OR OTHER	DATA	<del>-</del> .	
TYPE OF SUBMISSION			TYPE OF	ACTION	<u> </u>			
- N .: CI	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	Water Shut-O	ff	
☐ Notice of Intent	☐ Alter Casing	☐ Fra	ture Treat	Reclama	ation	☐ Well Integrity		
Subsequent Report	□ Casing Repair	☐ Nev	v Construction	☐ Recomp	lete	Other		
☐ Final Abandonment Notice	☐ Change Plans	. 🗖 Plu	g and Abandon	□ Tempor	arily Abandon	Well Spud		
	☐ Convert to Injection	□ Plu	g Back	☐ Water D	Disposal			
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 10/22/14 Spud 17 1/2" hole. F Class H w/additives. Mixed © 13.5 #/g w/1.75 yd. Tail w/200 AM 10/24/14. Did not circ cmt TOC @ 114'. PU 1" pipe & tat 14.8#/g w/1.34 yd. Circ 10 skt 1250# for 30 minutes, held Ol Chart & schematic attached.	ork will be performed or provided of operations. If the operation rebandonment Notices shall be file final inspection.)  Ran 1008' of 13 3/8" 48# F  14.6#/g w/1.49 yd. Follo  0 sks Class C w/1% CaCl2  1. Slow rate lift pressure @  g @ 100'. Cmt in 3 stages  s of cmt to the pit. At 11:19	the Bond No. o sults in a multip ed only after all H40 ST&C cs wed w/650 s 2. Mixed @ 1 300# @ 3 E s w/ 100 sks 5 A.M. 10/25.	n file with BLM/BIA le completion or reco requirements. includi g. Cemented with ks Class C w/add 4.8 #/g w/1.33 yd PM. Ran temp s Class C w/2% Ca	Required substitution in a raing reclamation of 180 sks That littives. Mixell. Plug down survey indicase [2]. Mixed	psequent reports shall be frew interval, a Form 3160 in, have been completed, a mixad d@ 1:45 atting @	iled within 30 days 0-4 shall be filed once nd the operator has		
Bond on file: NM1693 nationv	5/12/15 20 for 120000 13800		RE	CEIVED				
14. I hereby certify that the foregoing is  Name(Printed/Typed) JACKIE L	Electronic Submission # For MEWBOUI Committed to AFMSS f		PANY, sent to the by DEBORAH HA	e Carlsbad AM on 04/30/		OR RECOR	D	
Signature (Electronic	Submission)		Date 10/29/20	014	MAY -	1 2015		
	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE U	SE ()	Jan:	T	
Approved By			Title		<b>BUR</b> EAU OF LÂN CARLSBAD F	D MANAGEM <b>ENT</b> IELD OFFICE	]	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	Office							
						<del>````</del>		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



## WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Pg.	 of:	
-	 	

-74	*RDXL'	) 6	LOV	rington, NM	1 • 575-3	96-4540	' 9.	Y
Cc	mpany	newboune oil	. <u> </u>	Date: _/	10/29	4/14	Invoice # 1	60445
Le	ase: 3	105 nr. 5 2 ADAFEL CO				r: Ont 10 60 1		36
: Pl	ug Size	8туре: 12/22			Ko	Tester	<i>9</i>	Bur
		BOP: 1250	.,		lled BOP:	2000		
		Casing Valve Must Be Open During BOP Test.*				* Check V	alve Must Be Open/Disabled	To Test Kill Line Valve
:		· · · · · · · · · · · · · · · · · · ·	#26	;;				
:			)				The Day	Dart
•		Pacana Pacana	#2		· :·		Sand Pa	#19 🖼
;		<b>g b</b>		· ·		Kelly/		Valve #24
	-	Annular #15		#5	#6	Top Drive		
٠.							#22 #2	TIW S
 ::		Pipe Rams #12 Burns #13 Bu	#3	W W		1BOP 8 #17		Valve #18
	투	Billing Rams #15		#8B Mud Gaug	, a	Manual &		<b>3</b> 00
0				Valve		#16	Pump Valve Pum #20	np Valve #21
:: +	#11 #10		#25	]; 	74	1 known		
	=	Pipe Rams #14	#25 Super Ch	oke	501	on 60	ar f	
:		The state of the s		:		00-	DID Clock	
::		Casing						• •••
		Table to the control of the control	4.4					
	TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	1 12 12 12 12 12 12 12 12 12 12 12 12 12	REMARKS	
	TEST #	TEMS TESTED	TEST LENGTH	250	HIGH PSI	OH	REMARXS	
::	1 2		TEST LENGTH 30/30	250 250	122	Oh	REMARKS	
	1 2 3 3		30/20	250	1250	Oh Oh	REMARKS	
	1 2 3 4	7142,615 cosios	30/30	250 250	1250 1250	Oh Oh Oh	REMARKS	
	1 2 3 4 5	770(h 9,1,2,615 cosi os 3,4,5,10,15 cosins	30/30 30/30	250 250 250	1250 1250 1260	OA	REMARXS	
	1 2 3 4 5 6	770(h 9,1,2,615 cosi os 3,4,5,10,15 cosins	30/30 30/30	250 250 250 250	1250 1250 1250 1250	OA	REMARKS	
	2 3 9 5 6 7	270( N 9,1,2,615 cos, ns 3,4,5,10,15 cos, ns 26,26,5,11, cos, ns 8,11,18,15,(us, ns	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250	OA	REMARKS	
	1EST • 1 2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	270( N 9,1,2,615 cos, ns 3,4,5,10,15 cos, ns 26,26,5,11, cos, ns 8,11,18,15,(us, ns	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	OA OA OA	REMARXS	
	2 3 9 5 6 7	770( n. 9,1,2,615 cos, ng. 3,4,5,10,15 cos, ng. 25,26,5,11, cos, ng. 8,11,18,15, (asing. 7,11,19,15, (asing.) 16	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 4 5 6	270( N 9,1,2,615 cos, ns 3,4,5,10,15 cos, ns 26,26,5,11, cos, ns 8,11,18,15,(us, ns	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250 1250	OA OA OA		
	2 3 9 5 6 7	770( n. 9,1,2,615 cos, ng. 3,4,5,10,15 cos, ng. 25,26,5,11, cos, ng. 8,11,18,15, (asing. 7,11,19,15, (asing.) 16	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 4 5 6 7 6	770( n. 9,1,2,615 cos, ng. 3,4,5,10,15 cos, ng. 25,26,5,11, cos, ng. 8,11,18,15, (asing. 7,11,19,15, (asing.) 16	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 4 5 6 7 6	770( h 9,1,2,615 cos, os 3,4,5,10,15 cos, os 25,26,5,11, cos, os 8,11,18,15, cos, os 7,11,19,15, cos, os 16	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 4 5 6 7 6	770( N 9,1,2,615 cosing 3,4,5,10,15 cosing 25,26,5,11, cosing 8,11,18,15, casing 1,11,19,15, casing 16	30/30 30/30	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 9 4 7 6	270(h 9,1,2,615 cos, ns 3,4,5,10,15 cos, ns 25,26,5,11, cos, ns 8,11,18,15, cos, ns 1,11,19,15, cos, ns 16	30/30 30/30 30/30 Banp 3/30/ 10/10	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 9 5 6	270( h 9, 1, 2, 6.15 cos, ns 3,4,5,10,15 cos, ns 25,26,5,11, cos, ns 8,11,18,15, (as, ns 1,11,19,15, (as, ns 16	30/30 30/30 30/30 Banp 19/30 10/10	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		
	2 3 4 5 6	270( h 9, 1, 2, 6.15 cos, ns 3,4,5,10,15 cos, ns 25,26,5,11, cos, ns 8,11,18,15, (as, ns 1,11,19,15, (as, ns 16	30/30 30/30 30/30 Banp 39/30 10/10	250 250 250 250 250 250 250	1250 1250 1250 1250 1250 1250	Oh Oh Oh Oh		

## A WELDING SERVICES, IN

Company 20 4606 ne 011 Date 10/24/14
Lease Big Sinks 1 12 Pa Festion 14 County Lea
Drilling Contractor Pat or 36 Plug & Drill Pipe Size 17/2 4/4/0
Accumulator Pressure: 3000 Manifold Pressure: 1400 Annular Pressure: 1400
Accumulator Function Test - 00&GO#2  To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
<ul> <li>Make sure all rams and annular are open and if applicable HCR is closed.</li> <li>Ensure accumulator is pumped up to working pressure! (Shut off all pumps)</li> </ul>
1. Open HCR Valve. (If applicable) 2. Close annular. 3. Glose all pipe rams.
<ul> <li>4. Open one set of the pipe rams to simulate closing the blind ram.</li> <li>5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).</li> <li>6. Record remaining pressure psi. Test Fails if pressure is lower than required.</li> <li>a. [950 psi for a 1500 psi system] b. [1200 psi for a 2000 &amp; 3000 psi system]</li> </ul>
7. If annular is closed, open it at this time and close HCR.
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)  Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
a. (800 psi for a 1500 psi system) b. (1100 psi for 2000 and 3000 psi system)  1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)  2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to
3. Record pressure drop psi. Test fails if pressure drops below minimum.  • Minimum: a {700 psi for a 1500 psi system} b. {900 psi for a 2000 & 3000 psi system}

## To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  - 1. Open the HCR valve, {if applicable}
  - 2. Close annular
  - 3. With pumps only, time how long it takes to regain the required manifold pressure.
- Record elapsed time 27 cec. Test fails if it takes over 2 minutes.

  a. (950 psi for a 1500 psi system)
  b. (1200 psi for a 2000 & 3000 psi system)











