District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1300 R.o Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141¹ Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

ZFP-1772

Release Notification and Corrective Action											
						OPERATOR			☐ Init	ial Report 🛛 Final Repo	
Name of Company Chevron Delaware Basin						Contact Bradley Blevins					
Address PO Box 190, Hobbs, NM 88241						Telephone No. (575) 391-1462					
Facility Name Benson Shugart WFU #2 CTB						Facility Type Battery					
Surface Owner BLM Mineral Owner						API#					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/	West Line	County	
ı	26	188	30E	2310	}	South	330		East	Eddy County, NM	
Latitude N 32.71738° Longitude W 103.93519°											
NATURE OF RELEASE											
Type of Release Produced Water										Recovered 51 bbls	
Source of Release Tank overflow						Date and Hour of Occurrence 07/29/2013 @ 10:00 am				Date and Hour of Discovery	
Was Immediate Notice Given?						If YES, To Whom?					
Yes No Not Require											
By Whom? Bradley Blevins						Date and Hour 07/29/2013 @ 3:22 pm					
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*											
									ė.	RECEIVED	
The state of the s								e e e e e e e e e e e e e e e e e e e		OCT 25 2013.	
Describe Cause of Problem and Remedial Action Taken.* Failure to get a load from the tank caused an overflow and 59 bbls of produced water leaked onto the ground. 51 bbls of produced water were via vacuum truck.										MOCD ARTES: A duced water were recovered.	
Describe Area Affected and Cleanup Action Taken.* Failure to get a load from the tank caused an overflow and 59 bols of produced water leaked onto the ground. 51 bbls of produced water were recovered via vacuum truck. Remediation was completed in accordance with the remediation plan verbally approved by Mike Bratcher of NMOCD and approved by Mike Burton of the BLM via email on 09/20/2013.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: Snadly Re-							OIL CONS	ERVA I I	ATION I	DIVISION	
Printed Name: Bradley Blevins						pproved by D	istrict Supervisor	: H	vd.	M	
Title: HE Specialist						proval Date:	5/11/19	E:	xpiration Da	ate: NA	
E-mail Address: Bradley.blevins@chk.com						onditions of A	approval:	_		Attached	
Date: 10/23/2	013	ne: (575) 391-146	2		Y-	ilu	人				