Form 3160-5 (August 2007)

1. Type of Well

3a. Address

Name of Operator

☐ Oil Well ☐ Gas Well ☐ Other

MIDLAND, TX 79710-0250

Sec 22 T20S R28E SENW

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

OXY USA WTP LIMITED PTNRSHIP E-Mail: david_stewart@oxy.com

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Contact:

•	
	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010
OCD Artesia	5. Lease Serial No. NMNM82993
	6. If Indian, Allottee or Tribe Name
	7. If Unit or CA/Agreement, Name and/or No. NMNM84628
	8. Well Name and No. GOVERNMENT U 2
	9. API Well No. 30-015-26402-00-S1
de)	10. Field and Pool, or Exploratory N BURTON FLAT
	11. County or Parish, and State
•	EDDY COUNTY, NM

12	CHECK APPROPRIATE BOX	EST TO INDICATE NATURE	OF NOTICE REI	PORT OR OTHER DATA
12.	CHECK AFFROIRIALE BOX	ESTIC INDICATE NATURE	OF NOTICE, NE	i OKI, OK OTHER DATA

3b. Phone No. (include area code)

DAVID STEWART

Ph: 432-685-5717 Fx: 432-685-5742

TYPE OF SUBMISSION	` TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
Notice of Intent	☐ Alter Casing	☐ Fracture Treat	■ Reclamation	Well Integrity	
☐ Subsequent Report	Casing Repair	■ New Construction	☐ Recomplete	Other	
.□ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon		
	☐ Convert to Injection	Plug Back	■ Water Disposal		

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plugback Procedure

1. MIRU PU. ND X-Mas Tree. NU BOP.

2. POH 2-3/8" killing string.

3. RIH overshot and engage 2-3/8" tbg at 8428'.

4. Unset pkr. POH LD 2-3/8" tbg.

Plug and abandon Morrow-Atoka-Strawn

PROVIDE CIOZ Recepted for record MMOCD SEE ATTACHED FOR

CONDITIONS OF APPROVAL

NM OIL CONSERVATION ARTESIA DISTRICT

5. RIH 2-7/8" tbg open ended to 10952'
6. M&P 110sx CI H cmt @ 15.6 ppg from 10952-10080'. Flush the tbg twice the tbg capacity with 10ppg mud and pull up 640'. WOC for 4 hrs, then RIH and tag the cement plug. Note depth for OCD

AUG 18 2015

RECEIVED

14. I hereby certify that the foregoing is true and correct Electronic Submission #303641 verified by the BLM Well Information System For OXY USA WTP LIMITED PTNRSHIP, sent to the Carlsbad Committed to AFMSS for processing by EU FERNANDEZ on 08/11/2015 (15EF0040SE) Name (Printed/Typed) DAVID STEWART Title SR. REGULATORY ADVISOR

Signature (Electronic Submission) 06/02/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date 08 TitlePETROLEUM ENGINE 13/2015 Approved By CHARLES NIMMER AUG 1 3 2015 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully toguEAU OF LAND WANAGEMENT States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #303641 that would not fit on the form

32. Additional remarks, continued

records. POH.

Remedial cementing job for 5-1/2" csg

- 7. RIH and set CIBP at 9550'.
- 8. RU Wireline unit with full lubricator.
- 9. Perforate @ 9500' (total,4 holes) with 3-1/8" Titan guns with EXP-3323-301T charges (0.43" EH, 23.54" Pen) at 4 SPF and 60 degree phasing. RD wireline unit.

 10. RIH 5-1/2" pkr and set at 9450'

- 11. Pressure up tbg and see if get returns up 9-5/8" and 5-1/2" annulus. POH.

 12. RIH cement retainer on 2-7/8" tbg and set at 9450'. Test to 500 psi.

 13. Sting out and circulate. Sting into retainer and circulation through perforations and out the braden head (with the tbg/csg annulus closed, but monitoring pressure).
- 14. RU cementing company.
- 15. Establish circulation.
- 16. Pump Lead of 1050sx CI C Light cement (2.0 cu ft/sx, 12.8ppg).
- 17. Pump Tail of 950sx CI C with 2% CaCl cement (1.32 cu ft/sx, 14.8 ppg).
- 18. Flush the tbg.
- 19. Sting out 20. POOH with 2 stands.
- 21. Reverse circulate the tbg clean.
- 22. POOH with the tbg and stinger.
- 23. WOC, run temperature survey to find the top of cement behind 5-1/2" csg (Estimate at 2500')

Drill out and Test

- 24. RIH bit and clean to 9450' (PBTD).
- 25. Close the tbg/csg annulus, pressure test the csg to 250 psi for 10 min, if good test to 500 psi for 30 min.
- 26. If 500 psi test is definitely good, contact BLM field representative to schedule official MIT.
- 27. Run MIT test with chart recorder (test to 500 psi for 30 min).
- 28. POOH and lay down the work string. 29. ND BOP, NU WH, RD PU.

Perforating and frac Bone Spring


- 30. RU Wireline unit with full lubricator.
- Perforate Bone Spring formation in the interval 6470-8820
- 32. Frac Bone Spring formation with 1000 bbls of X-Link gel with 135000# 20/40 white sand.

Clean the well and run permanent completion

- 33. MIRU PU. ND X-Mas Tree. NU BOP.
- 34. RIH bit and clean out the well to PBTD at 9450'. POH.
- 35. RIH production string with seating nipple and tbg anchor. 36. Set tbg hanger. ND BOP. NU Rod BOP and well head.
- 37. RIH rod pump. Space out. Install polished rod. Test pump function.
- 38. RD Well Service Rig.
- 39. Put the well on production.

 OXY USA WTP LP - Current Government U #2 API No. 30-015-26402

LS pkr @ 10952' w/ blk plg



OXY USA WTP LP - Proposed Government U #2 API No. 30-015-26402

TD-11525

17-1/2" hole @ 620' 13-3/8" csg @ 620' w/ 1700sx-TOC-Surf-Circ

12-1/4" hole @ 3000' 9-5/8" csg @ 3000' w/ 1950sx-TOC-Surf-Circ

2-3/8" tbg w/ TAC

CIBP @ 9550' w/ CR @ 9450'

110sx @ 10952-10080' WOC-Tag

S pkr @ 10952' w/ blk plg

Perfs @ 6470-8820'

Perf @ 9500', sqz 2000sx cmt to +/- 2500' 7-7/8" hole @ 11525'

5-1/2" csg @ 11525' w/ 1200sx-TOC-10200'-TS

Perfs @ 10391-10798'

Perfs @ 11039-11280'

Government U 2 30-015-26402 Oxy USA WTP LP August 13, 2015 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by November 13, 2015.

- 1. Set solid cement 10952'-10080' WOC-Tag a minimum of 10080' as proposed.
- 2. Cement remediation as proposed. If TOC is lower than 2500' contact BLM prior to continuing.
- 3. Operator shall place a balanced class H cement plug from 8825' 9015' to seal the top of the Wolfcamp formation. WOC.
- 4. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- 5. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. Closed loop system required.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator to have H2S monitoring equipment on location.
- 10. A minimum of a 5000 (5M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M Diagrams of Choke Manifold Equipment). The accumulator system shall have an

immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.

- 11. Subsequent sundry required detailing work done and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 12. See attached for general requirements.

CLN 081315

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

