

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

OCT 07 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submits **RECEIVED** appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1528130514**

**OPERATOR**

☒ Initial Report    ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	Harrier Federal #001 Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-34434
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	35	16S	31E					Eddy County, NM

Latitude N 32.88301°    Longitude W 103.84284°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	30 bbls	Volume Recovered	0 bbls
Source of Release	Lightning struck a tank and blew out the bottom	Date and Hour of Occurrence	09/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Time			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck a tank, blowing out the bottom and causing 30 bbls of produced water to leak into the lined battery containment. No fluids were recovered and the tank was repaired/removed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 25' x 50' on location inside the lined battery. Remediation will be completed by removing the impacted soil from the lined battery and replacing it with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dusty Wilson	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 10/8/15	Expiration Date: N/A
E-mail Address: Dusty.Wilson@oxy.com	Conditions of Approval:	
Date: 10/7/15	Phone: (432) 685-5771	Attached <input type="checkbox"/>

**Remediation per O.C.D. Rules & Guidelines**  
**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: 11/8/15**

\* Attach Additional Sheets If Necessary

2RP-3318