

DEC 22 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1535754357** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>2100737</b>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #10 Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-23075
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	23S	30E	1980	North	660	East	Eddy

Latitude 32.335560° Longitude -103.827584°

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	81 bbls	Volume Recovered	40 bbls
Source of Release	Tank Overflow	Date and Hour of Occurrence	12/14/2015 time unknown	Date and Hour of Discovery	12/14/2015 11:15 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)		
By Whom?	Amy Ruth	Date and Hour	12/14/2015 4:52 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Coupling on water transfer pump failed and pump shut down. Produced water tank filled and overflowed into the battery earthen containment. The pump was repaired.					
Describe Area Affected and Cleanup Action Taken.* The leak affected 1550 ft <sup>2</sup> of well pad within the tank containment and standing fluids were recovered.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: Remediation Specialist	Approval Date: 12/23/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: <input checked="" type="checkbox"/> Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: 12/22/2015 Phone: 432-661-0571	<b>LATER THAN: 1/24/16</b>	

\* Attach Additional Sheets If Necessary

2RP-3464