

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

State of New Mexico  
Energy Minerals and Natural Resources

JAN 18 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
concordance with 19.15.29 NMAC.

**RECEIVED**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**Release Notification and Corrective Action**

**NAB1601536561**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 008H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:
API No. 3001539508	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	14	25S	30	300		1980		Eddy

Latitude: 32.13089 Longitude: 103.84192

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: 6 barrels
Source of Release: Pinhole in SWD Riser	Date and Hour of Occurrence 1-8-2016 @ 9:00am	Date and Hour of Discovery 1-8-2016 @ 9:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A pinhole developed on SWD riser tie in to main line due to internal corrosion. A vacuum truck was called to location and was able to recover 6 barrels of produced water from the ground surface.		
Describe Area Affected and Cleanup Action Taken.* The release occurred on the SWD riser at the tie in point of the main SWD line, the riser is located on the east side of Buck Jackson on the ROW. A vacuum truck was called to the location and was able to recover 6 barrels of produced water.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature: <i>Bradley Blevins</i>	Approved by Environmental Specialist <i>[Signature]</i>	
Printed Name: Bradley Blevins	Approval Date: <i>1/15/16</i>	Expiration Date: <i>N/A</i>
Title: Assistant Remediation Foreman	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: <i>1-12-2016</i> Phone: 432-214-3704	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

LATER THAN: *1/18/16*

*2RP-3495*

\* Attach Additional Sheets If Necessary