Form 3160-5 (March 2012)

(Instructions on page 2)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

**NMOCD** Artesia

FORM APPROVED OMB No. 1004-0137

	Exp	pires: Oct
ease Serial	No.	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

tober 31, 2014 5. Lease Serial NM 0426782 6. If Indian, Allottee or Tribe Name

abandoned well.	Use Form 3160-3 (A	PD) for such	proposals.				
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	· · · · · · · · · · · · · · · · · · ·						
Oil Well Gas Well Other			8. Well Name and No. Mary Federal #1				
2. Name of Operator BC Operating, Inc.					9. API Well No. 30-015-20785		
3a. Address	· <del>-</del> · · ·	3b. Phone No. (inc	lude area code)		10. Field and Pool or Ex	xploratory Area	
P.O. Box 50820 Midland, Texas 79710		432-684-9696			Sheep Draw; Strawn	(Gas)	
4. Location of Well (Footage, Sec., T.,	R.,M., or Survey Description	)			11. County or Parish, St		
1924' FNL & 651' FEL, Unit 'H', Section 11, T-23	3S, R-25E				Eddy County, New M	1exico	
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICA	TE NATURE OF	NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			ТҮРЕ О	F ACTI	ÓИ		
Notice of Intent	Acidize	· Deepen		Produ	luction (Start/Resume)		
Trouce of finein	Alter Casing	√ Fracture T	reat	Recla	mation	Well Integrity	
Subsequent Report	Casing Repair	New Cons	struction 🔽	Recor	nplete	Other	
	Change Plans	Plug and A	Abandon	] Temp	orarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back		Water	r Disposal		
testing has been completed. Final determined that the site is ready for Check cement behind casing and m	r final inspection.) take sure it is good. If it is	then plans are as	,	N	IM OIL CONSEI ARTESIA DIST FEB 0 8 2	RVATION RICT	
_		Andreas Contraction	380b			-	
Perf and frac Wolfcamp formation be	etween 8540' - 9700'.		LR\$		RECEIVE		
Put well on pump and begin product	lion.				Provide C	102 to NMOCD	
If cement is not sufficient, plans are recompletion work.	to shoot 2 squeeze holes,	set retainer and c	irculate cement i	up the a	annulus before pluggir	ng back well and starting	
• 9	whene		ved. (	) P	cy soften	~ will be issued	
14. I hereby certify that the foregoing is to	rue and correct. Name (Printe	d/Typed)					
Pam Stevens		Tid	le Regulatory A	nalyst	$\Delta$		
Signature Pam Stee	us)	Dat	te 06/25/2014	ACCI	PTED FOR R	RECORD /	
	THIS SPACE	FOR FEDERA	L OR STATE	OFF	ICE USE		
Approved by  Conditions of approval, if any, are attached that the applicant holds legal or equitable to	itle to those rights in the subjec	not warrant or certify	Title		THE PROPERTY OF AUTOMOTION OF	ate MUV	
entitle the applicant to conduct operations		arima far ann nas	Impuring!: and	16.11	CARLSBAD FIX D OF		
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre			knowingly and wil	iiiuii yo	make to any department	or agency of the United States any false,	

#### **GENERAL INSTRUCTIONS**

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

### - SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13 - Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment.

#### NOTICES

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and grantingapproval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

Mary Fed #1 7/25/2014

1924' FNL & 651' FEL Sec 11, T23S, R25E

**Eddy County, New Mexico** 

API: 42-371-33064

GL: 12' KB: 3736'

# Plug-back and Complete & Test Wolfcamp

## Well Data

Casing:

Tubing: 2-7/8" 8rd EUE 6.5 N-80 +/-10,044"

5-1/2" 20# N80 0-859'

5-1/2" 17# N-80 859'-7,598'

5-1/2" 20# N-80 7,598'-11,570'

TD: 11,570' PBTD: 10,309' Lok Set Packer @ 9,875'

## Pulling Unit Procedure

1. Comply with all company and governmental safety regulations.

- 2. RU pulling unit. TOOH with 2-7/8" production tubing and Lok Set packer.
- 3. TIH with 2-7/8" workstring with bit and scraper and cleanout to 9,785'.
- 4. TIH w CIBP and set at 9,780'.

## **Prep for Frac**

- 5. Set 2 frac tanks for flowback. Set 8 frac tanks and fill with fresh water.
- 6. RU acid pump truck w 250 gals. RIH with 3-1/2" 10# N80 tubing and compression packer (w hydraulic hold down). Run packer to 9,480'. Set 3-1/2" frac valve on top of tubing. (Note: have 2" crossover for acid pump truck).
- 7. Run flowback manifold and iron to flowback tanks.
- 8. Spot 250 of 15% HCL. Pick up packer to 9,200' and reverse excess acid in tubing. Set packer at 9,200'.
- 9. RU wireline and shoot perfs. See perf schedule.
- 10. Break down perfs with acid pump and put away. Shut in well.
- 11. RD and release wireline and acid pump truck. RD pulling unit if space is needed for frac equipment.

Note: Bring 3-1/2" frac valve and 2" regular crossover for acid pump truck.

### Completion

- 1. NU 3-1/2 frac valve.
- 2. MIRU frac crew. Verify water straps, fluid quality.
- 3. Complete frac in Wolfcamp formation (8,500' to 9,500') as designed (See attached frac design and plug/ perforations). **Monitor annular pressure on frac**. Maximum pressure = 7000 psi.
- 4. RDMO frac crew. Release frac tanks not needed for recovery.
- 5. Open well and flow back thru manifold to 2 oil and 4 water frac tanks.
- 6. Adjust choke to continuous flow. Keep office up to date with hourly flowback reports.
- 7. RU pulling unit once well is flowed down. TOH and lay down 3-1/2" frac string.
- 8. RIH with 2-7/8" production tubing. Put well on Pump.