

Submit 1 Copy To Appropriate District Office	, State of New Me			Form C-103	
<u>District I</u> – (575) 393-6161 E	Energy, Minerals and Natu	ONSERVATION-	WELL API NO.	tevised August 1, 2011	
District II (575) 748-1283	ARTE	SIA DISTRICI	30-015-23897		
811 S. First St., Artesia, NM 88210 District_III – (505) 334-6178	OIL CONSERVATION		5. Indicate Type of Lea	ase	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra Santa Fe, NM 87		STATE X	FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		ECEIVED	6. State Oil & Gas Lea	se No.	
SUNDRY NOTICES A	ND REPORTS ON WELLS		7. Lease Name or Unit	Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)) DRILL OR TO DEEPEN OR PLU FOR PERMIT" (FORM C-101) FC	UG BACK TO A DR SUCH	JURNEGAN STATE C	СОМ	
1. Type of Well: Oil Well Gas Well	X Other		8. Well Number 002		
2. Name of Operator CIMAREX ENERGY CO. OF COLORAI	00		9. OGRID Number 162683		
3. Address of Operator 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701			 Pool name or Wildcat MOSLEY CANYON; STRAWN 		
4. Well Location					
Unit Letter G : 2202	feet from the NORTH lin	e and 1670 fee	et from the EAST	line	
Section 12	Township 24S		24E NMPM	EDDY County	
11. E	Elevation (Show whether DR,		*		
	4,032' – GF	K			
12. Check Approp	priate Box to Indicate N	ature of Notice, F	Report or Other Data	l	
NOTICE OF INTENT	ΓΙΟΝ ΤΟ:	SUBS	EQUENT REPOR	RT OF:	
				ERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL				ID A	
PULL OR ALTER CASING MUL		CASING/CEMENT	JOB 🗋		
OTHER:		OTHER:		<u> </u>	
 Describe proposed or completed op of starting any proposed work). SI proposed completion or recompletion 	EE RULE 19.15.7.14 NMAC				
1) SET 4-1/2" CIBP @ 9,300'; PUMP 25 SXS. CMT. @ 9,300'-9,100'; CIRC. WELL W/ PXA MUD.					
2) PUMP 25 SXS. CMT. @ 8,340'-8,160' (T/WC.).					
 PERF. X ATTEMPT TO SQZ. 50 SXS. CMT. @ 5,155'-5,005' (T/B.S.); WOC X TAG CMT. PLUG. PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 4,341'-4,201' (CSG.PATCH). 					
5) CUT X PULL 4-1/2" CIBP @ +/-2,660'.					
6) PUMP 65 SXS. CMT. @ 2,784'-2,610' (T/DLWR., 4-1/2" CSG. STUB, 9-5/8" CSG.SHOE); WOC X TAG CMT. PLUG.					
 7) PUMP 45 SXS. CMT. @ 534'-434 8) MIX X CIRC. TO SURF. 25 SXS. 					
o)	0.111. (g 05 - 5 -				
DURING THIS PROCEDURE WE PLAN TO THE REQUIRED DISPOSAL, PER OC		OOP SYSTEM W/ A	STEEL TANK AND H	AUL CONTENTS	
					
Spud Date:	Rig Release Da	nte:			
		2/2/2			
well bore must be		2/26/201-			
I hereby certify that the information above i	s true and complete to the be	est óf my khowledge	and belief.		
	520				
signature David.	TITLE: AGE	ENT	DATE:	02/24/16	
Type or print name: DAVID A. EYLER	E-mail address: D	EYLER@MILAGR	O-RES.COM PHONE:	432.687.3033	
For State Use Only filled And The The new of State					
APPROVED BY: Conditions of Approval (if any):	TITLE ST	Hyperson	DATE 🗹	400 10016	
	se Attached	CeHs			

`





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: () MOre	\checkmark	
Well Name & Number:	Jurnecen State	COMZ
API #: 30-0/5-23897	0	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- **12. 19.15.7.16 :** B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE: 2/24/2014

APPROVED BY:

REVISED:11/2015

N.M.O.C.D.- Guidelines For Plugging

ļ

- All cement plugs will be a minimum of 100' in length, or a minimum of 25sx. Of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sx. Of gel per 100 bbls. Of water.
- A cement plug is required to be set 50' below, and 50' above all casing shoes, and casing stubs. These plugs must be tagged.
- A CIBP with 35' of cement on top, may be set instead of 100' plug.
- A plug as indicated above, must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set above and below all salt zones, **must be tagged.**
- No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.
- D.V. tools are required to have a 100' cement plug set 50' above, and 50' below the tool. This plug must be tagged.

Formations to be isolated with plugs placed at the top of each formation are:

- Fusselman
- Devonian
- Morrow
- Wolfcamp
- Bone Springs
- Delaware
- Any salt section (plug at top and bottom)
- Abo
- Glorietta
- Yates (this plug is usually at base of salt section)

If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths, or casing must be perforated and squeezed behind casing at the formation depths.

In the R-111P area (Potash mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.