

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brizos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised August 8, 2011  
Submittal Date: 7/13/2016  
Appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**Operator** ☒ Initial Report ☐ Final Report

**Name of Company:** Linn Energy **Contact:** EL Gonzales

**Address:** 2130 W Bender, Hobbs, NM 88240 **Telephone No.:** 575-738-1739

**Facility Name:** Turner B #082 **Facility Type:** Oil Producer

**Surface Owner:** Federal **Mineral Owner:** Federal **API No.:** 30-015-26385

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from	East/West Line	County
J	29	17S	31E	2550	South	1335	East	Eddy

Latitude: 32.80523284 Longitude: -103.8876114

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: Unknown	Volume Recovered: 0
Source of Release: Flow line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 05/03/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully:



Describe Cause of Problem and Remedial Action Taken:

On May 3, 2011, A BLM inspection of the site discovered a flowline leak in the road. A surface inspection form was submitted. On October 20, 2011, a second inspection of the site resulted in a secondary surface inspection form submitted.

Describe Area Affected and Cleanup Action Taken.

On June 23, 2016, DFSI personnel were on site to obtain samples within both of the leak areas. Within the release area, five samples were obtained and field sampled for chloride levels, as well as BTEX. The BTEX samples were performed using a Mini Rae Photoionization Detector (PID). All clean field samples under NMOCD and BLM regulatory guidelines were submitted for laboratory analysis at Cardinal Laboratories of Hobbs, NM to obtain confirmation, resulting in concentrations that decreased with depth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: EL Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor	Approval Date: 7/14/16	Expiration Date: N/A
E-mail Address: elgonzales@linnenergy.com	Conditions of Approval: work plan approved	Attached <input type="checkbox"/>
Date: 7/12/2016 Phone: 575-504-8002	on 7/13/16	

\* Attach Additional Sheets If Necessary

2RP-3779