Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103
1625 N. French Dr., Hobbs, NM 88240	y, Minerals and Natu	ral Resources	WELL API NO. 200	Revised July 18, 2013
611 5.1 H51 5t., 74tc3ta, 14vi 60210	CONSERVATION		5. Indicate Type of Lea	005-63249
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Frar Santa Fe, NM 87		STATE 6. State Oil & Gas Leas	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	54.14.1 6, 14.1 6 /		25900	se Ivo.
SUNDRY NOTICES AND R (DO NOT USE THIS FORM FOR PROPOSALS TO DRIL			7. Lease Name or Unit	Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR F			Willow Spring	"28" 5th k
1. Type of Well: Oil Well Gas Well	<b>▼</b> Other	·	8. Well Number 0	1
2. Name of Operator Line Energy				19441
3. Address of Operator 200 N Narienfeld Swite	100 Midland, Ti	79701	10. Pool name or Wild	Abo
4. Well Location Unit Letter : (c6)	eet from the South	\ line and	feet from the	East line
	Township 4 South Ra	nge 25E	NMPM Cou	nty Chares
11. Elevat	ion (Show whether DR, 35\7'	RKB, RT, GR, etc.	)	
12. Check Appropriate	e Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION	I TO:	SUE	SEQUENT REPOR	
PERFORM REMEDIAL WORK ☐ PLUG ANI TEMPORARILY ABANDON ☐ CHANGE	DABANDON 🔀 ☐	REMEDIAL WOR	RK □ ALTE IILLING OPNS.□ P AN	ERING CASING   ID A
PULL OR ALTER CASING  MULTIPLE	<del>-</del>	CASING/CEMEN		
DOWNHOLE COMMINGLE ☐ CLOSED-LOOP SYSTEM ☐	c			
OTHER:  13. Describe proposed or completed operati	ons. (Clearly state all r	OTHER:	nd give pertinent dates, inc	luding estimated date
of starting any proposed work). SEE RU proposed completion or recompletion.	ULE 19.15.7.14 NMAC	C. For Multiple Co		
1	cmt to 3,450. W	SCATAG	z 1	N
That 30:x cont fr. 29451-28451		·	(ut	off wellhead,
Spot 30x cont fr. 1993 - 1,593.	unck TAG		- instru	ll dry hole
shot soxx com to lady - 11-2011.		for plugging of well bo	re only.	& clear location.
Spot 30% cont fr. 1,409' - 1305.	Approved Liability	for plugging of well bo inder bond is retained to (Subsequent Report of ar he found at OCD We	Well Plugging)  None under	4 Clear Blatton,
Perf & Sqz. @ 958. War & TAG		onder send of Report of (Subsequent Report of ay be found at OCD Works, commend.state.nm.us.		
Purt & Sqz from 60- sutac	L. Correction V	WW.CISHU		NM OIL CONSERVATI
Spud Date: 2-26-2001	Rig Release Da	te: 3-	-12-2001	ARTESIA DISTRICT AUG 1 1 2016
WELL MUST BE PLUBBED A			(2 2001	RECEIVED
I hereby certify that the information above is true			ge and belief.	RECEIVED
That I		OPS ENGL	D.4.77	@//s///
SIGNATURE		1 1 .	1	8/10/16
Type or print name For State Use Only	E-mail address	: tusto reimi	· · ·	432-683-446
APPROVED BY: Jee At Long Conditions of Approval (if any):		LIAMES OF	FIEER DATE &	111/2016
A SEE AT	TACHED CO	1A-5		ι

# WèllView<sup>\*</sup>

## **Downhole Well Profile**

Well Name: Willow Spring '28' 1


	Surface Legal Location Sec. 28 4S 25E	Field Name Pecos Slope		State New Mexico	Well Configuration Type Vertical
Original KB Elevation (ft) 3,830.50	KB-Tubing Head Distance (ft)		Rig Release Date 3/12/2001 00:00	PBTD (All) (mKB)	Total Depth All (TVD) (ftKB)

	Туре	· -				<del> =</del>		
	Des	Make	Model	WP (psi)	Service	WP Top (psi) Bore Min (in)		
11								
IJ								

	Vertical - main hole, 7/27/2016 1:10:29 PM  Vertical schematic (actual)	1
••••	1.150,002	1
	an <u>a ana antang mangang mangan</u>	
		١
		1
	The state of the s	쎅
		1
		١
		1
		۱
		]
		1
		1
		١
	W& WW	1
		1
		1
		-
💥		
		1
		1
		-
		١
		١
······		-
		1
	<b>***</b>	
<b>W</b>		1
M		1
W		1
		1
W.	X.	-1
<b>33</b>	<u> </u>	
M		
~~~		1
		-
₩.	<b>***</b>	
	<b>**** </b> (*	
·	**************************************	~
<b>₩</b>	<b>***</b>	
		1
1		
	1000 1000 1000 1000 1000 1000 1000 100	
		-1

<del>is es es . po</del>toton.com

Casing Strings												
Csg Des		OD (in)		T	Wt/Len (lb/ft)	ft) Grade		Top Thread		Set Depth (ftKB		
Conductor		16		6	65.0	H-40					43.0	
Surface			11 3/	4	42.0	H-40		ST&C			958.0	
Intermediate			8 5/	8	24.0	J-55		ST&C		1943.0		
Production 5 1/2			2	15.5	15.5 J-55 LT8			C 4017		4017.0		
Perforations												
Date	То	p (ftKB	)		Btm (ftKB)	n (fiKB)			Linked Zone			
4/18/2001	3,	638.0		3,64	3,648.0							
Tubing Strings												
Tubing Description Production		n Date 24/2001				String Length (ft) 3,590.00		Set Depth (ftKB) 3,600.0				
Item Des		Jts	N	/ake	i	Mod	el	OD (in)	Wt (lb/ft)	Grade	Len (ft)	
Tubing		11 0			T&C	Ups	et	2 3/8	4.70	J-55	3,570 .00	
Blast Joint		1		-				3 1/16			19.00	
Seating Nipple		1			T&C	Ups	et	2 1/2	4.70	J-55	1.00	
Rod Strings												
Rod Description	Ru	Run Date		-	String	String Length (ft)			Set Depth (ftKB)			
Item Des		Jts	N	/lake	· · · · · · · · · · · · · · · · · · ·	Mod	ef	OD (in)	Wt (lb/ft)	Grade	Len (ft)	
		_										



Page 1/1

Report Printed: 7/27/2016

CONDITIONS FOR PLUGGING AND ABANDONMENT

#### District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.

4 ....

- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, Formations, all casing shoes, casing stubs, DV tools, attempted casing cut offs, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

- 17. Formations to be isolated with cement plugs are:
  - A) Fusselman
  - B) Devonian
  - C) Morrow

- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, and cement will be set 50' below formation bottom to 50' above formation top inside the casing

### DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging date
- 8. County

#### (SPECIAL CASES)

### AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)