NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 NUV **2 9 2017** Form C-141 Revised April 3, 2017

Supperperpendicular Supperpendicular Supperpendicular Supperpendicular Supperpendicular Suppersident Suppersi

Release Notification and Corrective Action Amended Report

## 

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	l	East/West Line	County	
K	35	18s	31e	1575	FSL	2200	FWL	Eddy	
L	L	1	ĺ		1		)		

Latitude\_32.701083\_\_Longitude\_-103.841542\_NAD83

NATURE OF RELEASE								
Type of Release: Water flood Injection "Recycled" water with trace of	Volume of Release:	Volume Recovered: Approximately 15						
oil and minor solids.	Approximately 20 bbls	bbls liquid contained in saturated soils-						
	Estimated using orifice calculator	calculated.						
Source of Release: Inlet Injection Line on Wellhead	Date and Hour of Occurrence: Date and Hour of Discovery:							
	Early Morning Hours of Nov 6,	Anonymous Call-in from Hunter- @						
	2017	Approximately 6:40 am- Agua Sucia on						
		site at 7:20 AM						
Was Immediate Notice Given?	If YES, To Whom?							
XX Yes* 🔲 No 🗋 Not Required	C Weaver-OCD and Louis Edgett-Agua Sucia- BLM on site same day.							
*By default OCD and Agua Sucia were notified.								
By Whom? Anonymous Call-in from Hunter- would not give name	Date and Hour: As noted above							
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. NA							
Yes XX No								
If a Watercourse was Impacted, Describe Fully.*								

No Shallow Groundwater in Area. Lease sets on dune sand mantle under laid by several hundred feet of impermeable Triassic Red Beds. No beneficial groundwater is found in this area.

Describe Cause of Problem and Remedial Action Taken.\* Nipple cracked on injection well inlet line. (See Attached Photo)- Agua Sucia personnel stopped the release early on the Morning of Nov 6, 2017. AS is in the process of redesigning the piping on the wellheads to prevent future occurrence.

2RP-4505