District I – (575) 393-6161 DEPEN ALL CONSERVATION and Natural Resources	Form C-103 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 APTESIA DISTRICT	WELL API NO. 30-015-05477
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 JAN 2 L GORNSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE S FEE
1220 S. St. Francis Dr., Santa Fe, NM RECEIVE- 87505	6. State Oil & Gas Lease No. B-3627
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Cedar Lake
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number <sub>3Y</sub>
2. Name of Operator	9. OGRID Number 371484
Rover Operating, LLC     3. Address of Operator	10. Pool name or Wildcat
17304 Preston Road, Suite 740, Dallas, TX 75252	Grbg Jackson SR Q G SA
4. Well Location	
Unit Letter D : 330 feet from the north line and	731feet from theline
Section 30 Township 17S Range 31E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc 3611' DF	
<u>3011 DF</u>	
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
— — — — — — — — — — — — — — — — — — — —	RILLING OPNS.
PULL OR ALTER CASING D MULTIPLE COMPL CASING/CEMEN	NT JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM 11	
OTHER: OTHER: Re	eturn to Production
— — — —	nd give pertinent dates, including estimated date
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completed operations.	nd give pertinent dates, including estimated date
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TOH w/rods	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TAC w/15k; Prepare to run rods.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TOH w/rods	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TAC w/15k; Prepare to run rods.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TAC w/15k; Prepare to run rods.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; TAC w/15k; Prepare to run rods.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#;
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; 'Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R   Spud Date: Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#; CD; Return well to production.
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; 'Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R   Spud Date: Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#; CD; Return well to production.
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#; RD; Return well to production.
OTHER: Image: Complete of the proposed of completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; The Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R   Spud Date: Rig Release Date:   Image: Complete to the best of my knowled	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#; RD; Return well to production.
OTHER: OTHER: Re   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.   8/25/2017: MIRU; TOH w/rods & pump.   8/28/2017 ND wellhead; NU BOP; TOH & scan tbg; LD bad jts; PU BHA; TIH; 'Set TAC w/15k; Prepare to run rods.   8/29/2017: TIH rods & pump; Space out & hang on; Check PA; Clean location; R   Spud Date: Rig Release Date:   I hereby certify that the information above is true and complete to the best of my knowled   SIGNATURE TITLE   Regulatory Administrat   Type or print name Connie Swan	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of Testing tbg to 6000#; RD; Return well to production.