

Form 3160-5 (June 2015)		UNITED STATES PARTMENT OF THE I JREAU OF LAND MANA	NTERIOR	ARTES	DNSERVA	FORM OMB N Expires: Ja 5. Lease Serial No. NMNM0219603	APPROVED O. 1004-0137 anuary 31, 2018
		NOTICES AND REPO		ELLS MAR	13 10	<sup>4</sup> 5. Lease Serial No. NMNM0219603	5
Do r aban	not use this doned wel	s form for proposals to I.  Use form 3160-3 (AP	D) for such	e-enter an	E-Fr/EL	( If Indian Allotter	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2         1. Type of Well         Image: Oil Well <td colspan="2" rowspan="2"><ol> <li>If Unit or CA/Agreement, Name and/or No</li> <li>Well Name and No. FEDERAL BZ 2</li> </ol></td>						<ol> <li>If Unit or CA/Agreement, Name and/or No</li> <li>Well Name and No. FEDERAL BZ 2</li> </ol>	
3a. Address         3b. Phone No. (include area code)           104 S 4TH STREET         Ph: 575-748-4168           ARTESIA, NM 88210         Fx: 575-748-4585						10. Field and Pool or Exploratory Area EAGLE CREEK	
4. Location of Well (For	otage, Sec., T.	, R., M., or Survey Description	1)			11. County or Parish,	State
Sec 21 T17S R25E NESE 1650FSL 330FEL						EDDY COUNTY, NM	
12. CHEC	K THE AP	PROPRIATE BOX(ES)	TO INDICA	ATE NATURE OI	F NOTICE,	REPORT, OR OTH	HER DATA
TYPE OF SUBMIS	SUBMISSION TYPE OF ACTION						
Notice of Intent		Acidize	🗖 De	epen	Product	tion (Start/Resume)	U Water Shut-Of
Notice of Intent		Alter Casing	🗖 Ну	draulic Fracturing	🗖 Reclam	ation	Well Integrity
Subsequent Report	t	Casing Repair	🗖 Ne	w Construction	Recom	olete	Other
Final Abandonment Notice	nt Notice	Change Plans	🛛 Plu	ig and Abandon	Tempor	arily Abandon	_
		Convert to Injection			□ Water I	-	
If the proposal is to deep	pen directiona	eration: Clearly state all pertine illy or recomplete horizontally,	ent details, inclu , give subsurface	ding estimated starting e locations and measure	g date of any p red and true ve	proposed work and appro ertical depths of all pertir	nent markers and zones
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site	epen directiona which the wor of the involved eted. Final Ab is ready for fi	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection.	ent details, inclu, give subsurface the Bond No. c ssults in a multip led only after al	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include	g date of any p red and true ve . Required su mpletion in a	proposed work and appro ertical depths of all pertin bsequent reports must be new interval. a Form 316	tent markers and zones filed within 30 days for 4 must be filed once
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e	ppen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a	Ily or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil	ent details, inclu , give subsurface the Bond No. c esults in a multip led only after al	ding estimated starting e locations and measur on file with BLM/BIA ple completion or reco l requirements, includi WS:	g date of any p red and true ve . Required su mpletion in a	proposed work and appropertical depths of all pertin becquent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC	tent markers and zones filed within 30 days for 4 must be filed once
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole with circulate a 125 sx c	rpen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. ith fresh wat class C cem	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this	ent details, inclu , give subsurface the Bond No. c soults in a multip led only after al s well as follo on equipmen arch and 5-1/2	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: nt. 2 inch casing to 50	g date of any p red and true vo . Required su mpletion in a ing reclamatio	proposed work and appropertical depths of all pertin becquent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 sx c 5. Back fill as needed	rpen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. ith fresh wat class C cem led.	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in	ent details, inclu , give subsurface the Bond No. c sults in a multipled only after al s well as follo on equipment on equipment to surface. V	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, includi ws: 	g date of any p red and true vo . Required su impletion in a ing reclamatio	roposed work and appro ertical depths of all pertir bsequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATT	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 sx c 5. Back fill as needed	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. ith fresh wat class C cem led. and install	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in ient plug from 1245 ft up dry hole marker. Clean u	nt details, inclu give subsurface the Bond No. c sults in a multipled only after al swell as follo on equipmen nch and 5-1/2 to surface. V up location as	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, includi ws: 	ate of any p red and true ve . Required su mpletion in a ing reclamatio	oroposed work and approprized work and approprized by the sof all perting because the ports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTACT	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 xc 5. Back fill as neede 6. Cut off wellhead	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. ith fresh wat class C cem led. and install	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in ient plug from 1245 ft up dry hole marker. Clean u	nt details, inclu give subsurface the Bond No. c sults in a multipled only after al swell as follo on equipmen nch and 5-1/2 to surface. V up location as	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, includi ws: 	ate of any p red and true ve . Required su mpletion in a ing reclamatio	roposed work and appro ertical depths of all pertir bsequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATT	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 xc 5. Back fill as neede 6. Cut off wellhead	pen directiona which the wor f the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. ith fresh wat class C cem led. and install cs attached	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in tent plug from 1245 ft up dry hole marker. Clean u control of the marker of the second true and correct. Electronic Submission #	ent details, inclu give subsurface the Bond No. c sults in a multip led only after al well as follo on equipment inch and 5-1/2 to surface. V up location as apiced for re-	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: 	g date of any p red and true ve . Required su mpletion in a ing reclamation 00 psi and 00 psi and (	roposed work and appro rentical depths of all pertin bequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATT/ SELL ATTACI COLLDITIONS	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole with circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic	pen directiona which the wor f the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. ith fresh wat class C cem led. and install cs attached	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in tent plug from 1245 ft up dry hole marker. Clean u Cocconnect. Electronic Submission # For EOG Y I amitted to AFMSS for proc	ent details, inclu give subsurface the Bond No. c sults in a multip led only after al well as follo on equipment inch and 5-1/2 to surface. V up location as apiced for re-	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: nt. 2 inch casing to 50 VOC. 5 per regulated. -/J -/ 8 cord - NMCCD ed by the BLM Well NC, sent to the C ISCILLA PEREZ or	g date of any p red and true ve . Required su mpletion in a ing reclamation 00 psi and 00 psi and (	noposed work and approprice depths of all perting because reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTACIL SELL ATTACIL ATTACIL CONSIDITIONS	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole with circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. ith fresh wat class C cem led. and install cs attached	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in tent plug from 1245 ft up dry hole marker. Clean u dry hole marker. Clean u Electronic Submission # For EOG Y I umitted to AFMSS for proc IRTA	ent details, inclu give subsurface the Bond No. c sults in a multip led only after al well as follo on equipment inch and 5-1/2 to surface. V up location as apiced for re-	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: nt. 2 inch casing to 50 VOC. 5 per regulated. -/J -/ 8 cord - NMCCD ed by the BLM Well NC, sent to the C ISCILLA PEREZ or	g date of any p red and true ve . Required su mpletion in a ing reclamation 00 psi and 00 psi and ( 1 Information carlsbad 1 01/31/2018 ATORY SP	noposed work and approprice of all perting because the ports of all perting because the ports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTACIANT SELL ATTACIANT SELL ATTACIANT SUSTEM (18PP0946SE)	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. and install cs attached re foregoing is Com TINA HUE	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in tent plug from 1245 ft up dry hole marker. Clean u dry hole marker. Clean u Electronic Submission # For EOG Y I umitted to AFMSS for proc IRTA	ent details, inclu give subsurface the Bond No. c sults in a multipled only after all swell as follo on equipment the and 5-1/2 to surface. V up location as concerned for re-	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: nt. 2 inch casing to 50 WOC. 3 per regulated. -/J -/ 8 cord - NMCCD d by the BLM Well NC, sent to the C ISCILLA PEREZ or Title REGUL Date 01/30/20	20 psi and 1 Information 1 arisbad 0 1/31/2018 0 1/31/2018 0 1/31/2018	roposed work and approprices diversional depths of all pertinal depths of all pertinal bequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTACIC AT	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has NN PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. 245 ft. and install cs attached re foregoing is Com TINA HUE	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in ter, pressure test 4-1/2 in test	ent details, inclu give subsurface the Bond No. c sults in a multipled only after all swell as follo on equipment the and 5-1/2 to surface. V up location as concerned for re-	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: 	20 psi and 1 Information 1 arisbad 0 1/31/2018 0 1/31/2018 0 1/31/2018	roposed work and appro rentical depths of all pertin bequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTA SELL ATTACI CONDITIONS of System (18PP0946SE) ECIALIST	nent markers and zones filed within 30 days 50-4 must be filed once and the operator has N PROCEDURE 4CHED
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wit circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic 14. I hereby certify that the Name ( <i>Printed/Typed</i> ) Signature Approved By	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. and install f cs attached efforegoing is Com TINA HUE (Electronic S	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in ter, pressure test 4-1/2 in test 4-1/2	ent details, inclu give subsurface the Bond No. o sults in a multipled only after all swell as follo on equipment to surface. V up location as control for re- 402650 verific RESOURCES cessing by PR	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, include ws: nt. 2 inch casing to 50 VOC. 5 per regulated. -/J -/ 8 cord - NMCCD ed by the BLM Well NC, sent to the C ISCILLA PEREZ or Title REGUL Date 01/30/20 AL OR STATE C	g date of any p red and true ve. Required su mpletion in a ing reclamation 00 psi and 00 psi and ( Unformation arisbad 01/31/2018 ATORY SP 018 0FFICE U	roposed work and appro rentical depths of all pertin bequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTA SELL ATTACI CONDITIONS of System (18PP0946SE) ECIALIST	ent markers and zones filed within 30 days 50-4 must be filed once and the operator has N PROCEDURE 4CHED 2D FOR 0F APPROV
If the proposal is to deep Attach the Bond under v following completion of testing has been comple determined that the site EOG Y Resources, 1. MIRU all safety e 2. RIH with GR/JB t 3. Set a CIBP at 12 4. Load the hole wil circulate a 125 sx c 5. Back fill as neede 6. Cut off wellhead Wellbore schematic 14. I hereby certify that the Name ( <i>Printed/Typed</i> ) Signature Approved By Conditions of approval, if an certify that the applicant hold which would entite the appli Title 18 U.S.C. Section 1001	pen directiona which the wor of the involved eted. Final Ab is ready for fi , Inc. plans equipment a to 1255 ft. 245 ft. ith fresh wat class C cem led. and install cs attached te foregoing is Com TINA HUE (Electronic S	Illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. to plug and abandon this as needed. Pull production ter, pressure test 4-1/2 in ter, pressure test 4-1/2 in test 4-1/2	ent details, inclu give subsurface the Bond No. o sults in a multipled only after all swell as follo on equipment to surface. V up location as control and 5-1/2 to surface. V up location as control	ding estimated starting e locations and measu on file with BLM/BIA ple completion or reco l requirements, includi ws: 	g date of any p red and true ve . Required su impletion in a ing reclamation 00 psi and 00 psi and 11nformation arisbad 01/31/2018 ATORY SP 018 0FFICE U	roposed work and appro rentical depths of all pertin bequent reports must be new interval, a Form 316 n, have been completed a RECLAMATIC ATTA SELL ATTACI ATTA SELL ATTACI CONDITIONS of System (18PP0946SE) ECIALIST SE	ent markers and zones. filed within 30 days 50-4 must be filed once and the operator has N PROCEDURE ACHED CD FOR OF APPROV 3-G-1 Date





## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

٠

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.** 

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



## **United States Department of the Interior**

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## **Reclamation Objectives and Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612