Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill of the proposals to the

abandoned well. Use form 3160-3 (APD) for such proposition				6. If Indian, Allottee of Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. CYPRESS 34 FEDERAL 3H		
Name of Operator OXY USA INCORPORATED	D STEWART	9	9. API Well No. 30-015-35692-00-S1			
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521	Phone No. (include area code) 432.685.5717	1	10. Field and Pool or Exploratory Area CEDAR CANYON			
4. Location of Well (Footage, Sec., T		1	11. County or Parish, State			
Sec 34 T23S R29E NESW 21			EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE, R	EPORT, OR OTH	IER DA	ATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen	☐ Production	oduction (Start/Resume)		ater Shut-Off
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamati	eclamation		ell Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	Recomple	te	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporar	rarily Abandon		
	Convert to Injection	□ Plug Back	■ Water Dis	er Disposal		
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclar determined that the site is ready for final inspection. Well Prep Procedure: 1. MIRU PU and rig equipment 2. Ensure well is dead 3. MU tubing equipment and POOH w/2-7/8" tubing and rod pump 4. RIH with cleanout BHA 5. RU power swivel if needed and cleanout to PBTD 6. POOH with cleanout BHA and work string 7. RIH with work string to top of KOP and set RBP. Test casing to 6200# or max treating pre whichever is lower. 8. Bleed off pressure & RBIH to latch on RBP, release RBP & POOH. LD w/ RBP 9. Perform drift run with Mohawk BHA 10. RIH w/ 4.25" 13.1# P110 R2M expandable liner & set @ approximately				NM OIL CONSERVATION ARTESIA DISTRICT JUN 2 9 2018		
14. I hereby certify that the foregoing is true and correct.						
Electronic Submission #424670 verified by the BLM Well Information System For OXY USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 06/25/2018 (18PP2040SE)						
Name (Printed/Typed) DAVID S	Titlè REGUL	ATORY ADV	ISOR			
Signature (Electronic	Date 06/19/2	018				
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE US	E		
_Approved By _JONATHON SHEP	TitlePETROLE	UM ENGINE	1 ENGINEER		Date 06/26/2018	
Conditions of approval, if any, are attached certify that the applicant holds legal or equinch would entitle the applicant to conditions.	Office Carlsba		- 		= :	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a crime statements or representations as to any	for any person knowingly and watter within its jurisdiction.	l willfully to mak	e to any department or	r agency (of the United

Additional data for EC transaction #424670 that would not fit on the form

32. Additional remarks, continued

7900-10950'

11. Expand the liner using Mohawk procedures

Plug & Perf stimulation operation:

Conduct pre-job safety meeting, discuss scope of work and hazard
 Check WH pressure & bleed off pressure if any to grounded flowback tank
 MIRU Cameron WH Company and equipment.

 Install 10M frac stack on wellhead
 MIRU frac and WL equipment
 RIH with WL and plug and perf for stage 1 with 4 clusters (7925-10927') per attached perf design.

7. Spot 7.5% HCl acid and breakdown stage 1

8. Frac stage 1 per the pump schedule below

9. RIH with WL and plug & perf for stage 2 and frac afterwards
10. Repeat process for the remaining stages (estimated 16 total stages)

11. RDMO frac and WL company

Wellbore Clean out and Flowback Procedure:

1. Hold Pre-job safety meeting, discuss scope of work and hazards

 Check WH pressure, bleed off pressure if any to grounded flowback tank
 MIRU 2-3/8" CT unit, PU 4.13" JZ bit, (Mohawk liner is 4.158" ID drift) RIH and DO plugs and CO to PBTD

4. Circulate hole clean and pump gel sweeps5. RDMO CT unit and turn the well over to production

6. Open to Flowback

7. An artificial lift procedure will be provided once flowback operations completed.

Revisions to Operator-Submitted EC Data for Sundry Notice #424670

Operator Submitted

Sundry Type: **RCMPL**

NOI

Lease:

NMNM86024

RCMPL NOI

NMNM86024

Agreement:

Operator:

OXY USA INC. P.O. BOX 50250 MIDLAND, TX 79710 Ph: 432-685-5717

BLM Revised (AFMSS)

OXY USA INCORPORATED 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521 Ph: 713.350.4816

Admin Contact:

DAVID STEWART SR. REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Cell: 432-634-5688 Ph: 432-685-5717

DAVID STEWART REGULATORY ADVISOR E-Mail: david_stewart@oxy.com

Ph: 432.685.5717

Tech Contact:

DAVID STEWART SR. REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Cell: 432-634-5688

Ph: 432-685-5717

DAVID STEWART REGULATORY ADVISOR E-Mail: david_stewart@oxy.com

Ph: 432.685.5717

Location:

State: County: EDDY

Field/Pool:

NM EDDY

CEDAR CANYON BONE SPRING

CEDAR CANYON

Well/Facility:

CYPRESS 34 FEDERAL 3H Sec 34 T23S R29E NESW 2100FSL 1650FWL 32.259815 N Lat, 103.975716 W Lon

CYPRESS 34 FEDERAL 3H Sec 34 T23S R29E NESW 2100FSL 1650FWL

, j .