Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED

OMB NO. 1004-0137 Expires: January 31, 2018 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. NMNM78214 SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to kerealist

abandoned wel	I. Use form 3160-3 (APD) for	sheriph hand	6. If Indian, Allottee	or Tribe Name
SUBMIT IN 1	RIPLICATE - Other instruction	ons on page CD	AFTES TO If Unit or CA/Agr	reement, Name and/or No.
1. Type of Well			8. Well Name and N	
☑ Oil Well ☐ Gas Well ☐ Other			ANEMONE ANE	
2. Name of Operator Contact: TINA HUERTA YATES PETROLEUM CORPORATIONE-Mail: tina_huerta@eogresources.com			9. API Well No. 30-015-28041	-00-S1
105 SOUTH FOURTH STREET Ph: 575-74 ARTESIA, NM 88210 Fx: 575-748		Phone No. (include area code) 575-748-4168 575-748-4585	10. Field and Pool o INDIAN BASIN	N-STRAWN K. Hills West
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)		11. County or Parish	111231000
Sec 9 T22S R24E NESW 1980FSL 1980FWL			EDDY COUNT	14. NM 16364
12. CHECK THE AP	PROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE, REPORT, OR OT	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
⊠ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off
	☐ Alter Casing	☐ Hydraulic Fracturing	Reclamation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	Recomplete	Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	Temporarily Abandon	
	Convert to Injection	☑ Plug Back	☐ Water Disposal	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. EOG Y Resources, Inc. plans to plug back and recomplete this well to the Morrow as follows: 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment. Load the hole as necessary with treated water. 2. Run a GR/JB to 7800 ft. 3. Set a cement retainer at +/- 7750 ft. 4. Squeeze Canyon perforations 7855 ft - 8006 ft with 250 sx Class C cement with 2 percent CaCl2 followed by 250 sx Class H Neat cement. Hesitate squeeze the last 250 sx with 30 minute shut downs as follows: pump 100 sx - shut down, pump 50 sx - shut down. If it pressures out, sting out and displace tubing. If no positive pressure, pump a tubing volume of displacement and prepare to re-squeeze. 5. MIRU reverse unit to drill out cement. Pressure test to 500 psi. If necessary re-squeeze DISTRICT II-ARTESIA O.C.D.				
	Electronic Submission #42317 For YATES PETROLEUI Imitted to AFMSS for processing	M CORPORATION, sent to g by PRISCILLA PEREZ or	o the Carlsbad n 06/08/2018 (18PP1915SE)	
Name(Printed/Typed) TINA HUERTA		Title REGUL	ATORY SPECIALIST	
Signature (Electronic S	Submission)	Date 06/07/20	018	
	THIS SPACE FOR F	EDERAL OR STATE (OFFICE USE	
/s/ Joi	Title	Fraginast	JUN _{ate} 1 1 2018	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduction	itable title to those rights in the subje	um Engineer d Field Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

6/30/18- hold to see y worker de open morrow pool done - wee mane to re-open morrow pool

Additional data for EC transaction #423172 that would not fit on the form

32. Additional remarks, continued

Canyon. Clean out down to RBP at 9950 ft. Circulate the hole clean. Pressure test to 500 psi. 6. Perforate Morrow 9880 ft - 9890 ft 66 total shots.

7. Set a packer at +/-9830 ft with a rupture disc in place. TIH with tubing, SN and O/O tool to latch onto the packer. Load the annulus with packer fluid containing an oxygen scavenger and a

corrosion inhibitor.

8. Swab the tubing down, drop bar to break the disc. MIRU to break down the Morrow sand perforations with 1500g 7-1/2 percent IC HCL acid with a gas surfactant and iron control additives for 10,000 ppm. The acid should be inhibited for 150 degrees at 8 hrs. Pump the acid at 2-3 BPM and flush to the bottom perf with treated water.

9. Swab/flow the well back immediately and allow the well to clean up.

10. Turn well over to production.

Wellbore schematics attached.



