Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTIM OF ARTESTATES RY NOTICES AND REPORTS ON WELL A 20 7018

FORM APPROVED OMB NO. 1004-0137

5. Lease Serial No. NMLC029338A

	Expi	res	Ja	anı	ary	31,	20
ease S	erial l	٧o.					

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an	g,
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals.	

<ol><li>If Indian, Allottee or Tribe</li></ol>	: Name	
--	--------	--

abandoned wel		-64	70-	
SUBMIT IN T	RIPLICATE - Other instr	o) for such proposals.  Fuctions on page 2	7. If Unit	or CA/Agreement, Name and/or No.
1. Type of Well			8. Well N	ame and No. CKSON SA 10
② Oil Well ☐ Gas Well ☐ Oth  2. Name of Operator	Contact:	ESLIE GARVIS	9. API W	ell No.
BURNETT OIL COMPANY IN	C E-Mail: LGARVIS@	BURNETTOIL.COM		5-04152-00-S1
3a. Address 801 CHERRY STREET UNIT FORT WORTH, TX 76102-68		3b. Phone No. (include area code Ph: 817-583-8730 Fx: 817-332-8438		and Pool or Exploratory Area /BURG
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)		11. Coun	ty or Parish, State
Sec 14 T17S R30E SWSE 33	0FSL 2310FEL		EDD	COUNTY, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE C	F NOTICE, REPORT	C, OR OTHER DATA
TYPE OF SUBMISSION		TYPE O	F ACTION	
■ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/	Resume)
■ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	Temporarily Abar	don
	☐ Convert to Injection	□ Plug Back	■ Water Disposal	
If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final Al determined that the site is ready for f Burnett proposes to Plug and	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation res- bandonment Notices must be file inal inspection.  Abandon this well using the	give subsurface locations and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu the following procedure:	ured and true vertical deptit A. Required subsequent rej ompletion in a new interva ding reclamation, have bee	off Varity and
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for f Burnett proposes to Plug and  1. MIRU, NDWH NUBOP  2. Set CIBP @ 2712'.  3. Spot 25 sxs cmt @ 2712'-2  4. Spot-35 sxs cmt @ 2,245'-5. Spot-35 sxs cmt @ 1,617'-	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation respondent Notices must be file inal inspection.  Abandon this well using the Acceptage of the Inal inspection.  Abandon this well using the Inal inspection.  547'. WOC. Tag  2.145'. Perf/Sqz/Tag  1,617'. Perf/Sqz/Tag  1,075'. Perf/Sqz/Tag  1,00'. Perf/Sqz/Tag  1,00'. Perf/Sqz/Tag	give subsurface locations and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu- the following procedure:  120 7-18  120 120 1364 - 1264	ured and true vertical depth A. Required subsequent rej ompletion in a new interva ding reclamation, have been  At Cut  To Sur to  SEE AT	s of all pertinent markers and zones. Foorts must be filed within 30 days la Form 3160-4 must be filed once in completed and the operator has
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for full Burnett proposes to Plug and  1. MIRU, NDWH NUBOP 2. Set CIBP @ 2712'. 3. Spot 25 sxs cmt @ 2712'-2 4. Spot 35 sxs cmt @ 2712'-2 5. Spot 35 sxs cmt @ 2,245'-5. Spot 35 sxs cmt @ 1,617'-6. Spot 45 sxs cmt @ 1,294'-7. Spot 50 sxs cmt @ 603'-40'-8. Spot 60 sxs cmt @ 225'-09. POOH. Top off well. Cut off Clean location.	ally or recomplete horizontally, rk will be performed or provide to operations. If the operation respondence in the operation respon	give subsurface locations, and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu the following procedure:	and true vertical deptit  A. Required subsequent rej  completion in a new interval  ding reclamation, have been  At Cut  SEE AT  CONDI  all Information System  the Carlsbad	so tall pertinent markers and zones. Soorts must be filed within 30 days to a Form 3160-4 must be filed once in completed and the operator has soorts must be filed once in completed and the operator has soorts must be filed once in completed and the operator has soorts must be filed once in completed and the operator has soorts for the filed once in complete and the operator has soorts must be filed within 30 days to a Form the filed once in complete and the operator has soorts must be filed within 30 days to a filed within 30 days to a filed within 30 days to a filed once in complete and the operator has soorts must be filed within 30 days to a filed once in complete and the operator has soorts must be filed within 30 days to a filed once in complete and the operator has soorts must be filed within 30 days to a filed once in complete and the operator has soorts must be filed once in complete and the operator has soorts must be filed once in complete and the operator has soorts for the operator has soorts for the operator has soonts for the operator
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for full Burnett proposes to Plug and  1. MIRU, NDWH NUBOP 2. Set CIBP @ 2712'. 3. Spot 25 sxs cmt @ 2712'-2 4. Spot 35 sxs cmt @ 2,245' - 5. Spot 35 sxs cmt @ 2,245' - 5. Spot 35 sxs cmt @ 1,617'. 6. Spot 45 sxs cmt @ 1,617'. 7. Spot 50 sxs cmt @ 603' -40. 8. Spot 60 sxs cmt @ 225' - 0. 9. POOH. Top off well. Cut off Clean location.  14. I hereby certify that the foregoing is Comm.	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation respondence in the operation respond	give subsurface locations and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu the following procedure:    C	ared and true vertical deptite.  A. Required subsequent rejompletion in a new interval ding reclamation, have been supported by the support of the support o	so tall pertinent markers and zones. Soorts must be filled within 30 days to a Form 3160-4 must be filled once in completed and the operator has soort with the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the complete of the com
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for full Burnett proposes to Plug and  1. MIRU, NDWH NUBOP 2. Set CIBP @ 2712'. 3. Spot 25 sxs cmt @ 2712'-2 4. Spot 35 sxs cmt @ 2,245'-5. Spot 35 sxs cmt @ 1,617'-6. Spot 45 sxs cmt @ 1,617'-7. Spot 50 sxs cmt @ 603'-40. 8. Spot 60 sxs cmt @ 225'-0. POOH. Top off well. Cut off Clean location.  14. I hereby certify that the foregoing is Common Name (Printed/Typed) LESLIE G.	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation respondence in the operation respond	give subsurface locations, and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu the following procedure:    C	ared and true vertical deptite.  A. Required subsequent rejompletion in a new interval ding reclamation, have been supported by the support of the support o	so tall pertinent markers and zones. Soorts must be filled within 30 days at 50rm 3160-4 must be filled once in completed and the operator has a complete and the operator has a complet
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for full Burnett proposes to Plug and  1. MIRU, NDWH NUBOP 2. Set CIBP @ 2712'. 3. Spot 25 sxs cmt @ 2712'-2 4. Spot 35 sxs cmt @ 2,245'-5. Spot 35 sxs cmt @ 1,617'-6. Spot 45 sxs cmt @ 1,617'-7. Spot 50 sxs cmt @ 603'-40. 8. Spot 60 sxs cmt @ 225'-0. POOH. Top off well. Cut off Clean location.  14. I hereby certify that the foregoing is Common Name (Printed/Typed) LESLIE G.	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation respondence in the operation respond	give subsurface locations and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec ed only after all requirements, inclu the following procedure:    C	ared and true vertical deptite.  A. Required subsequent rejompletion in a new interval ding reclamation, have been supported by the support of the support o	so tall pertinent markers and zones. Soorts must be filled within 30 days to a Form 3160-4 must be filled once in completed and the operator has soort with the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the completed and the operator has a source of the complete of the com

TD 3,480'

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted