Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Res	ources Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	EIVED	WELL API NO. 35-015-31082
011 C First Ct Astaria NNA 00010	OIL CONSERVATION DIVIS	
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 MAY District IV – (505) 476-3460	ຄ 3 2016220 South St. Francis Dr	STATE FEE
	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	ARTESIA O.C.D.	LC-029415-A
SUNDRY NOTICES	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS	S TO DRILL OR TO DEEPEN OR PLUG BACK	T TO A
DIFFERENT RESERVOIR. USE "APPLICATI PROPOSALS.)	ON FOR PERMIT" (FORM C-101) FOR SUCH	PUCKETT "A"
	Well Other	8. Well Number WH 2
2. Name of Operator		9. OGRID Number
HUDSON OIL COMPANY OF TEXA	S	025111
3. Address of Operator	NUCPEU EVECTOR	10. Pool name or Wildcat
	Г WORTH, ТХ 76102	MALJAMAR GRAYBURG/SANANDRES
4. Well Location		
		_feet from the <u>WEST</u> _line
	wnship T17S Range R31E	NMPM County EDDY COUNTY
	I. Elevation (Show whether DR, RKB, I	RT, GR, etc.)
35	901 KB	
10 (1)		
12. Check App	ropriate Box to Indicate Nature of	of Notice, Report or Other Data
NOTICE OF INTE	NTION TO:	SUBSEQUENT REPORT OF:
		DIAL WORK
TEMPORARILY ABANDON C	_	MENCE DRILLING OPNS.☐ P AND A ☐
PULL OR ALTER CASING M	ULTIPLE COMPL CASIN	IG/CEMENT JOB
DOWNHOLE COMMINGLE		Nettly OCD 24 hrs . prior to
CLOSED-LOOP SYSTEM		OUA MOLE POLICE
OTHER:		D. ————————————————————————————————————
13. Describe proposed or completed	d operations. (Clearly state all pertinen	t details, and give pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For N	
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion.	details, and give pertinent dates, including estimated date fulltiple Completions: Attach wellbore diagram of
 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging 	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion.	t details, and give pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string.	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Noletion.	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-1/0 3K BOP's. MI
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Noletion.	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-110 3K BOP's. MI
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down role 2,965. RIH with tubing and tag	details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 1-110 3K BOP's. MI
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squee: 3. RIH with tbg and tag cement @ 1,	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810'. If necessary, pump additional	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'coment to bring top to 1,810'.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeed 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76.	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810'. If necessary, pump additional	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squee: 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76-POOH with tubing.	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" s	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76-POOH with tubing.' 5. RIH and perforate 7" and 10" casing of the starting of the property of the starting of the starting of the starting of the property of the starting of the start	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" sang @ 60'. Squeeze 50 sx cent. 200.	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down row 2,065'. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" sang @ 60'. Squeeze 50 sx cent. 200.	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement. surface.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBF to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemer anchors, restore and reseed location.	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down representation of the property of the propert	t details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down representation of the property of the propert	t details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemer anchors, restore and reseed location. RECLAMATION: "Rip and remove cases."	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down representation of the properties of the pro	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-1/0 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed."
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBF to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemer anchors, restore and reseed location.	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down representation of the properties of the pro	t details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 1-110 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squee: 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing. '5. RIH and perforate 7" and 10" casing 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove called the starting of the starting	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down row 2,065. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" sang @ 60'. Squeeze 50 sx cement to surface around both casing stripaliche, contour to surrounding topog	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squee: 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing. '5. RIH and perforate 7" and 10" casing 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove called the starting of the starting	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down row 2,065. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" sang @ 60'. Squeeze 50 sx cement to surface around both casing stripaliche, contour to surrounding topog	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and Install 1-1/0 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed."
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squee: 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing. '5. RIH and perforate 7" and 10" casing 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove called the starting of the starting	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down rule 2,065. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" stag @ 60'. Squeeze 50 sx cement to surface around both casing stripaliche, contour to surrounding topog Rig Release Date:	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76 POOH with tubing.' 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove case Spud Date: NOVEMBER 06, 2000	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down rule 2,065. RIH with tubing and tag ze 75 sx cement from 2,060' – 1,810,810'. If necessary, pump additional 4'. Squeeze cement across 8-1/4" stag @ 60'. Squeeze 50 sx cement to surface around both casing stripaliche, contour to surrounding topog Rig Release Date:	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76. POOH with tubing 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove cases and the second secon	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down received a complete to the best of modern and complete to the complete to the	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hoe from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D. y knowledge and belief.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1, 4. RIH and perforate 7" casing @ 76 POOH with tubing.' 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove case Spud Date: NOVEMBER 06, 2000	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down received a complete to the best of modern and complete to the complete to the	details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing o'. cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. ngs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBF to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemer anchors, restore and reseed location. RECLAMATION: "Rip and remove cases and the second secon	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down representation of the property of the propert	details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. higs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D by knowledge and belief.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet. 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove cases and the second	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down representation of the property of the propert	details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. higs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D by knowledge and belief.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBF to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing.'. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemer anchors, restore and reseed location. RECLAMATION: "Rip and remove cases and the second secon	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Moletion. g equipment. POOH and lay down representation of the property of the propert	details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. higs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D by knowledge and belief.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp. 1. MIRU well service rig and plugging and unload 2,100' 2-3/8" work string. 2. RIH with 7" GR to 2,065'. Set CIBI to 500 psi. RIH and perforate 7" casing @ 2,060'. Squeet. 3. RIH with tbg and tag cement @ 1,4. RIH and perforate 7" casing @ 76. POOH with tubing. 5. RIH and perforate 7" and 10" casin 6. Cut off well head and verify cemeranchors, restore and reseed location. RECLAMATION: "Rip and remove cases and the second	d operations. (Clearly state all pertinen SEE RULE 19.15.7.14 NMAC. For Notetion. g equipment. POOH and lay down received a complete to the best of method address: KZORNES@N	details, and give pertinent dates, including estimated date fultiple Completions: Attach wellbore diagram of ods. RD pumping tee and install 7-170 3K BOP's. MI CIBP. Displace well with 9.5 ppg mud. Test casing of cement to bring top to 1,810'. hope from 764' - 564'. WOC. RIH and tag cement. surface. higs. Install below ground dry hole marker. Cut off raphy, reseed." NOVEMBER 15, 2000 MAY 0 3 2019 DISTRICT II-ARTESIA O.C.D by knowledge and belief.



Operator: Well Name: **Hudson Oil Company of Texas**

Field:

Puckett "A" W.H. #2 Maljamar

County/State: API Number

Eddy County, New Mexico 30-015-31082

Lease Number LC-029415-A Location:

TOC @ Surface (CBL 3-12-01) Cmt plug from Surface - 60'

Sec 24 - T17S - R31E 1330' FNL & 10' FWL

Spud Date: 11-6-00 KB [ft]: 3,901 TD: 4,052' GL [ft]: 3,888' PBTD 3,640' KB-GL: 13' WELLHEAD AND TREE DETAILS Size & Rating A Section: **B** Section: Tree:

DRILLING DETAILS

CASING DETAILS						CMTING	DETAILS
Hole	Size	Wght	Grde	TOL	Depth	Vol	TOC [ft],
12-1/4"	8-5/8"	24	J-55		636'	415 sx	Surface
7-7/8"	5-1/2"	17	J-55		4,007'	3410 sx	Suf (CBL)
	•						

Anhy @ 590'

Top of Salt @ 690'

Base of Salt @ 1,710'

Yates @ 1900'

Queen @ 2,835'

Grayburg @ 3,220'

San Andres @ 3,570'

Cmt plug 1,780' - 1,900'

Cmt plug 536' - 736' 8-5/8" @ 636'

Squeeze holes @2,895'. Cement with 500 sacks down Braden head and 1300 sx into squeeze holes.

Cmt plug 2,990' - 3,240'

CIBP @ 3,240'

3,294' - 3,460'

CIBP @ 3,570'


3,588' - 3,794'

5-1/2" @ 4,007 TD @ 4,052'

PERFORATION DETAILS								
Zone	Gross Interval	Gross Interval Net Pay Shot		Shots IP Date				
:								
Grayburg	3,294' - 3,460'	166	61	2-2-01				
San Andress	3,588' - 3,794'	206	86	12-14-00	2-1-01			

TREATMENT DETAILS								
Interval [bbls] Type Sd [lbs] ISIP ATR ATP								
3,294' - 3,460'	773	Gel	45,000	2,340	31	2,655		
3,588' - 3,794'	300	Gel	6,000	2,700	25	3,942		

Date:	4/18/2019		
By:	Greg Milner		



Anhy @ 590'

Yates @ 1900'

San Andres @ 3,570'

Operator:

Hudson Oil Company of Texas

Well Name:

Puckett "A" W.H. #2 Maljamar

Field: County/State:

Eddy County, New Mexico

API Number

30-015-31082 Lease Number LC-029415-A

Location:

Sec 24 - T17S - R31E

TOC @ Surface (CBL 3-12-01)

1330' FNL & 10' FWL

DRILLING DETAILS KB [ft]: Spud Date: 3,901' 11-6-00 GL [ft]: 3,888' TD: 4,052' **PBTD** 3,640' KB-GL: 13' WELLHEAD AND TREE DETAILS

Size & Rating A Section: **B** Section:

Tree:

					• [
CASING DETAILS					CMTING DETAILS		
Hole	Size	Wght	Grde	TOL	Depth	Vol	TOC [ft],
12-1/4"	8-5/8"	24	J-55		636'	415 sx	Surface
7-7/8"	5-1/2"	17	J-55		4,007'	3410 sx	Suf (CBL)
							i

8-5/8" @ 636'

	Downhole Item 2/2/2001	Length	Depth
	KB Correction	13.00	13.00
111	2-3/8" 4.7# J-55 8rd EUE	3,494.00	3,507.00
	SN	1.10	3,508.10
	Perf Sub	3.00	3,511.10
	Mud Anchor	31.00	3,542.10

	Downhole Item	Length Depth So	
	Polish Rod	-	18.00 18.0
139	3/4" Steel Rods		3,475.00 3,493.0
	2" x 1-1/2" x 12' Pump		12.00 3,505.0

Squeeze holes @2,895'. Cement with 500 sacks down Braden head and 1300 sx into squeeze holes.

3,294' - 3,460'

CIBP @ 3,570'

,588' - 3,794'

5-1/2" @ 4,007' TD @ 4,052'

PERFORATION DETAILS									
Zone Gross Interval Net Pay Shots IP Date P&A									
Grayburg	3,294' - 3,460'	166	61	2-2-01					
San Andress	3,588' - 3,794'	206	86	12-14-00	2-1-01				

TREATMENT DETAILS									
Interval	[bbls]	Type	Sd [lbs]	ISIP	ATR	ATP			
3,294' - 3,460'	773	Gel	45,000	2,340	31	2,655			
3,588' - 3,794'	300	Gel	6,000	2,700	25	3,942			

Date:	4/15/2019
By:	Greg Milner

Hudson Oil of Texas – P&A Procedure – 4/16/2019

Puckett "A" W.H #2

API #: 35-015-31082

AFE#:

Field: Maljamar, Grayburg-San Andres Surf Location: Sec 24, T17S – R31E 1330' FNL & 10' FWL

Latitude: 00.0000 N / Longitude: -00.0000 W

Eddy County, NM Spud Date: 11-6-00

Directions to Location

From Maljamar: West on Hwy 82 for 4 miles. Turn south into location.

Description	Size	Wght	Grade	ID	Drift	Burst	Collapse	Btm MD	TOC
Surface	8-5/8"	24	J-55	8.097"	7.972"	2,940	1.370	636'	Surface
Production	5-1/2"	17	J-55	4.89"	4.767"	5,320	4,910	4,007'	Surf (CBL)
Tubing	2-3/8"	4.7	J-55	1.995"	1.901"	7,700	8,100	3,542'	

KB: 3,901 GL: 3,888' **PBTD**: 3,640' **TD:** 4,052'

Current Perfs: 3,294' – 3,460'

Objective: P&A Well Bore in compliance with the rules and regulations for the state of New Mexico.

Proposed Perfs: None

Procedure

- 1. MIRU well service rig and plugging equipment. POOH and lay down rods. RD pumping tee and install 7-1/6" 3K BOP's. Strap tubing out of hole and stand back in derrick.
- 2. RIH with 5-1/2" GR to 3,250'. Set CIBP @ 3,240'. RIH with tubing and tag CIBP. Displace well with 9.5 ppg mud. Test casing to 1000 psi. Spot 25 sx cement on top of CIBP. POOH with tubing and WOC.
- 3. RIH with tbg and tag cement @ 2,990'. If necessary, pump additional cement to bring top to 2,990'. POOH with tbg to 1900'. Spot 25 sx plug from 1900' 1780'. WOC. RIH and tag cement. POOH.
- 4. RIH and spot 25 sx plug from 736' 536'. WOC. RIH and tag cement. POOH with tubing.
- 5. RIH and circulate cement 60' to surface.
- 6. Cut off well head and verify cement to surface around both casing strings. Install below ground dry hole marker. Cut off anchors, restore and reseed location.

THIS PROCEDURE HAS BEEN PROPOSED IN CONSIDERATION OF AND WITH RESPECT GIVEN TO THE MANY VARIABLES AND POTENTIAL PROBLEMS THAT MAY BE ENCOUNTERED IN THIS WELL IN THIS GEOGRAPHICAL AREA. THEREFORE, THIS PROCEDURE IS TO SERVE AS A GENERAL GUIDELINE AND WILL BE REVIEWED AND MODIFIED WHEN REQUIRED AS DETERMINED BY ACTUAL WELLBORE CONDITIONS ENCOUNTERED IN THE OPERATIONS. SAFETY AND PRUDENT PRACTICES WILL TAKE PRIORITY AT ALL TIMES.

Prior to rig up of any operations and prior to the actual operations, always hold safety meeting to discuss any potential hazards, accurately record names of all personnel on location, pick meeting place, discuss evacuation plans, designate hospital of choice and have coordinates and phone numbers for care flight operations if necessary. Completely discuss the operation and/or rig-up so that all personnel understand the plan, responsibilities and any potential changes that may take place during the rig up or operation

Prepared By:

Greg Milner

Date: 4-18-19

Petroleum Engineer