

	UNITED STATES EPARTMENT OF THE I UREAU OF LAND MANA	NTERIOR OCD	Artosia O	FORM APPROVED MB NO. 1004-0137 pires: January 31, 2018	
SUNDRY	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an		5. Lease Serial NMLC028		
abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, All	lottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Oil Well Gas Well Other			7. lf Unit or CA 89101239	 If Unit or CA/Agreement, Name and/or 8910123980 Well Name and No. RJ UNIT 127 	
2. Name of Operator COG OPERATING LLC Contact: ABIGAIL ANDERSON E-Mail: abbym@bcmandassociates.com		9. API Well No 30-015-03			
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-580-7161	10. Field and P GRAYBUF	ool or Exploratory Area RG	
4. Location of Well (Footage, Sec., 7	T., R., M., or Survey Description)	11. County or F	Parish, State	
Sec 35 T17S R29E NWNE Tract 2A 660FNL 1980FEL			EDDY CO	UNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
	□ Acidize	Deepen	Production (Start/Resur	ne) 🔲 Water Shu	
Notice of Intent	☐ Alter Casing	Hydraulic Fracturing	Reclamation	U Well Integ	
Subsequent Report	Casing Repair	New Construction	Recomplete	□ Other	
Final Abandonment Notice	 Change Plans Convert to Injection 	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal		
1. Set 7" CIBP @ 2950'. Spot MLF. ALA • • • • • • • • • 2. Perf & Sqz 55 sx @ 481 38 3. Perf & Sqz 35 sx @ 60' to s	25 sx cmt on top. Pressu 4 (a) 840. SQ Z 4 WOC & Tag. 3 D 7 surface.	re test csg, to 500 psi. Circula - cm+ to 740. C Shoe & T/Sal	te hole w/ 2485 . -762		
1. Set 7" CIBP @ 2950°. Spot MLF. ALL ↑ Leg. Per 2. Perf & Sgz 55 sx @ 481- 3 8	25 sx cmt on top. Pressu 4 (a) 840. SQ 7 WOC & Tag. 307 surface. on Below-Ground Dry Hole	re test csg, to 500 psi. Circula - Cm+ 40 740. Choe E 7/Sal	ATTACHED F	Cnt to ZZ((salt) DR	
1. Set 7" CIBP @ 2950'. Spot MLF. Add Pring 2. Perf & Sqz 55 sx @ 481 38 3. Perf & Sqz 35 sx @ 60' to s	25 sx cmt on top. Pressu 4 (a) 840. SQ Z 4 WOC & Tag. 3 D 7 surface.	re test csg, to 500 psi. Circula - Cm+ 40 740. Choe E 7/Sal	te hole w/ 2485. (wec Tag. (B/	Cnt to ZZ((salt) DR	
1. Set 7" CIBP @ 2950". Spot MLF. Add Order 2. Perf & Sqz 55 sx @ 481 30 3. Perf & Sqz 35 sx @ 60' to s 4. Cut off wellhead and weld o	25 sx cmt on top. Pressu 4 3 840. So z 4 WOC & Tag. 3 0 7 surface. on Below-Ground Dry Hole G C 8/ Accepted for reco	te test csg. to 500 psi. Circula Cont to 740. Cont to 740. Shoe E 7/Sol Marker. SEE CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A	Cnt to 220 (salt) OR PPROVAL RECEMED AUG 21 201	
1. Set 7" CIBP @ 2950". Spot MLF. Add A fee, Per 2. Perf & Sqz 55 sx @ 481-36 3. Perf & Sqz 35 sx @ 60' to s 4. Cut off wellhead and weld of 14. 1 hereby certify that the foregoing is Comm	25 sx cmt on top. Pressu 4 (a) 840 . SC 2 b 840 . SC 2 b 840 . SC 2 b 1 b 1 b 1 c 1	re test csg. to 500 psi. Circula C Shoa & 7/Sol a Marker. 2 2 / 19 SEE CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY of	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A	Cnt to 220 (sait) OR PPROVAL RECEIVED AUG 21201	
1. Set 7" CIBP @ 2950". Spot MLF. ALA A Long A Star 2. Perf & Sqz 55 sx @ 481-36 3. Perf & Sqz 35 sx @ 60' to s 4. Cut off wellhead and weld of 14. 1 hereby certify that the foregoing is Comm	25 sx cmt on top. Pressu 4 3 840. So z 4 WOC & Tag. 3 0 7 surface. on Below-Ground Dry Hole G C 8/ Accepted for reco	te test csg. to 500 psi. Circula Cont to 740. Cont to 740. Shoe E 7/Sol Marker. SEE CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A	Cnt to 220 (sait) OR PPROVAL RECEMED AUG 21201	
1. Set 7" CIBP @ 2950". Spot MLF. ALA A Long A Star 2. Perf & Sqz 55 sx @ 481-36 3. Perf & Sqz 35 sx @ 60' to s 4. Cut off wellhead and weld of 14. 1 hereby certify that the foregoing is Comm	25 sx cmt on top. Pressu WOC & Tag. 3 D 7 Surface. on Below-Ground Dry Hold C C 8 Accepted for reco Strue and correct. Electronic Submission # For COG O itted to AFMSS for process ANDERSON	re test csg. to 500 psi. Circula C Shoa & 7/Sol a Marker. 2 2 / 19 SEE CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY of	te hole w/ 2485. (G) ATTACHED F(NDITIONS OF A Information System arlsbad on 05/01/2019 (19DLM0458S	Cnt to 220 (sait) OR PPROVAL RECEMED AUG 21201	
 Set 7" CIBP @ 2950". Spot MLF. Ald Alegebra for the second second	25 sx cmt on top. Pressu 4 0 840. So z 5 wrface. on Below-Ground Dry Hole G C 8/ Accepted for reco strue and correct. Electronic Submission # For COG O itted to AFMSS for process ANDERSON Submission)	re test csg. to 500 psi. Circula C Shoa & 7/Sol a Marker. 2 2 / 19 rd - NMOCD CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY of Title AGENT	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A Information System arisbad on 05/01/2019 (19DLM0458S	Cnt to 220 (sait) OR PPROVAL RECEMED AUG 21201	
 Set 7" CIBP @ 2950". Spot MLF. Add A function of the second second	25 sx cmt on top. Pressu 4 0 840. So z 5 wrface. on Below-Ground Dry Hole G C 8/ Accepted for reco strue and correct. Electronic Submission # For COG O itted to AFMSS for process ANDERSON Submission)	re test csg. to 500 psi. Circula Cont to 740. Cont to 740. Cont to 740. See Marker. SEE CON 463658 verified by the BLM Well PERATING LLC, sent to the Ca Sing by DEBORAH MCKINNEY OF Date 05/01/2	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A Information System arisbad on 05/01/2019 (19DLM0458S	Cont to 220 (solt) DR PPROVAL RECEMED AUG 2 1 201 E) STRUCTULARTESIA	
1. Set 7" CIBP @ 2950". Spot MLF. Add Pue, Per 2. Perf & Sqz 55 sx @ 481 20 3. Perf & Sqz 35 sx @ 60' to s 4. Cut off wellhead and weld of 14. I hereby certify that the foregoing is Comm Name (Printed/Typed) ABIGAIL of Signature (Electronic S	25 sx cmt on top. Pressu 4 0 840. SQ 2 4 WOC & Tag. 3 0 7 surface. on Below-Ground Dry Hole G C 8 Accepted for reco ited to AFMSS for process ANDERSON Submission) THIS SPACE FO M. Approval of this notice does itable title to those rights in the	re test csg. to 500 psi. Circula Cont to 740. Shoe to 740. Shoe to 740. SEE CON 463658 verified by the BLM Wel PERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY of Title AGENT Date 05/01/2 DR FEDERAL OR STATE Title CH not warrant or	te hole w/ 2485. (B) ATTACHED F(NDITIONS OF A Information System arisbad on 05/01/2019 (19DLM0458S	Cont to 220 (solt) DR PPROVAL RECEMED AUG 2 1 201 E) STRUCTULARTESIA	
1. Set 7" CIBP @ 2950". Spot MLF. Add A function for the formal of	25 sx cmt on top. Pressu 4 0 840. SQ 2 4 WOC & Tag. 3 0 7 surface. on Below-Ground Dry Hole G C 8 Accepted for reco strue and correct. Electronic Submission # For COG 0 itted to AFMSS for process ANDERSON Submission) THIS SPACE FO A. Approval of this notice does ittable title to those rights in the ict operations thereon. U.S.C. Section 1212, make it a	re test csg. to 500 psi. Circula Cont to 740. Shoe & 740. Marker. 22/19 SEE CON 463658 verified by the BLM Wel PPERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY OF Title AGENT Date 05/01/2 Date 05/01/2 Date 05/01/2 Date Cffice Cffice Cffice Cffice	te hole w/ 2485. (B) ATTACHED FO NDITIONS OF A Information System arisbad on 05/01/2019 (19DLM0458S D19 OFFICE USE	Cont to 220 (so it) OR PPROVAL RECEMED AUG 2 1 2011 E) STRICTILARTESIA	
 Set 7" CIBP @ 2950". Spot MLF. ALA Place, Perf 2. Perf & Sqz 55 sx @ 481-96 3. Perf & Sqz 35 sx @ 60' to st 4. Cut off wellhead and weld of the standard of the standard of the	25 sx cmt on top. Pressu 4 WOC & Tag. 3 0 7 surface. on Below-Ground Dry Hole G C & Solution Accepted for reco ittue and correct. Electronic Submission # For COG O itted to AFMSS for process ANDERSON Submission) THIS SPACE FO A. Approval of this notice does intable title to those rights in the ict operations thereon. U.S.C. Section 1212, make it a statements or representations as	re test csg. to 500 psi. Circula Cont to 740. Shoe & 740. Marker. 22/19 SEE CON 463658 verified by the BLM Wel PPERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY OF Title AGENT Date 05/01/2 Date 05/01/2 Date 05/01/2 Date Cffice Cffice Cffice Cffice	te hole w/ 2485. (B) ATTACHED FO NDITIONS OF A Information System arisbad on 05/01/2019 (19DLM0458S 019 OFFICE USE	Conf to 220 (sait) OR PPROVAL RECEINED AUG 2 1 2011 E) STRUCTHARTESIA 5-5- Date	

58

COG Operating LLC





4/25/2019

RJ Unit # 127 WBD (2)

SH

-104.0429611

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

• 'Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.