2 1				
		NOV 1 9 2019 OCD Artesia		
	UNITED STATES	STRICTIL-ARTESIAO.C.	D. FORM APF OMB No. 10 Expires: July	04-0137
BUREAU OF LAND MANAGEM SUNDRY NOTICES AND REPORTS			5. Lease Serial No. NMNM05855	
Do not use this	form for proposals to dri Use Form 3160-3 (APD) 1	Il or to re-enter an	6. If Indian, Allottee or Tribe Na	me
. Type of Well	IIT IN TRIPLICATE – Other instru	ctions on page 2.	7. If Unit of CA/Agreement, Nat	ne and/or No.
Oil Well Gas	Well Other		8. Well Name and No. DITKA FEDERAL COM #1	
2. Name of Operator MACK ENRGY CORPORATION		·	9. API Well No. 30-015-37384	
a. Address O. BOX 960 ARTESIA NM 88211-0960	(575)	hone No. <i>(include area code)</i> 748-1288	10. Field and Pool or Explorator PAVO MESA; ABO	y Area
Location of Well (Fontage, Sec., 7 75 FNL & 330 FWL-SEC, 25 T16S R28E	C.R., M., or Survey Description)		11. Country or Parish, State EDDY, NM	· _ · _ · _ · _ · _ · _ · _ · _ · _ · _
12. CHI	CK THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	l	
TYPE OF SUBMISSION		TYPE OF A		
Notice of Intent	Acidize			ater Shut-Off
Subsequent Report	Casing Repair	New Construction	Ξ.	her
Final Abandonment Notice	Convert to Injection		emporarily Abandon later Disposal	
testing has been completed. Fina	work will be performed or provide the lved operations. If the operation result Abandonment Notices must be filed	Its in a multiple completion or reco	 Required subsequent reports must impletion in a new interval a Form 3 	be filed within 30 days
Tollowing completion of the invo testing has been completed. Final determined that the site is ready f SET 4.5% CIBP @-6990'. PRES: SPOT 25 SX CMT @ 6990'. 69 PERFORATE @- 300' & SQZ 66 CUT OFF WELLHEAD. VERIFY	work will be performed or provide th lved operations. If the operation resu l Abandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 54' - WOC & TAG 55X CMT FROM-388' - SURFACE CMT TO SURFACE. WELD ON I	ne Bond No. on file with BLM/BIA Its in a multiple completion or reco I only after all requirements, includi // MLF 5.5'@ 6100 -5700 54/0 (7-/440) -57000 -57000 -5700 -57000 -57000	Required subsequent reports must mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Alea f	be filed within 30 days 160-4 must be filed once I and the operator has
Standard DHM Topological DHM Set 45; CIBP @ 6990', PRESS SPOT 25 SX CMT @ 6990' 6 SPOT 25 SX CMT @ 6990' 6 SPOT 25 SX CMT @ 6990' 6 SPOT 25 SX CMT @ 6984' 59 PERFORATE @ 300' & SQZ 66 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL DRY+ Standard DHM	work will be performed or provide the lived operations. If the operation resu I Abandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 6100 54' - WOC & TAG 56/0 SX CMT FROM 280' - SURFACE CMT TO SURFACE, WELD ON I HOLE MARKER REQUIRED)	ne Bond No. on file with BLM/BIA Its in a multiple completion or recoil only after all requirements, includi MLF 5.5" @ 6100 -5700 5410 (7/440 438 592 (m) P&A MARKER	. Required subsequent reports must l mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Alea f	be filed within 30 days
Standard DHM Topological DHM SET 4-57 CIBP @-6990', PRESS SPOT 25 SX CMT @ 6990' & SOZ 66 SPOT 25 SX CMT @ 6984'-59 PERFORATE @-386' & SOZ 66 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL-DRY-F Standard DHM	work will be performed or provide the lived operations. If the operation resu (A bandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40'- WOC & TAG 5405- SX CMT FROM 300'- SURFACE CMT TO SURFACE, WELD ON I HOLE MARKER REOLIRED CONTSIDE LPC H	ne Bond No. on file with BLM/BIA Its in a multiple completion or recoil only after all requirements, includi MLF 5.5" @ 6100 -5700 5410 (7/440 438 592 (m) P&A MARKER	Required subsequent reports must I mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Ala f (T/G Add Ala (T/Son Add Ala f	be filed within 30 days 160-4 must be filed once 1 and the operator has 5:3567-3368 1erietta :2104-1904 Ardres :796-296
Tollowing completion of the invo testing has been completed. Fina determined that the site is ready f SET 4.5; CIBP @ 6990', PRESS SPOT 25 SX CMT @ 6990' 60 SPOT 25 SX CMT @ 6990' 60 SPOT 25 SX CMT @ 6990' 60 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL DRY-F Standard DHM Gcc II/20 / Accepted to record - N	work will be performed or provide the lived operations. If the operation resu (A bandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40'- WOC & TAG 5405- SX CMT FROM 300'- SURFACE CMT TO SURFACE, WELD ON I HOLE MARKER REOLIRED CONTSIDE LPC H	ne Bond No. on file with BLM/BIA Its in a multiple completion or recoil only after all requirements, includi "MLF 5.5" 6 6100 5410 CT/440 PRA MARKER 502 CM FACHED FOR IONS OF APPROV	Required subsequent reports must I mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Ala f (T/G Add Ala (T/Son Add Ala f	be filed within 30 days 160-4 must be filed once 1 and the operator has 5:3567-3368 1erietta :2104-1904 Ardres :796-296
Tollowing completion of the invo testing has been completed. Fina determined that the site is ready f SET 4.5; CIBP @ 6990', PRESS SPOT 25 SX CMT @ 6990' 60 SPOT 25 SX CMT @ 6990' 60 SPOT 25 SX CMT @ 6990' 60 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL DRY-F Standard DHM Gcc II/20 / Accepted to record - N	work will be performed or provide th lved operations. If the operation resu 1 Abandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40'- WOC & TAG GIOD 44'- WOC & TAG GIOD 54'- WOC & TAG GIOD 54'- WOC & TAG GIOD 54'- WOC & TAG GIOD 54'- WOC & TAG GIOD 55'- CMT FROM 398'- SURFACE CMT TO SURFACE, WELD ON I HOLE MARKER REQUIRED) CONTSIDE SEE ATT CONDITI	ne Bond No. on file with BLM/BIA Its in a multiple completion or recoil only after all requirements, includi "MLF 5.5" & GIO 54/0 (T/AG 984 MARKER SQZ CM FACHED FOR IONS OF APPROV	Required subsequent reports must I mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Ala Add Ala (T/Son Add Ala (T/Son Add Ala	ENTER ENTER 160-4 must be filed once 160-4 must be filed once 160-4 must be filed once 160-4 must be filed once 160-33667 1706-33667 1796-6967 ENTER IN AFM
Tollowing completion of the invo testing has been completed. Fina determined that the site is ready f SET 4-5; CIBP @-6000; PRESS SPOT 25 SX CMT @ 6000; PRESS SPOT 25 SX CMT @ 6000; GO PERFORATE @-300' & SOZ 60 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL DRY: Standard DH M Gccepted for record - N Accepted for record - N	work will be performed or provide th lved operations. If the operation resu 1 Abandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 54' - WOC & TAG 56.00 54' - WOC & TAG 56.00 CMT TO SURFACE, WELD ON I IGLE MARKER REQUIRED) CONTSIDE LPC H SEE ATT CONDITI true and correct. Name (Printed/Typed,	ne Bond No. on file with BLM/BIA Its in a multiple completion or recoil only after all requirements, includi "MLF 5.5" 6 6100 5410 CT/460 PBA MARKER SQZ CM FACHED FOR IONS OF APPROV Title AGENT	Required subsequent reports must I mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Alac f (T/Son Add Blug (T/Son Add Alag (T/Son Add Alag	be filed within 30 days 160-4 must be filed once 1 and the operator has 5: 3567 - 3368 1 richta) : 2104 - 1904 Ardres : 796 - 296
Tollowing completion of the invo testing has been completed. Fina determined that the site is ready f SET 4-5; CIBP @-6090', PRESS SPOT 25 SX CMT @ 63964-69 PERFORATE @-386' & SOZ 66 CUT OFF WELLHEAD, VERIFY ELOW GROUND LEVEL DRY+ Standard DHM Gccpted tor record . Accepted tor record . Signature for for foregoing is Signature for foregoing is Min PERANTON	work will be performed or provide the lived operations. If the operation resul (Abandonment Notices must be filed or final inspection.) SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SURE TEST CSG, CIRC HOLE W 40' - WOC & TAG 56.00 SEE ATT SEE ATT CONDITI True and correct. Name (<i>Printed Typed</i>) THIS SPACE FOR 4. Approval of the notice does not war it the to those rights in the subject lease V	rinte Service	Required subsequent reports must mpletion in a new interval, a Form 3 ng reclamation, have been completed by Add Ala f (T/S Add Blug (T/Son Add Ala (T/Son Add Ala (T/Son Add Ala (T/Son Add Ala (T/Son Add Ala (T/Son Add Ala (T/Son (T) (T)	ENTER ENTER ENTER End the operator has ENTER E

Ż

121/4 " hole 350 SX CMT. Sur F 7 Rivers 746 1265 Qu Perf 438 Attimpt SQZ To Surt 1623 GB 25 5× 796-696 (T/7R) 6/8 hole 2054 SA. 3510 GI 4797 Tb 25 SX 2104-1904 (T/SA) 5560 Aba Prod 6866 ωc 25 SX 2520-3360 (T/GL) 825 Sx cmt 253× 5610-54105 1 (1/ABO) -6234 6102 - Surf Cicc. 29 SX 6100-5900 Tag 51/2 25 5x cmt Halliberton FO CIBA 6100 Cementer @ 6102 41/2" 6234-TD ECP@ 6157 TD IIII6 A open hole PK H TVD 6851 PerFS 6993 - 10883

-, lemos 11-2-19 575-361-2648

MACK ENERGY CORPORATION DITKA FEDERAL COM #1 *388= SURFACE (66 SX) 12.25" Hole 8.625" (159 TOC/D SURFACE -338' 4 6284-5934 (25 sx) 7K 746 7" HOLE 618" 6234 4 QUEEN 1265 6.125 (59 6 Burg 1673' TOL a SULFALE SA 2054' Gluxicta 3510' Antw/ 8255x Tubb 4797 From 6102-Surt Abo 5560' Circ. WEAMP 6866 6990-6640' (25sx) - CIBP 26990' stz. 6993 Splil string ECA EIST 6/8 6/8 5.5 Hole 4/2 11.6 # 4.5" (sg 10883' 11116 1 6441- 11.116 1118 5 TOC @ 6234

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

.

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat , • • Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.