			Form C-103 Revised July 18, 2013
District I ~ (575) 393-6161 Energy, Minerals and Natural 1625 N. French Dr., Hobbs, NM 88240	Resources	WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 3 2019 OIL CONSERVATION D	IVISION	30-005-61240	
District III - (505) 334-6178 1220 South St. Francis		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.	
District IV – (500) STRICTUL AFTESIAO.C.D. Santa Fe, NM 8750 1220 S. St. Francis Dr., Santa Fe, NM 8750 87505		o. State on & Gas I	
SUNDRY NOTICES AND REPORTS ON WELLS			nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG I DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR S		Paulette PV State	
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other		8. Well Number 3	
2. Name of Operator	1	9. OGRID Number25835010. Pool name or Wildcat	
VANGUARD OPERATING, LLC 3. Address of Operator			
5847 SAN FELIPE, STE. 3000, HOUSTON, TEXAS, 77057		Diablo; Fusselman Assoc	
4. Well Location	1		
Unit Letter P :660 feet from the SOUTH		feet from theE.	ASTline
	nge 25E	NMPM	County Eddy
11. Elevation (Show whether DR, RI 3780	KB, RT, GR, etc.)		教授新校
3780		780.00	
12. Check Appropriate Box to Indicate Natu	ire of Notice, F	Report or Other D	ata
NOTICE OF INTENTION TO:	SUBS	EQUENT REPO	ORT OF
	EMEDIAL WORK		
	OMMENCE DRIL		AND A
PULL OR ALTER CASING MULTIPLE COMPL	ASING/CEMENT	ЈОВ 🗌	
CLOSED-LOOP SYSTEM			
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pert	THER:		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. I proposed completion or recompletion.	For Multiple Com	pletions: Attach wel	lbore diagram of
proposed completion of recompletion.			-
Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v	well to evaluate an	y future uphole reco	
Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v	well to evaluate an	y future uphole reco	
Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v TA procedure is as follows:	vell to evaluate an	y future uphole reco	
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/ 3 	35' of cement via	bailer.	npletion opportunities.
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/ 3. Contact NMOCD prior to running MIT test. Fill casing with treated 	35' of cement via	bailer. ure test to 500 psig f	npletion opportunities. or at least 30 minutes.
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/ 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 	35' of cement via	bailer. ure test to 500 psig f TA status may	npletion opportunities. or at least 30 minutes. pe granted after a
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 4. RD WS & WL. 	35' of cement via ed water and press	bailer. ure test to 500 psig f TA status may successful MIT	npletion opportunities. or at least 30 minutes. oe granted after a test is performed.
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. 	35' of cement via ed water and press	bailer. ure test to 500 psig f TA status may successful MIT Contact the OC	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 4. RD WS & WL. 	35' of cement via ed water and press	bailer. ure test to 500 psig f TA status may successful MIT	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. 	35' of cement via ed water and press	bailer. ure test to 500 psig f TA status may successful MIT Contact the OC	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this way TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. 	35' of cement via ed water and press approved	bailer. ure test to 500 psig f TA status may successful MIT Contact the OC	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this w TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. 	35' of cement via ed water and press approved	bailer. ure test to 500 psig f TA status may successful MIT Contact the OC	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. Temporary Abandoned Status USE 7-1- 202 Spud Date: 	35' of cement via ed water and press epproved	bailer. ure test to 500 psig f TA status may f successful MIT Contact the OC so it may be wi	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this way TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. 	35' of cement via ed water and press epproved	bailer. ure test to 500 psig f TA status may f successful MIT Contact the OC so it may be wi	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this v TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. Temporary Abandoned Status USE 7-1- 202 Spud Date: 	35' of cement via ed water and press epproved	bailer. ure test to 500 psig f TA status may f successful MIT Contact the OC so it may be wi	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this way TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. Temporary Abandoned States Total Context Pressure Context Pressure Chart. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of the data and the context pressure of t	35' of cement via ed water and press epproved	bailer. ure test to 500 psig f TA status may f successful MIT Contact the OC so it may be wi	npletion opportunities. or at least 30 minutes. oe granted after a test is performed. D to schedule the tes
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this way TA procedure is as follows: MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/ 3 Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. RD WS & WL. File subsequent C-103 and MIT chart. Temporary Abandoned States and Top the information above is true and complete to the best SIGNATURE	35' of cement via ed water and press approved O of my knowledge	bailer. ure test to 500 psig f TA status may l successful MIT Contact the OC so it may be wi and belief. DATE1	npletion opportunities. or at least 30 minutes. be granted after a test is performed. D to schedule the tes tnessed.
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this was TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/2 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 4. RD WS & WL. 5. File subsequent C-103 and MIT chart. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best SIGNATURE MIRU WS. LD production equipment. Yearporeary Abandaneed Status TITLE Op Type or print name KHC Zimmermann E-mail address: kzimm	35' of cement via ed water and press epproved O of my knowledge erations Engineer herman@vnrenerg	bailer. ure test to 500 psig f TA status may b successful MIT Contact the OC so it may be wi and belief. DATE1 y.com PHONE	npletion opportunities. or at least 30 minutes. be granted after a test is performed. D to schedule the test tnessed. <u>1/22/2019</u> : _432-202-0145
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this was TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/2 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 4. RD WS & WL. 5. File subsequent C-103 and MIT chart. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best SIGNATURE MIRU WS. LD production equipment. Yearporeary Abandaneed Status TITLE Op Type or print name KHC Zimmermann E-mail address: kzimm	35' of cement via ed water and press epproved O of my knowledge erations Engineer herman@vnrenerg	bailer. ure test to 500 psig f TA status may b successful MIT Contact the OC so it may be wi and belief. DATE1 y.com PHONE	npletion opportunities. or at least 30 minutes. be granted after a test is performed. D to schedule the test tnessed. <u>1/22/2019</u> : _432-202-0145
 Vanguard Operating, LLC is requesting to temporarily abandon (TA) this was TA procedure is as follows: 1. MIRU WS. LD production equipment. 2. RU WL. Set 4-1/2" CIBP @ 3,656' (Top perf @ 3,706'). Cap w/2 3. Contact NMOCD prior to running MIT test. Fill casing with treate Record pressure chart. 4. RD WS & WL. 5. File subsequent C-103 and MIT chart. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best SIGNATURE MIRU WS. LD production equipment. Yearporeary Abandaneed Status TITLE Op Type or print name KHC Zimmermann E-mail address: kzimm	35' of cement via ed water and press epproved O of my knowledge erations Engineer herman@vnrenerg	bailer. ure test to 500 psig f TA status may b successful MIT Contact the OC so it may be wi and belief. DATE1 y.com PHONE	npletion opportunities. or at least 30 minutes. be granted after a test is performed. D to schedule the tes tnessed.

`

LEASE/WELL:	PAULETTE PV STATE #3		GR	37
LOCATION	660' FSL & 660' FEL		SPUDDED	12/26/19
	P-SEC 16-T05S-R25E	Χ.		
CO/ST:	CHAVES COUNTY, NEW MEXICO		COMPLETED	1/29/19
			LAT	33.86619
FIELD:	PECOS SLOPE; ABO		LONG	-104.3162
API NO.	30-005-61240		FORMATION TOPS PER C-105	
			SAN ANDRES	5
			GLORIETA	16
		CURRENT	FULLERTON	30
		CURRENT	ABO	36
	6 E			

40'

0000

PBTD: 4,273' TD: 4,300'

24" CONDUCTOR CMT W/3 YDS READY MIX TO SURF

14-3/4" HOLE 10-3/4" 40.5# CMT W/ 600 SX.

7-7/8" HOLE

4-1/2" 10.5#

CMT W/ 350 SX.

ABO PERFS: 3,706-4,087' (12 HOLES) -ACIDIZE W/ 3,000 GALS 7.5% -FRAC W/ 40,000 GALS GELLED 2% KCL, 40 TONS CO2, 80,000# 20/40 SAND 4,294'

3780 12/26/1981 1/29/1982

33.8661957 -104.31628<u>4</u>

KDZ 11-22-2019

LEASE/WELL:	PAULETTE PV STATE #3		GR	3780
LOCATION	660' FSL & 660' FEL P-SEC 16-T05S-R25E		SPUDDED	12/26/1981
CO/ST:	CHAVES COUNTY, NEW MEXICO		COMPLETED	1/29/1982
FIELD:	PECOS SLOPE; ABO		LAT LONG	33.8661957 -104.316284
API NO.	30-005-61240	PROPOSED TA	FORMATION TOP SAN ANDRES GLORIETA FULLERTON ABO	S PER C-105 599 1624 3014 3656
	24" CONDUCTOR CMT W/ 3 YDS READY MIX TO SURF 14-3/4" HOLE 10-3/4" 40.54 CMT W/ 600 SX.	945'		
	x			

0000

,

PBTD: 4,273' TD: 4,300'

2 4,294'

7-7/8" HOLE

4-1/2" 10.5# CMT W/ 350 SX.

SET CIBP /6/3,656', CAP W/35' CMT.

ABO PERFS: 3,706-4,087' (12 HOLES) -ACIDIZE W/ 3,000 GALS 7.5% -FRAC W/ 40,000 GALS GELLED 2% KCL, 40 TONS CO2, 80,000# 20/40 SAND ~

KDZ 11-22-2019