

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
811 South First, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO. 30-015-20764
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1565
7. Lease Name or Unit Agreement Name Texaco BE
8. Well No. 2
9. Pool name or Wildcat Grayburg Jackson, SR, QN, GB, SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3688' GR

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type Of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Mack Energy Corporation

3. Address of Operator  
P.O. Box 960, Artesia, NM 88211-0960

4. Well Location  
Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line  
Section 16 Township 17S Range 30E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3688' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP w/35' cement cap @ 2498', 100' above top perforation. ← 256x plug @ 1095' TAG
3. Set 100' cement plug from 559-459', 50' above and below 8 5/8 casing shoe. ← TAG
4. Set 60' surface plug, WOC 24 hours and tag.
5. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 7/28/2003

TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO. (505)748-1288

(This space for State Use)

APPROVED BY AT Brall TITLE Compliance Officer DATE 8/6/03

CONDITIONS OF APPROVAL, IF ANY: Additional Plug & TAGs as indicated above

<b>OPERATOR:</b> Mack Energy		<b>API#</b> 30-015-20764	
<b>WELL:</b> Texaco BE #2		<b>LOCATION:</b> A-16-17s-30e	
<b>SURFACE CSG-HOLE SIZE</b> 11"	<b>CSG. SIZE</b> 8 5/8"	<b>SET @</b> 509'	<b>SX. CMT.</b> TOC. Circ.
<b>LONG STRING- HOLE SIZE</b> 7 7/8	<b>CSG. SIZE</b> 5 1/2"	<b>SET @</b> 3948'	<b>SX. CMT.</b> TOC. Cir
<b>OTHER-</b>			

