CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I		OIL CON	ICED\/ATI		NOIS				
P.O. Box 1980, Hobbs, NM 88240		OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505				WELL API NO. 30-015-24522			
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM	3	•			sIndicate Type of Le				
DISTRICT III				1121314	1578		STATE	FEE	
1000 Rio Brazos Rd., Aztec, I	S10111213141576				State Oil & Gas Lease No.				
		CES AND REP			2004				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUE BACKTO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" RECEIVED  (FORM C-101) FOR SUCH PROPOSALS.)						ទាន់ease Name or Unit Agreement Name Marathon 25 State			
Type of Well:	(FORM C-1	101) FOR SUCH P	ROPOSALS.)	UCD ART	ESTA.	No.	eate .		
OIL WELL	GAS WELL		OTHER	·		9/	•		
2Name of Operator SDX Resources, Inc.				وران المرازية	::7:5797	₃Well No. 7			
sAddress of Operator	. =>. ====		· · · · · · · · · · · · · · · · · · ·		<del>* * * * * * * * * * * * * * * * * * * </del>	⊌Pool name or Wild			
PO Box 5061, Midland	d, TX 79704		·	·		Red Lake, QN	-GB-SA		
Unit Letter A	330	Feet From The	North	Line and	330	Feet From The	, East	Line	
Section	25	Township	17S	Range	28E	NMPM	Eddy	County	
		10Elevation 3663' G	n (Show whether DF R	, RKB, RT, GR, e	tc.)				
11	Check Ap	propriate Box	to Indicate N	ature of No	tice, Rep	ort, or Other	Data		
							EPORT OF:		
PERFORM REMEDIAL WORK	BANDON	REMEDIAL WORK			ALTERING CASI	NG			
TEMPORARILY ABANDON CHANGE PLANS			.NS	COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT			NDONMENT		
PULL OR ALTER CASING CASING TEST AND CEMI					NT JOB				
OTHER: Plug Back			🗙	OTHER:					
n2Describe Proposed or Compwork) SEE RULE 1103.  EXISTING: Perfs: 7052-7114 & 39 P&A in 1984: CRT @ 3	18-82 3840'. Plugs @		urf.	e pertinent dates,	including est	imated date of startin	g any proposed		
Re-entered 1998: PBT PROPOSE: TIH & set CIBP @ 280 Perf: 2 spf: 2238, 40, 4 Pull up to ~ 2150' & set Flow back acid & swab Frac w/40,000 gal X/L Flow back frac. Circ to Pump back load & purr	0'. Circ w/2% 4, 46, 48, 54, t tool. Acidize test zone. Do borate 30# ge CIBP w/2% K	KCL & tst csg, C 56, 62, 64 (18 how/2500 gal 15% epending on result @ 25 bpm w/6	IBP & BOP to 1 oles, CBL depth NEFE. Ilts will either pu	s). mp test zone o				· · .	
I hereby certify that the inform SIGNATURE TYPE OR PRINT NAME BONN	mie (	<del>-</del>		dge and belief.	ry Tech		DATE <u>09-10-</u>		
(This space for State Used APPROVED BY	ORIGIN/ DISTRIC	AL SIGNED BY T II SUPERVIS	<b>30</b> R	g TLE			SEP	1 7 2003	