Form 3160-5 (April2004) G SUNDRY NOTICES AND REPORTS C	,	FORMAPPROVED OM B No 1004-0137 Expires: March 31, 2007 5. Lease Senal No
SUNDRY NOTICES AND REPORTS C		NMNM 100527
Do not use this form for proposals to drill or abandoned well. Use form 3160-3 (APD) for s	to re-enter an such proposals.	6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions o	n reverse side.	7 If Unit or CA/Agreement, Name and/or No
Oil Well Cos Well Other		8. Well Name and No.
2 NameofOperator DAVID H. ARRINGTON OIL & GAS INC		Orange Steelhead Scud Fed Com #11 9 API Well No.
3a Address 3b. Phone No. (include area code) PO BOX 2071 MIDLAND TX 79702 (432)682-6685		30-015-35117 10 Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec, T., R, M, or Survey Description)	1002-0000	Wildcat; Wolfcamp
Sec 25, 17S, 23E, 660' FSL & 1880' FEL	AUG 13 2007	11 County or Parish, State Eddy NM
12. CHECK APPROPRIATE BOX(ES)TO INDICATE	PRATURE OF NOTICE, I	
TYPE OF SUBMISSION	TYPEOF ACTION	
X Noticeof Intent Acidize Deepen AlterCasing FractureT		Well Integrity
Subsequent Report	struction Recomplete	Other
Final Abandonment Notice X Change Plans Plug and I Convert to Injection Plug Bacl		
determined that the site is ready for final inspection.) Please disregard the form 3160-5 submitted 05/08/07 - w same.	e have decided to kee	p the original, permitted location the
Existing permit will expire August 23, 2007, we respectful	AP	PROVED FOR 2 MONTH PERIOD
14 I hereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>)		
DEBBIE FREEMAN	Title ENGINEER TE	ECH
Signature Siter 2	Date 07/11/2007	
THIS SPACE FOR FEDERAL	OR STATE OFFICE	
Approved by /s/ James Stovall Conditions of approval, if any, are attached Approval of this notice does not warm	Title	Date 2007

þ

(Instructions on page 2))
--------------------------	---

Į

1

Operator's Name:	DAVID H. ARRINGTON OIL & GAS, INC.
Well Name & No.	1H – ORANGE STEELHEAD SCUD FEDERAL C
Location:	660' FSL & 1880' FEL – SEC 25 – T17S – R23E – EDDY – SHL
	660' FNL & 1880' FEL – SEC 25 – T17S – R23E – EDDY - BHL
Lease:	NM-100527

I. DRILLING OPERATIONS REQUIREMENTS:

- **A.** The Bureau of Land Management (BLM) is to be notified a minimum of 4 hours in advance for a representative to witness:
 - 1. Spudding well
 - 2. Setting and/or Cementing of all casing strings
 - 3. BOPE tests
 - Eddy County call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822
- **B.** Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.

II. CASING:

A. The <u>8-5/8</u> inch surface casing shall be set at <u>1300</u> feet and cemented to the surface.

- 1. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- 2. Wait on cement (WOC) time for a primary cement job will be a minimum of 12 hours for a non-water basin, 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compression strength, whichever is greater. (This is to include the lead cement)
- 3. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
- 4. If cement falls back, remedial action will be done prior to drilling out that string.
- **B.** The minimum required fill of cement behind the <u>5-1/2</u> inch production casing is <u>tie back 200 feet</u> into the 8-5/8 inch casing.
- C. If hardband drill pipe is rotated inside casing; returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool I joints of the drill pipe will be installed prior to continuing drilling operations. 9¹⁰¹¹¹²¹³



1

III. PRESSURE CONTROL:

- **A.** All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 17.
- **B.** The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - 1. The tests shall be done by an independent service company.
 - 2. The results of the test shall be reported to the appropriate BLM office.
 - **3.** All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
 - 4. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

IV. DRILLING MUD:

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the <u>Wolfcamp</u> formation, and shall be used until production casing is run and cemented.

- 1. Recording pit level indicator to indicate volume gains and losses.
- 2. Mud measuring device for accurately determining the mud volumes necessary to fill the hole during trips.
- 3. Flow-sensor on the flow line to warn of abnormal mud returns from the well

LBabyak 7/30/07

