A 2/10/2010

(Instructions on page 2)

Form 3160-5 (April 2004)

RECEIVED

FEB 1 0 2010

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD ART STIAN Senal No

BUREAU OF LAND MANAGEMENT NMOCD SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	ART 55 Less Senal No NMN M06769 5 6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No
I. Type of Well ☐ ☐ Gas Well ☐ ☐ Other ☐ Other	North Hackberry Yates - SR NM 70995 X 8. Well Name and No.
2. Name of Operator Southwest Royalties, Inc.	North Hackberry Yates Unit #120 9. API Well No.
3a Address 3b Phone No (include area code) 6 Desta Drive, Suite 2100 432/688-3267	30-015-24981 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	North Hackberry Yates
2428' FSL & 64' FEL (NESE) Sec 23, T19S, R30E	11 County or Parish, State Eddy County, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTIO	ON
✓ Notice of Intent ☐ Alter Casing ☐ Fracture Treat ☐ Reclamate Treat ☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recomp	olete Other
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA following completion of the involved operations. If the operation results in a multiple completion or recompleted involved operations. If the operation results in a multiple completion or recompleted in the site is ready for final inspection. 1. Notify BLM office 24 hrs prior to commencing P&A operations. 2. Move in and rig up pulling unit. 3. Nipple down wellhead; nipple up BOP's. 4. Pull 2-7/8" tubing from well. 5. Rig up wireline. Run in hole with 5-1/2" CIBP and set at approximately 1730'. Dump 3 and tag top of cement. 6. Circulate 5-1/2" casing with 9 PPG MLF. 7. Spot 100' cement plug inside 5-1/2" casing from 560' to 660'. Note: 8-5/8" surface casing wes set and cemented to surface at 610'; 5-1/2" production of 8. Spot 15 sx plug from 100' to surface. Rig down pulling unit. 9. Cut off wellhead. Cover cellar. Instal P&A marker. 10. Rip and re-seed location and berm roads.	Required subsequent reports shall be filed within 30 days pletton in a new interval, a Form 3160-4 shall be filed once greclamation, have been completed, and the operator has 5' of class "C" neat cement on CIBP. WOC 4 hrs casing was also cemented to surface.
ATTACHED	IONS OF APPROVAL
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	
Dawn M. Howard Title Operations Ass	istant
Signature Date 1/1	5/0
THIS SPACE FOR FEDERAL OR STATE OF	FICE USEPROVED
Approved by Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and with States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	FEB 8 2010 /s/ Chris Walls This by represent the property of the United CARLS AD FIELD OFFICE CARLS AD FIELD OFFICE


Wellbore Schematic (From Surface to TD)

Printed:

1/15/2010

Well ID: 101106-120

API # 30-015-24981



3,000

2482' FSL & 64' FEL	GL Elev:	3,248.00
Sec,Blk,Sur(Lbr,Lge,Sur)or(Sec,Twn,Rng): 23, , T29S-R30E	Fill Depth:	1,913
County, State: Eddy, NM	PBTD:	1,913.00
Aux ID:	TD:	2,003.00
KB = 11.5; DF = ; All Depths Corr To: KB	BOP:	

Hole Size

Diameter	Top At	Btm At	Date Drilled
12.2500	0.00	610.00	9/20/1984
7.8750	610.00	2,003.00	9/23/1984

Surface Casing					D	ate Ran:	9/20/1984
Description	#	Diameter	Weight	Grade	Length	Top At	Btm At
Casing	1	8.6250	24.00	K55	20.74	11.50	32.24
Cut jt							
Casing	13	8.6250	24.00	K55	534.31	32.24	566.55
Float Collar	1	8.6250	24.00	K55	1.70	566.55	568.25
Casing	1	8.6250	24.00	K55	41.05	568.25	609.30
Shoe jt							
Guide Shoe	1	8.6250	24.00	K55	0.70	609.30	610.00
Notched shoe							

Production Casing String 1 Date Ran: 9/24/1984 # Diameter Weight Grade Description Length Top At Btm At 15.50 5.5000 K55 7.81 11.50 19.31 Casing cut jt 48 5.5000 15.50 K55 1,942.20 19.31 1,961.51 Casing 5.5000 1.47 1,961.51 1,962.98 Float Collar 1 5.5000 15.50 K55 38.40 2,001.38 Casing 1 1,962.98 5.5000 1.62 2,001.38 2,003.00 Float Shoe

Cemen

Cemen	τ						
# Sx	Class	Weight	ID	OD	Top At	Btm At	TOC Per
	Н	15.60	5.500	8.625	0.00	610.00	Est
Section	of BH sqz ir	side surfa	ce pipe se	ection			
1200	Н	15.60	5.500	7.875	610.00	1,570.00	Circ
bradenl	head sqzd at	ter it was f	lowing. C	BL indicate n	o cmt +/-1570	0 to 1800	
50	С	14.80	8.625	12.250	0.00	610.00	Circ
circ thru	ı 1" 50 sx cla	iss C neat					
400	C	14.80	8.625	12.250	61.00	610.00	Tag
Did not	circ. Tag w/	1"@ 61'					
	С		5.500	7.875	1,570.00	1,800.00	CBL
Poor Ce	ement here.					-	
650	С		5.500	7.875	1,800.00	2,003.00	CBL
450 sx	Gulfmix, tail	w/ 200 sx	CI C + 2%	CaCl. Circ 1	00 sx to surf,	but channel	flowed later.

Zone and Perfs Yates-7 Rvrs, Nort

Perforations

Тор	Bottom		Status				Ttl #	
1,781.00	1,789.00	Yates-7 Rvrs, Nort	PA	9/28/1984	10/16/1984	2	16	
sqzd w/ 100	sx <u>5</u> 0/50 ca	il-seal foamed to 11 ppg	w/ N2 &	100 sx cl C i	neat at 14.8	ppg.		
1,802.00	1,810.00	Yates-7 Rvrs, Nort	A	10/18/1984		2	16	
1,940.00	1,942.00	Squeeze Holes	PA	9/25/1984	9/28/1984	4	12	
5-1/2"x8-5/8	5-1/2"x8-5/8" flwg. Attmpt to circ @ 1500#. Could not.							

Wellbore Schematic (From Surface to TD)

Printed:

1/15/2010

North Hackberry Yates Unit # 120

Well ID: 101106-120

API # 30-015-24981

Wellbore Plugs and Junk

			Solid	Date
922.00	Cmt	5.500	Yes	9/28/1984
nt. Later tagged	@1913'			
322.00	CIBP	5.500	Yes	9/28/1984
		nt. Later tagged @1913' 922.00 CIBP	mt. Later tagged @1913' 922.00 CIBP 5.500	mt. Later tagged @1913' 922.00 CIBP 5.500 Yes

Tubing String 1						Date Ran:	10/22/1984
Description	#	Diameter	Weight	Grade	Length	Top At	Btm At
Tbg Sect 1	59	2.8750		J55	1,833.50	11.50	1,845.00
Stg Nipple	1	2.8750			0.50	1,845.00	1,845.50
Prf Nipple	1	2.8750			3.00	1,845.50	1,848.50
Mud Anchor	1	2.8750			32.00	1,848.50	1,880.50
Bull Plug	1	2.8750			0.50	1,880.50	1,881.00

North Hackberry Yates Unit 120 30-015-24981 Southwest Royalties February 2, 2010 Conditions of Approval

Plugging Procedure:

- 1.-6. Ok
- 7. Well is in R-111-P Potash set plug across entire salt zone from 1,550'-450'. WOC and tag plug at 450' or lower. (Base of salt 1500', surface shoe at 610' and top of salt 500')

"一张"等。

8.-9. Ok

See attached standard Conditions of Approval

CRW 020210

· Super.

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Any plug that requires a tag will have a minimum WOC time of 4 hours.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

DHW 111109



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To. 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plant of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

- equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter
Surface Protection Specialist
575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979