

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, New Mexico 87505

DISTRICT II  
811 South First, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.  
30-015-01605

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B-11538

7. Lease Name or Unit Agreement Name

Red Lake Sand Unit

8. Well No.  
11

9. Pool name or Wildcat  
Red Lake; Queen-Grayburg-SA

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well:  
OIL WELL  GAS WELL  OTHER

RECEIVED

2. Name of Operator  
Mack Energy Corporation

JAN 22 2004

3. Address of Operator  
P.O. Box 960, Artesia, NM 88211-0960

OCD-ARTESIA

4. Well Location  
Unit Letter C : 990 Feet From The North Line and 1650 Feet From The West Line  
Section 29 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:


1. Notify OCD 24 hours prior to starting plugging operations.
2. Set 100' cement plug in 8 5/8, 100' above perfs @ 1902'. WOC and tag.
3. Circulate hole with mud gel.
4. Set 100' cement plug from 593-493' 50' above and below 13 3/8 casing. WOC and tag.
6. Set plug @ 60' circulate cement to surface.
7. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 1/22/04  
TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO. \_\_\_\_\_

(This space for State Use)  
APPROVED BY [Signature] TITLE Field Rep ID DATE JAN 28 2004  
CONDITIONS OF APPROVAL, IF ANY:

STATE

MACK ENERGY CORPORATION  
RED LAKE SAND UNIT #11  
Sec 29 T17S R28E 990FNL 1650FWL



13 3/8" @543', C/w 400sks & CIRC

8 5/8" @ 1996' C/w 910sks & CIRC  
CMT PLUG SET AT 1980'

5 1/2" @ 7507' C./w 300sks shot off at 6000' and pulled

1. Notify OCD 24 hrs. prior to any work done.
2. Set 100' cmt plug in 8 5/8" 100' above perms @ 1902-1910' and tag.
3. Circ hole with mud gel.
4. Set 100' cmt plug in 8 5/8" 593'-493' 50'in & out 13 3/8" shoe
5. 60' circ cmt to surface
6. Install Dry Hole Marker