

District I
1625 N. French Dr., Hobbs. NM 88240
District II
1301 W. Grand Avenue, Artesia. NM 88210
District III
1000 Rio Brazos Road, Aztec. NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe. NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAR 02 2009

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-33714

Release Notification and Corrective Action

NKMW1109435919

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company St. Mary Land & Exploration Co. 154903	Contact Donna Huddleston
Address 3300 N. A Street, Bldg. 7, Ste. 200 Midland, TX	Telephone No. (432)688-1789
Facility Name Parkway Delaware Unit #513	Facility Type Injection

Surface Owner BLM	Mineral Owner BLM	Lease No.
-------------------	-------------------	-----------

LOCATION OF RELEASE

Unit Letter J	Section 35	Township 19S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 bbls	Volume Recovered 0
Source of Release 2.5" flange Balon trunk line valve	Date and Hour of Occurrence 2/25/09 9:30AM	Date and Hour of Discovery 2/25/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher W/OCD & Jim Amos W/ BLM	
By Whom? Bill Hearne	Date and Hour 10/25/09 10:20AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

2.5" flanged Balon trunk line valve failure (bottom of valve blow out) @ junction box.
Injection pumps shutdown on low (900#) injection pressure. Estimated 50 bbls. produced water spilled.

Describe Area Affected and Cleanup Action Taken.*

West of injection station and North of PDU 513. Spill Area: 180' x 70' = 12,600 sq. ft. Pasture.

Dig out contaminated soil and remediate with fresh soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Donna Huddleston	OIL CONSERVATION DIVISION	
Printed Name: Donna Huddleston	Approved by District Supervisor Mike Bratcher	
Title: Production Tech	Approval Date: 4/4/11	Expiration Date:
E-mail Address: dhuddleston@stmaryland.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/26/2009 Phone: (432)688-1789	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 5/4/11	

* Attach Additional Sheets If Necessary

2 RP-690