

NO. OF COPIES RECEIVED	
DISTRIBUTION	
AREA OFF	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
J.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

RE VED

Form C-103  
Supersedes Oll  
C-102 and C-103  
Effective 1-1-65

NOV 10 '88

O. C. D.  
ARTESIA OFFICE

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
LG-159

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR NOTICES TO WELL OWNERS TO ABANDON OR PLUG WELLS TO A DIFFERENT RESERVOIR.  
(USE FORM C-103 FOR ABANDON OR PLUG WELLS TO A DIFFERENT RESERVOIR.)

OIL WELL  GAS WELL  OTHER

Name of Operator  
ELK OIL COMPANY

Address of Operator  
Box 310, Roswell, New Mexico 88201

Location of Well  
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE East LINE, SECTION 2 TOWNSHIP 9S RANGE 27E N.M.P.M.

7. Unit Agreement Name

8. Form of Lease Issue  
Graham State Comm.

9. Well No.  
1

10. Field and Pool, or Wildcat  
Wildcat Abo

12. County  
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)  
3881 Grd.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and Abandon as follows:

- 50' plug across perfs @ 2,147-168; 4 1/2" casing TD is 2,380'.
- Pulled approximately 1,500' of 4 1/2" casing.
- Place 50 sx. plug in and out of 4 1/2" stub and tag.
- 50 sx. plug base of 8 5/8" @ 1,390' & tag.
- 10 sx. plug at surface w/standard 4' x 4' dry hole marker.

Location clean & ready for inspection.

Post ID-2  
1-20-89  
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY Joseph J. Kelly TITLE President DATE 11/9/88

APPROVED BY David Moore TITLE Geologist DATE 1/30/89

CONDITIONS OF APPROVAL, IF ANY: