

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
RECEIVED BY
SEP 17 1984
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

56. Indicate Type of Lease
State Fee
57. State Oil & Gas Lease No.
647

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator
Hondo Oil & Gas Company ✓
3. Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM
THE East LINE, SECTION 25 TOWNSHIP 17S RANGE 28E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)
3663.2' GL
7. Unit Agreement Name
8. Farm or Lease Name
State "BV" A
9. Well No.
1
10. Field and Pool, or Wildcat
Eddy Undes. Glorieta
12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Propose to plug and abandon in the following manner:
1. RU, POH w/rods & pump. Install BOP.
 2. POH w/compl assy.
 3. Set cmt retr @ 3850'.
 4. Cmt squeeze perfs 3918-3982' & spot 5 sx cmt on top of retr.
 5. Circ well bore w/9.5# gel BW-25# gel/bbl.
 6. Spot 100' cmt plug 1026-976' & 10 sx @ surf. * 1026-926
 7. Install regulation dry hole marker, clean & level location for final abandonment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED Elizabeth S. Bush TITLE Drlg. Engr. DATE 9/13/84

APPROVED BY Mike Williams TITLE Oil & Gas Inspector DATE SEP 18 1984
CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness