

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/ -
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11662	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Kewanee Oil Company	8. Farm or Lease Name State "A"
3. Address of Operator P. O. Box 3786, Odessa, Texas 79760	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17S</u> RANGE <u>29E</u> NMPM.	10. Field and Pool, or Wildcat Square Lake G-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3637' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to pull 4-1/2" O.D. casing and plug and abandon.

Propose to spot cement plug from 2500' to 2640' to cover perforations at 2533-47' and 2632-36'. Shoot 4-1/2" pipe at 1750'. Fill hole with mud-laden fluid and spot 100' cement plug from 197' to 297', 50' inside surface casing and 50' below surface casing seat, and spot 10' cement plug at surface. Weld permanent marker at wellhead.

Propose to commence work on or about 4-28-69.

RECEIVED

APR 22 1969

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lee C. Newton TITLE Division Engineer DATE 4-21-69

APPROVED BY W. A. Gressitt TITLE OIL AND GAS INSPECTOR DATE APR 25 1969

CONDITIONS OF APPROVAL, IF ANY: Load hole with mud and spot 2 additional plugs as follows
25 sacks @ 4 1/2" casing stub + 25 sacks at base of salt approx 875
meas. plus from 197-297 ft. + 100' + 297-297 ft. to base of cement plug