Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

11

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

Form C-103 Revised 1-1-89
\

P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO	אסופואום או	WELL API NO.				
= · · · • · • · · · · · · · · · · · ·	2040 Pacheco St. Santa Fe, NM 87505			30-015-03213			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	sindicate Type of Leas						
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	State Oil & Gas Leas B-4918						
SUNDRY NOTIC	ES AND REPORTS ON WEL	LS					
(DO NOT USE THIS FORM FOR PRO	7Lease Name or Unit Agreement Name						
DIFFERENT RESERV (FORM C-1	Old Loco Unit						
₁Type of Well: OIL GAS WELL ☑ WELL ☐							
xName of Operator Web Oil Company			₃Well No. 14				
Address of Operator P. O. Box 1124, Artesia, NM 88211	Pool name or Wildca						
4Well Location							
Unit Letter N: 330	Feet From The South	Line and 2310	Feet From The	West Line			
32 Section 17S	Township 29E F	lange	NMPM	Eddy County			
	10Elevation (Show whether DF, I	RKB, RT, GR, etc.)					
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING							
TEMPORARILY ABANDON	≫NS.	PLUG AND ANBANDONMENT					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONIMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB							
OTHER:		OTHER:					
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.							
TO'							
PBTD 2602'							
7" @ 2352, w/ 100 sx,., 8 " hole,	8 5/8 @ 322 w/ 48 sx.', 10" hole. 7"						
Top of Fish @ 2130'							
Proposal for plug and abandon 37							
1. Set CIBP @ 1980' , load hole with 2.Perf. 7" @ 850 & 350' RIH w/ page	h plugging mud. Dump 10'. Class '	'C" cmt. on top CIBP'	retest Saz w/na	cker @ 250 w 50 sylc ass			
"C", WOC and pressure test - TAG		ome, Troo and pressu	io todi. Oqe. W pa	DITO: 100 240 W. 00 9A 0.009			
4. Spot 10 sx. surface plug.							
5. Install dry hole marker and clean location.							
1. retrotate 7 casing	4. Perforate ?" casing 5 50 Circulate cement To surface inside r cutside?" casing.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE	тп	LE AGent		DATE 12-06-00			
TYPE OR PRINT NAME Wayne Brooks				TELEPHONE NO. 915-580-7161			
(This space for State Use)							
APPROVED BY Mile Stulke his	LL TIT	RE Field Rep. I	<u></u>	DATE 12/12/2000			
CONDITIONS OF APPROVAL, IF ANY:							
* Notifie N.M O.C.D. To witness Plugging Operations.							