

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THE VICINITY  
(Other instructions on re-  
verse side)Form approved  
Budget Bureau No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "B"

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 17, T17S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P.O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FSL, 1980' FWL (Unit Letter N)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3672' Grd.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Convert to water inj.

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*In accordance w/NMOCC Order No. R-3185 dated 2/1/67 we propose to  
convert this well to water injection as outlined below:

1. Clean out to original T.D. of 3430'.
2. Run 4½" OD 8R 9.5# casing to 3430' and cement w/200 sx of Class  
"C" containing 5# salt/sack. WOC 18 to 24 hours.
3. Perforate Jackson zone w/one 0.42" jet shot at 3320, 3321, 3324,  
3326, 3334, 3344, 3346, 3350, 3351, 3357, 3364, 3367, 3369,  
3371, 3376, 3378, 3379, 3401, 3403, 3408, 3409, 3421 and 3422  
(GR-N Log).
4. Treat w/3500 gallons 15% HCl acid and ball sealers.
5. Run tension packer on 2-3/8" tubing and set at 3275'. Load  
annulus w/treated fresh water.
6. Commence water injection.

Work to start about 1/15/70.

18. I hereby certify that the foregoing is true and correct

SIGNED

*P.D. Hutchins*

TITLE

Dist. Drlg. Supervisor

DATE

12-15-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

DATE

DEC 23 1969

\*See Instructions on Reverse Side

ARTESIA, OFFICE