

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN THE
(Other instruct
verse side)ICATE*
on reForm approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC C29395 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T17S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ WELL GAS ☐ WELL OTHER ☒ Water Injection Well

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL 660' FEL (Unit letter P)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3695' Grd.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☒REPAIR WELL ☐

(Other)

Run 4 1/2" Innerstring

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

To effect a more efficient injected water pattern, we propose the following work:

1. Clean out to T.D. of 3451'.
2. Run 4 1/2" OD 8R 9.5# casing to T.D. and cement w/200 sx of Class "C" cement containing 5# salt and 5# gilsonite per sack.
3. Perforate Jackson zone w/one 0.42" jet at 3330, 3331, 3342, 3348, 3359, 3363, 3367, 3375, 3380, 3391, 3399, 3403, 3417, 3425, 3426, 3431 and 3437' (17 holes - GR-Neutron log).
4. Treat w/3000 gallons 15% HCl acid.
5. Run tension packer on 2-3/8" tubing and set @ 3275'.
6. Resume water injection.

Work to start about 1/14/69

DEC 16 1968

RECEIVED
DEC 15 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

O. D. Sitchas

TITLE Dist. Drlg. Supervisor

DATE

12-12-69

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
DEC 15 1969
R. L. BECKMA

*See Instructions on Reverse Side