rmerly 9-331) DEPARTI	UNTED STATES AMEL. OF THE NI	ERIOR (Other instruction	Expires Aug	eau No. 1004-0135 gust 31, 1985 FION AND BERIAL NO.	
SUNDRY NOT	ICES AND REPOR			TTEE OR TRIBE NAME	
	ATION FOR PERMIT— IOI		7. UNIT AGREEMEN	T NAME	
OIL X GAS OTHER		OCT 29 1984	Q PARM OR TRACE	VAMP	
NAME OF OPERATOR		0.00		8. FARM OR LEASE NAME	
GETTY OIL COMPANY		O. C. D.	9. WELL NO.	Skelly Unit	
ADDRESS OF OPERATOR		ARTESIA, OFFICE		2	
P.O. BOX 730, HOBBS, LOCATION OF WELL (Report location of	NEW MEXICO 88240	J	10. FIBLD AND POO		
LOCATION OF WELL (Report location of See also space 17 below.) At surface	Hearly and in accordance with	m any peace requirement.	1 -	Jackson_SR-A-G	
Unit Ltr K, 1980 FSL	& 1980 FWL				
	15. ELEVATIONS (Show whe	ther DF. RT. GR. etc.)	Sec. 22,		
PERMIT NO.		3843' DF	Eddy	N.M.	
				N.P.	
	•	ate Nature of Notice, Report,	or Other Data		
NOTICE OF INTE		1			
	PULL OR ALTER CASING	WATER SHUT-OFF		NG WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		G CABING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDO	MENT*	
REPAIR WELL CHANGE PLANS (Other) Convert to injection (Note: Report result Completion or Record		sults of multiple complet	tion on Well		
nent to this work.)* 1. Rig up pulling ur 2. Pull rods. 3. Install BOP.		be locations and measured and true v		racio and police perti-	
nent to this work.)* 1. Rig up pulling ur 2. Pull rods. 3. Install BOP. 4. Pull tubing. 5. RIH w/bit and scr 6. RIH and jet open 7. Spot converter fr 8. Shut in overnight 9. Acidize this well 0. Swab load. 1. RIH and set the	raper and clean or hole. com 3432-3168'. t. 1 w/5000 gal. of	ut to 3370'.			
nent to this work.)* 1. Rig up pulling ur 2. Pull rods. 3. Install BOP. 4. Pull tubing. 5. RIH w/bit and scr 6. RIH and jet open 7. Spot converter fr 8. Shut in overnight 9. Acidize this well 0. Swab load. 1. RIH and set the 2. Convert to inj. Y hereby certify that the foregoing SIGNED Dale R. Crocket (This space for Federal or State of APPROVED BY	raper and clean or hole. com 3432-3168'. t. l w/5000 gal. of 1000 gal. of 1000 gal. 7' pkr @±3076'.	Area Superintendent	DATE	0/20/84	
nent to this work.)* 1. Rig up pulling ur 2. Pull rods. 3. Install BOP. 4. Pull tubing. 5. RIH w/bit and scr 6. RIH and jet open 7. Spot converter fr 8. Shut in overnight 9. Acidize this well 10. Swab load. 11. RIH and set the 12. Convert to inj. 13. Signed Dale R. Crocket 14. This space for Federal or State of APPROVED BY CONDITIONS OF APPROVAL. IF	raper and clean on hole. com 3432-3168'. t. l w/5000 gal. of 1000 gal. of 1000 gal. 7' pkr @±3076'. TITLE TITLE TANY:	Area Superintendent	DATE	9/20/84	
nent to this work.)* 1. Rig up pulling ur 2. Pull rods. 3. Install BOP. 4. Pull tubing. 5. RIH w/bit and scr 6. RIH and jet open 7. Spot converter fr 8. Shut in overnight 9. Acidize this well 10. Swab load. 11. RIH and set the 12. Convert to inj. 13. Signed Dale R. Crocket 14. This space for Federal or State of APPROVED BY CONDITIONS OF APPROVAL. IF	raper and clean or hole. com 3432-3168'. t. l w/5000 gal. of fine decorrect TITLE TANY: J.AMidland	Area Superintendent	DATE	9/20/84	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of Line Unity S. Sea Lev (alse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

The Assets as

Zi W