

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT R/VING
OFFICE FOR ADJ. ADJ.
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Marbob Energy Corporation		8. FARM OR LEASE NAME Sinclair Parke	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface 2310 FNL 2308 FWL		10. FIELD AND POOL, OR WILDCAT Jackson Abo	
14. PERMIT NO. 30-015-10334		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3677' DF	
11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-T17S-R30E		12. COUNTY OR PARISH Eddy	
13. STATE NM		18. STATE NM	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to plug and abandon as follows: Set CIBP @ 6900' w/25' cmt on top plug. Set cmt plug from 6160-6000'. Set cmt plug over DV Tool from 4450-4300'. Perf csg at 1414' and squeeze perfs w/75 sx cmt - 50 sx outside and 25 sx inside. Perf csg @ 380' and squeeze perfs w/75 sx cmt - 50 sx outside and 25 sx inside. Set cmt plug at surface and install dry hole marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED Robin Smith TITLE Production Clerk DATE 9/20/91

(This space for Federal or State office use)

APPROVED BY David H. Glass TITLE _____ DATE 3-12-92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side