Form 3160-5 (November 1983)

CONDITIONS OF APPROVAL, IF ANY:

## UNITED \_ (ATES

N.M. QII Cons. DIVISIOTI

DAT

C155

(Formerly 9-331)	DEPARTM	<del>-</del>			reverse side )	, I alai d	expires August 31, 1985	•	
	BUREAU OF LAND MANAGEMENT						5. LEASE DESIGNATION AND SERIAL NO. LC-029418-B		
CUNDDY NOTICES AND DEDODES ON WELLS							6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT - " for such proposals.)							AN, ALIOTTEE OR TRI	DE NAIME	
1.						7. UNIT AGREEMENT NAME			
OIL GAS OTHER WELL P & A							Skelly Unit		
							Skeny Cint		
2. NAME OF OPERATOR							8. WELL NAME AND NO.		
The Wiser Oil Company							73		
3. ADDRESS OF OPERATOR							9. API WELL NO.		
P.O. Box 2568 Hobbs, New Mexico 88241							30-015-10504		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.							10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.)							Fren Seven Rivers		
At surface							11. SEC., T., R., M., OR BLK. AND		
2130' FSL & 660' FWL							SURVEY OR AREA		
2135 155 600 1 115							23-T17S-R31E		
14. PERMIT NO 15. ELEVATIONS (Show whether DF, R					T. GR. etc.)	12. COUN	TTY OR PARISH	13. STATE	
		3866' DF	•				y County	NM	
16.	Check	Annropriate F	Sox to indicate	e Natur	e of Notice Report or Othe		1 County		
						BSEQUENT REPORT OF:			
TEST WATER SHUT	OFF []	DITT OF AL	TER CASING		WATER SHUT-OFF		REPAIRING WELL		
TEST WATER SHOT		FOLL OR AL	TER CABING		WATER SHOT-OFF	H	REFAIRING WELL		
FRACTURE TREAT		MULTIPLE C	COMPLETE		FRACTURE TREATMENT		ALTERING CASING	· []	
SHOOT OR ACIDIZE		ABANDON*	:		SHOOTING OR ACIDIZING	, 📙	ABANDONMENT *		
REPAIR WELL		CHANGE PL	ANS		(Other)				
(Other)	(Note: Report result						of multiple completion on Well mpletion Report and Log form.)		
	ED OP COMPLET	ED OPER ATIO	NS: (Clearly state	all nertir	ent details, and give pertinent dates			,	
					red and true vertical depths for all r				
	-	-					-		
Wiser request approval to Plug & Abandon the well by procedure listed below.  1. TIH w/CIBP & set @ 3800'.  2 BLM recarly show CIBP at 3250' W/35'cout, Cap									
2. Dump 15 sks.	~		ent nlug	<i>L</i> ( )			,	•	
3. Circulate aba		_	m prug.						
4. Set CIBP @ 2			it on nliig						
5. Tag cement.	2500 oc dump	.J SKS. CCIIICI	n on plug.						
6. Set 25 sks. ce	mont plug @ 1	د <u>رس</u> ،							
7. Tag plug @ 1		300 .							
		9 <b>0</b> ,							
8. Set 15 sks. ce 9. Tag plug @ 7		30							
<b>3.</b> 3 0									
10. Set 10 sks. ce	_	m sultace.							
11. Install dry ho									
12. Clean location	<b>n</b>				Danier 2240) 2477 P 227	10) 2/511			
Perfs: 2340'-2466' & 323.  18. I hereby certify that the foregoing is true and correct.									
16. I nereby certify that th	e toregoing is true a	на соттест.							
signed <u>b. M.</u>	Jones R.	mst	TITLE Supe	erintenc	lent	DATE_	September 29, 200	00	
(This snace for Federal				<del></del>		<del></del>	A	****	

\*See Instruction On Reverse Side

\*BUREAU OF LANGUAGE MENT

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false in this idea or fraudulent or representations as to any matter within its jurisdiction.

minimum 50' cont. surface plugcont. to surface 4.) 154x cont. 1 780', 2 July 1984) 729 Squeeped W/ 360 14 Ix 78 hole est! Toc = 560 in armulest int. nust Some of the ont. nust 42", 10.541.6 have gone down. caseng coming leak 1123-1185' aguelzed W/ 25 1x. (Occ. 1993) Base of talt 1634 cont. W/400xx. 24: yates 1804' 3.) 25 m cmt. plug 1600'. max fill = 2300' max TOC = 1546 2.) CIBP at 2300' + 15 ex cont. cop. SevenRiver 2159' Perf + 2340'- 2466' (gen. '79) Queen 2777' Penrose 2948 1.) Existing plang.) ЗK Grayburg 3164' (80pt 1991) CIBP@3250'+ 35'contircap. Aguery of perf 3238-3246 (206.72) Bremier 3440' andrdret 3540 Perfo 3238 - 3751 (april 67) Perf+ 3769-3814 (Dec. 61)

> by Pete Chester 10/13/00

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 505-627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within thirty (30) days from the approval date of this Notice of Intent to Abandon.
- 2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 505-627-0272, Eddy County call 505-234-5972; for wells in Lea County call 505-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

- 6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

(rev. 5/30/2000)

acs -- 8/26/96