

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

OIL CONSERVATION DIVISION

P. O. BOX 2080
SANTA FE, NEW MEXICO

RECEIVED BY

AUG 26 1983

O. C. D.

ARTESIA, OFFICE

Form C-103
Revised 10-1-77

3. Indicate Type of Lease
State ☒ Fee ☐
4. State Oil & Gas Lease No.
E-537-5

SUNDY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPER OR PLUG BACK TO A RESERVOIR.
USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Empire South Deep Unit
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Unit No. 11
4. Location of well UNIT LETTER F 1980 North 2130 FEET FROM THE LINE AND FEET FROM West 32 17-S 29-E TOWNSHIP RANGE	10. Field and Pool, or Acreage Empire South-Wolfcamp
11. Elevation (Show whether DF, RT, GR, etc.) 3609' RDB	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate and acidize as follows: Move in service unit and kill well. Pull rods, pump, tubing and anchor. Perf 8296'-8308', 8324'-8344', 8456'-8480', and 8496'-8520. Run in hole with retrievable bridge plug (RBP) and set at 8550'; packer set at 8446', a seating nipple, and tubing. Pump 3000 gals of 20% HCL acid at 3-5 BPM with additives. If communication occurs, then flush with 51 bbl of cut brine. Release packer and latch onto RBP. Reset RBP at 8370' and packer at 8200'. Swab dry. Pump 2000 gals of 20% HCL at 3-5 BPM with additives. Flush with 51 bbl cut brine. Release packer and latch onto RBP. Pull tubing, packer and RBP. Run in with tubing, anchor, pump and rods return to production.

0+4-NMOCD,A 1-HOU R.E. Ogden, Rm 21.150 1-F. J. Nash, HOU Rm. 4.206 1-PJS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patricia J. Sena TITLE Assist. Admin. Analyst

DATE 8-25-83

Original Signed By

Leslie A. Clements

Supervisor District II

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

DATE AUG 29 1983