

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Ralph Nix and Jerry Curtis	5. State Oil & Gas Lease No. E-7256
3. Address of Operator P. O. Box 617, Artesia, New Mexico 88210	7. Unit Agreement Name
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1746 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 19 S. RANGE 29 E. NMPM.	8. Farm or Lease Name Nix State X
	9. Well No. One
	10. Field and Pool, or Wildcat Millman Queen Gray.
15. Elevation (Show whether DF, RT, GR, etc.) 3390' G.L.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. **Start Immediately upon approval.**

If casing is not pulled we plan to:

**Place 15 sack plug at 1987';
Load hole with mud;
Put surface plug and marker.**

If casing is pulled we will:

**Place 15 sack plug at 1987';
Place 20 sack plug at stub of 4 1/2";
Place 25 sack plug at base of 8 5/8";
Put surface plug and marker.**

FDW

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Alfred Williams</i></u>	TITLE Office-Manager	DATE 7-26-68
APPROVED BY <u><i>W.A. Gressett</i></u>	TITLE Oil and Gas Inspector	DATE
CONDITIONS OF APPROVAL, IF ANY:		