(May 1963)	DEFAR	TMENT OF THE I		o nM		M 032240	
· · · · · · · · · · · · · · · · · · ·		GEOLOGICAL SUR				INDIAN, ALLOTTEE OR	TRIBE
(Do not use this	JDRY NC	DTICES AND REPO posals to drill or to deepen ICATION FOR PERMIT_"	ORIS ON	WELLS a different reservoir.			
1.	Use "APPLI	ICATION FOR PERMIT—"	for such proposa	s.)	7. UNI	T AGREEMENT NAME	
OIL GAS GAS OTHER						8. FARM OR LEASE NAME	
2. NAME OF OPERATOR						Barbara-Federal	
Len Mayer 3. Address of operato					9. WEI		
Box 1495, Roswell, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					10. FI	10. FIELD AND POOL, OR WILDCAT	
At surface					No H	Lackberry	Yate
2310 [‡] FS			Ŧ			SURVEY OR AREA	A .\D
Section 2	9, Twp.	195, Rge. 311	د			9-195-31E	
14. PERMIT NO.		15. ELEVATIONS (Show 3487 GL		3, etc.)		DUNTY OR PARISH 1: DUNTY OR PARISH 1:	NM
		Appropriate Box To In					
16.	Check A	• •			BSEQUENT BEI		
TEST WATER SHUT-	[]	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WEL	r [
TEST WATER SHUT-		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASI	ic
SHOOT OR ACIDIZE		ABANDON*	X	SHOOTING OR ACIDIZIN	• 🛄	ABANDONMENT*	
REPAIR WELL (Other)		CHANGE PLANS		(Other) (NOTE: Report r Completion or R	esults of mult	tiple completion on eport and Log form.)	Well
	OR COMPLETED	OPERATIONS (Clearly state a subsu	all pertinent det:	11	datos includi	ng estimated date of	f starti
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug Wil	Propose Will Il hole 50 ft. to bas	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface apt to pull 30	cement p cop of ce ft. cem casing (0 ft. 8-	n casing by lug at TD of ment plug to ent plug 185 720°) and so 5/8" surface	cutting 2218 base 50-1950 et 100 e casing	g casing Propose of salt ¹ , fill ft cement g, and if	
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 185 720°) and so 5/8" surface ce casing pa	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface pt to pull 30 sax plug whe	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 185 720°) and so 5/8" surface ce casing pa	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will bole 50 ft. to bas l to bas set 25 co surfa	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s	cement p cop of ce ft. cem casing (0 ft. 8- ere surfa standard	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e
TD 2218. @ 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t	Propose Will 11 hole 50 ft. to bas 1 attem set 25 to surfa and le	to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface of of surface of sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (00 ft. 8- ere surfa standard REC	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing pa marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt i, fill ft cement g, and if d fill hol plug. RECEN SEP6 U.S. PE	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Wil successful with mud t Will clean	Propose Will 11 hole 50 ft. to bas 1 attem set 25 to surfa and le	e to pull 7" p spot 100 ft. e w/mud from t Will set 100 se of surface of surface of surface of sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (00 ft. 8- ere surfa standard REC	n casing by lug at TD of ment plug to ent plug 189 720') and so 5/8" surface ce casing pa marker with	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug.	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify W	Propose Will 11 hole 50 ft. 1 to bas 1 attem set 25 to surfa 1 and le	e to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface opt to pull 30 sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (0 ft. 8- ere surfa standard RE S	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing pa marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. CEP SEP O SEP SEP SEP SEP SEP SEP SEP SEP	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify of SIGNED	Propose Will 11 hole 50 ft. 1 to bas 1 attem set 25 to surfa and le	e to pull 7" p spot 100 ft. e w/mud from t Will set 100 se of surface of surface of sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (0 ft. 8- ere surfa standard RE S	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing pa marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. RECEN SEP6 U.S. REC 8/30	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify (SIGNED (This space for Fe	Propose Will 11 hole 50 ft. 1 to bas 1 attem set 25 to surfa 1 and le	e to pull 7" p spot 100 ft. e w/mud from t Will set 100 se of surface of surface of sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (0 ft. 8- ere surfa standard RE	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing pa marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. CEP SEP O SEP SEP SEP SEP SEP SEP SEP SEP	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify of SIGNED (This space for Fe Approver ST CONDITIONS OF	Propose Will 11 hole 50 ft. 1 to bas 1 attem 50 surfa and le	e to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface of surface to pull 30 sax plug whe ace, setting s evel location.	roductic cement p op of ce) ft. cem casing ()0 ft. 8- ere surfa standard RE () () () () () () () () () () () () ()	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing para marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. CEP SEP O SEP SEP SEP SEP SEP SEP SEP SEP	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify of SIGNED (This space for Fe Approver ST CONDITIONS OF	Propose Will 11 hole 50 ft. 1 to bas 1 attem 50 surfa and le	e to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface of surface to pull 30 sax plug whe ace, setting s evel location.	roductic cement p op of ce ft. cem casing (0 ft. 8- ere surfa standard RE	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing para marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. CEP SEP O SEP SEP SEP SEP SEP SEP SEP SEP	e 1966 1966 1966 1966
TD 2218. (a) 1950 ft. to then fi approx. 19 hole w/mud plug. Will successful with mud t Will clean 18. I hereby certify (SIGNED (This space for Fe	Propose Will 11 hole 50 ft. 1 to bas 1 attem 50 surfa and le	e to pull 7" p spot 100 ft. w/mud from t Will set 100 se of surface of surface to pull 30 sax plug whe ace, setting s evel location.	roductic cement p op of ce) ft. cem casing ()0 ft. 8- ere surfa standard RE () () () () () () () () () () () () ()	n casing by lug at TD of ment plug to ent plug 185 720') and so 5/8" surface ce casing para marker with CEIVED	cutting 2218 base 50-1950 et 100 e casing arts an 15 sax	g casing Propose of salt , fill ft cement g, and if d fill hol plug. CEP SEP O SEP SEP SEP SEP SEP SEP SEP SEP	e 1966 1966 1966 1966

÷